	DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT  Operator						OMB NO. 1004-0137 Expires: January 31, 2018			
	r	5. Lease Serial No. NMNM100558								
SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.							6. If Indian, Allottee or Tribe Name			
	- Commondo	o) for such pr	opusais.			·				
SUBMIT IN TRIPLICATE - Other instructions on page 2						7. If Unit or CA/Agreement, Name and/or No.				
1. Type of Well Gas Well Chher							8. Well Name and No. RDX 15 13			
Name of Operator Contact: CAITLIN O'HAIR     RKI EXPLORATION & PROD LLC E-Mail: caitlin.ohair@wpxenergy.com						9. API Well No. 30-015-36834-00-\$1				
3a. Address				-cede)					<del></del>	
3500 ONE WILLIAMS CENTER MD 35 Ph: 5 TULSA, OK 74172			ARTES	JNS IA DI	ERVATIO STRICT	10. Field and Pool or Exploratory Area N BRUSHY DRAW-WOLFCAMP Selaware Last				
4. Location of Well (Footage, Sec	FEB 1 9 2019				11. County or Parish, State					
Sec 15 T26\$ R30E SWNE 32.044579 N Lat, 103.8680					EDDY COU	NTY, N	IM			
12 CHECK THE	A DDD ODD I A TE DOVÆS	TO DIDICAT	RE	<b>SEIV</b>	ED	DEDORT OR		ND 4704		
12. CHECK THE	APPROPRIATE BOX(ES)	TO INDICAT	ENATU	KE UI	NOTICE, I	REPORT, OR O	JIHER	CDATA		
TYPE OF SUBMISSION		TYPE OF ACTION								
☐ Notice of Intent	☐ Acidize	☐ Deep	en		☐ Production	on (Start/Resume	;) [	☐ Water Shut-O	ff	
Subsequent Report     Subsequent Re	☐ Alter Casing		aulic Fract	_	☐ Reclama			☐ Well Integrity	,	
	Casing Repair		Construction		☐ Recompi			Other		
☐ Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection	⊠ Plug	and Aband	on	☐ Water D	rily Abandon				
Class C 5654 4896 WOC 9-11-18 Tag Plug @ 4890 9-12-18 Perforate @ 3544 spot. Spot 25 sacks Class 9-13-18 Tag Plug @ 3526 out intermediate. Squeeze WOC.	work will be performed or provide yed operations. If the operation re Abandonment Notices must be find final inspection.  I Isaiah BLM. Load & Test Casing 500 P.  Notify Chase BLM. Tag Ap Attempt to establish rate. Notify Chase BLM. Tag Ap 70 sacks Class C.  Notify Chase BLM. Tag Ap 70 sacks Class C.  Notify Chase BLM. Tag App 80 sacks Class C to	e the Bond No. on sults in a multiple led only after all rust of the sults of the s	file with BL completion requirements late Salt Cass with Character @ 103	M/BIA or reco , includ: Gel Mu ase BI 30'. Es	. Required sub mpletion in a n ing reclamation d. Spot 75 s <u>M.</u> Approve	ew interval, a Form, have been completed.  RE  acks  All Indian Plants Markets  RE  All Indian Plants Markets  Report Markets  RE  All Indian Plants Markets  RE	ist be file in 3160-4 eted and in ECIAM/	ed within 30 days must be filed once	DURE	
	g is true and correct. Electronic Submission f For RM EXPLO nmitted to AFMSS for proces N O'HAIR	RATION & PRO	DD LLC, se RAH MCKII	ent to t	he Carisbad on 09/19/2018	-	i)			
Signature (Electron	nic Submission)			9/18/2						
	THIS SPACE F	OR FEDERA	L OR ST	知	<b>选利性D</b>	FOR RECO	ORD			
Approved By			Title		650	9-1-5319		Date		
Conditions of approval, if any, are attacertify that the applicant holds legal or which would entitle the applicant to co	equitable title to those rights in the	s not warrant or se subject lease	Office		SEP.	21 2018 nen Lie				

(Instructions on page 2) \*\*\* BLM REVISED \*\*\* BLM REVISED \*\*\* BLM REVISED \*\*\* BLM REVISED \*\*\*

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and Whitely to AND WAY ACTAIN or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. CARLSBAD FIELD OFFICE





## United States Department of the Interior

#### **BUREAU OF LAND MANAGEMENT**

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

#### Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
  Operations must include adequate measures for stabilization and reclamation of disturbed lands.
  Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
  process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (PAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

البريدان

Henryetta Price Environmental Protection Specialist 575-234-5951

Shelly Tucker
Environmental Protection Specialist
575-234-5979

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist – 575-393-3612 Form 3160-5 (June 2015)

### **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

# SUNDRY NOTICES AND REPORTS ON WELLS

5. Lease Serial No. NMNM100558

Do not use thi abandoned wei		6. If Indian, Allottee or Tribe Name							
SUBMIT IN 1		7. If Unit or CA/Agreement, Name and/or No.							
Type of Well     ☐ Gas Well ☐ Oth		8. Well Name and No. RDX 15 13							
Name of Operator     RKI EXPLORATION & PROD		9. API Well No. 30-015-36834-00-S1							
3a. Address 3500 ONE WILLIAMS CENTE TULSA, OK 74172		10. Field and Pool or Exploratory Area BRUSHY DRAW-WOLFCAMP							
4. Location of Well (Footage, Sec., T		11. County or Parish, St	ate						
Sec 15 T26S R30E SWNE 19 32.044579 N Lat, 103.868003		EDDY COUNTY, NM							
12. CHECK THE AI	PPROPRIATE BOX(ES) TO INC	DICATE NATURE OF	F NOTICE, F	REPORT, OR OTH	ER DATA				
TYPE OF SUBMISSION		TYPE OF	ACTION		<del></del>				
☐ Notice of Intent	☐ Acidize ☐	Deepen	☐ Production	n (Start/Resume)	☐ Water Shut-Off				
_		Hydraulic Fracturing	☐ Reclamat	ion	☐ Well Integrity				
Subsequent Report	_ • •	New Construction	☐ Recomplete		☐ Other				
☐ Final Abandonment Notice	l – •	Plug and Abandon		orarily Abandon					
13. Describe Proposed or Completed Op	·	☐ Plug Back	☐ Water Di	<u> </u>					
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.  9-5-18 MIRU WSU. Contact Isaiah BLM. 9-10-18 Set CIBP @ 5654'. Load & Test Casing 500 PSI. Held. Circulate Salt Gel Mud. Spot 75 sacks Class C 5654'-4896'. WOC. 9-11-18 Tag Plug @ 4890'. Notify Chase BLM. Tag Approved. 9-12-18 Perforate @ 3544'. Attempt to establish rate. No rate. Discuss with Chase BLM. Approved spot. Spot 25 sacks Class C 3594'-3345'. WOC. 9-13-18 Tag Plug @ 3526'. Notify Chase BLM. Tag Approved. Perforate @ 1030'. Establish circulation out intermediate. Squeeze 70 sacks Class C. WOC. 9-14-18 Tag Plug @ 700'. Notify Chase BLM. Tag Approved. Perforate @ 150'. Establish circulation out intermediate. Circulate 80 sacks Class C to surface in annulus & leave 5-1 /2" Casing full.									
14. I hereby certify that the foregoing i  Comm  Name (Printed/Typed) CAITLIN	Electronic Submission #435794 For RKI EXPLORATION hitted to AFMSS for processing by I	& PROD LLC. sent to t	the Carlsbad on 09/19/2018						
Name (Frimew Typeu) CATTLIN	U HAIR	Title GODINI	1161		<u> </u>				
Signature (Electronic	Submission)	Date 09/18/20	018						
	THIS SPACE FOR FEI	DERAL OR STATE	OFFICE US	BE					
Approved By ACCEPT		DEBORAH MCKINNEY tleLEGAL INSTRUMENTS EXAMINER		Date 09/21/2018					
Conditions of approval, if any, are attach certify that the applicant holds legal or ed which would entitle the applicant to cond	uitable title to those rights in the subject luct operations thereon.	Office Carlsbac		·	<del></del>				
Title 18 U.S.C. Section 1001 and Title 43	3 U.S.C. Section 1212, make it a crime for statements or representations as to any m	r any person knowingly and natter within its jurisdiction.	l willfully to ma	ke to any department or	agency of the United				

#### Revisions to Operator-Submitted EC Data for Sundry Notice #435794

**Operator Submitted** 

**BLM Revised (AFMSS)** 

Sundry Type:

ABD SR

Lease:

NMNM100558

NMNM100558

Agreement:

Operator:

WPX ENERGY 3500 ONE WILLIAMS CENTER MD 35 TULSA, OK 74103 Ph: 539-573-3527

Admin Contact:

CAITLIN O'HAIR SUBMITTER

E-Mail: caitlin.ohair@wpxenergy.com

Ph: 539-573-3527

Tech Contact:

CAITLIN O'HAIR SUBMITTER

E-Mail: caitlin.ohair@wpxenergy.com

Ph: 539-573-3527

Location:

State: County: NM EDDY

Field/Pool:

BRUSHY DRAW; DELAWARE, E

Well/Facility:

RDX 15 013 Sec 15 T26S R30E SWSE 1950FNL 2310FEL 32.044986 N Lat, 103.867965 W Lon

RKI EXPLORATION & PROD LLC 3500 ONE WILLIAMS CENTER MD 35 TULSA, OK 74172 Ph: 539-537-1196 Fx: 539 573 2922

CAITLIN O'HAIR SUBMITTER E-Mail: caitlin.ohair@wpxenergy.com

Ph: 539-573-3527

CAITLIN O'HAIR SUBMITTER

E-Mail: caitlin.ohair@wpxenergy.com

Ph: 539-573-3527

NM EDDY

**BRUSHY DRAW-WOLFCAMP** 

RDX 15 13 Sec 15 T26S R30E SWNE 1950FNL 2310FEL 32.044579 N Lat, 103.868003 W Lon