Form 3160-5 (June 2015) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMNM89057	
				6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well				8. Well Name and No. SNAPPING 12-1 FED 522H	
S Oil Well Gas Well Other				9. API Well No.	
2. Name of Operator Contact: LINDA GOOD DEVON ENERGY PRODUCTION CONE-Mail: linda.good@dvn.com				9. APT well No. 30-015-44738-(	)0-X1
3a. Address 333 WEST SHERIDAN AVEN OKLAHOMA, OK 73102	3b. Phone No. (include area code). The Field and Pool or Exploratory Area Ph: 405-552-6558 ARTESIA COTRICT				
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		MAR 1 1 2019		11. County or Parish, State EDDY COUNTY, NM	
Sec 12 T26S R31E SENW 2325FNL 1790FWL 32.058487 N Lat, 103.737679 W Lon					
	PPOPPIATE BOX(ES)		EIVED	REPORT OR OT	
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, TYPE OF SUBMISSION TYPE OF ACTION					
	□ Acidize □ Deepen □ Production (Start/Resume) □ Water Shut-Off				
Notice of Intent	Acture Alter Casing	Hydraulic Fracturing	Reclam		□ Well Integrity
Subsequent Report	Casing Repair	□ New Construction			Other
Final Abandonment Notice	Change Plans	Plug and Abandon	<ul> <li>Temporarily Abandon</li> <li>Water Disposal</li> </ul>		Change to Original A PD
	Convert to Injection	Plug Back			
13. Describe Proposed or Completed Op If the proposal is to deepen direction. Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f Upon review of the CBL, the T per the COA's the TOC needs	ally or recomplete horizontally, rk will be performed or provide doperations. If the operation re- bandonment Notices must be fil inal inspection.	give subsurface locations and measure the Bond No. on file with BLM/BIA sults in a multiple completion or reco ed only after all requirements, includ requirements on the Snapping	red and true vo Required su mpletion in a ing reclamatio	ertical depths of all pertir bsequent reports must be new interval, a Form 310	nent markers and zones. e filed within 30 days 60-4 must be filed once
up to 4650' respectively. Afte injection down the 5-1/2"x9-5/ 700 psi, indicating that we will annulus to remediate the low to perform the remediation aft	r running the cement eval 8" annulus. We were able be able to perform a brac TOC. Devon Energy Pro- er the frac that is schedul	luation log we attempted to es e to achieve an injection rate of denhead squeeze down the 5- duction Co., LP respectfully re ed to start approximately 2/28	tablish of 2 bpm an 1/2"x9-5/8" quest perm /19.	ACCEPUS	FOF RECORD MOCD 4/1-19 2101 UALICE
During the frac job we will tie a pop-off set at 1500 psi. The frac we will tie into 5-1/2"x9-5. Based off the previous injectio	Pressure will be monitore 8" annulus and attempt to on test performed we have	ed and recorded at all times. <i>I</i> o establish an adequate injecti	After the on rate.	OCD Ar	rtesia
14. I hereby certify that the foregoing is	Electronic Submission # For DEVON ENERG	454973 verified by the BLM Wel Y PRODUCTION COM LP, sent essing by PRISCILLA PEREZ of	to the Carls	bad	
Name (Printed/Typed) LINDA GO	Title REGUL	ATORY SP	ECIALIST		
Signature (Electronic	Date 02/18/2	Date 02/18/2019			
	THIS SPACE FO	OR FEDERAL OR STATE	OFFICE U	SE	
Approved By_LONG VO					
Conditions of approval, if any, are attached certify that the applicant holds legal or eq which would entitle the applicant to cond	e subject lease	ase Office Carlsbad			
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.					
(Instructions on page 2) <b>** BLM REV</b>	ISED ** BLM REVISE	D ** BLM REVISED ** BLN	I REVISE	D ** BLM REVISE	:D **

×4

## Additional data for EC transaction #454973 that would not fit on the form

## 32. Additional remarks, continued

6

, **L** 

perform the bradenhead squeeze to bring TOC above the COA requirement. If we are able to establish an injection rate we will remediate the low TOC by pumping a bradenhead squeeze down the 5-1/2"x9-5/8" annulus.

The Weatherford Ultraview log is too large to attach to this sundry, so I will email it to Long Vo. with the BLM.