Form 3160-5 (June 20+5) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals_APR 0 1 2019					FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMNM41645 6. If Indian, Allottee or Tribe Name				
SUBMIT IN TRIPLICATE - Other instructions on page 2						9. Well Neuro and No.			
I. Type of Well					8. Well Name and No. FEDERAL 13 COM 2				
2. Name of Operator CIMAREX ENERGY COMPANY OF CO-Mail: DEYLER@MILAGRO-RES.COM					9. API Well No. 30-015-33344-00-C2				
3a. Address 600 N MARIENFELD STE 600 MIDLAND, TX 79701	(include area code) 7-3033			10. Field and Pool or Exploratory Area WHITE CITY-WOLFCAMP					
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)						11. County or Parish, State			
Sec 13 T25S R26E NESW 1565FSL 1400FWL						EDDY COUNTY, NM			
12. CHECK THE AP	PROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE	, REP	ORT, OR OT	HER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION								
□ Notice of Intent	Acidize	pen 🖸 Produc		ction (Start/Resume)		🗖 Water S	hut-Off		
_	Alter Casing	🗖 Hydi	aulic Fracturing	🗖 Reclan	nation		🗖 Well Int	egrity	
Subsequent Report	Casing Repair		Construction		Recomplete				
Final Abandonment Notice	Change Plans Convert to Injection	🛛 Plug 🗖 Plug	and Abandon Back	-	irily Abandon isposal				
Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for fi 01/27/19: TAG EXISTING CIB SET 4-1/2" CIBP ON TOP OF 01/28/19: TAG CIBP @ 9,220' 01/31/19: CUT 4-1/2" CSG. @ TO 1,000# X HOLD; PUMP 30 02/01/19: DID NOT TAG CMT 02/02/19: TAG CMT. @ 8,357' 02/03/19: PUMP 45 SXS.CMT 02/04/19: TAG CMT. @ 5,325' 02/05/19: PERF. SQZ. HOLES SXS.CMT. @ 2,140'(PER BLM 02/06/19: PERF. SQZ. HOLES	operations. If the operation res andonment Notices must be file nal inspection. P @ 9,985'; CUT X POOF STUCK PKR. @ 9,200'(P ; PUMP 25 SXS.CMT. @ 8,600' - NOT FREE; ATT 9 SXS. CMT. @ 8,650'(PE 9 SXS. CMT. @ 8,650'(PE 9 CUG; PUMP 30 SXS.C ; CUT X PULL 4-1/2" CSC ; OUT X PULL 4-1/2" CSC ; OUT X PULL 4-1/2" CSC ; OUMP 45 SXS.CMT. @ 5 @ 2,090'; ATTEMPT TC 1; WOC X TAG CMT. @ 5 @ 1,505'; ATTEMPT TC	ults in a multiple d only after all r <u>PER BLM); CI</u> 9,200'-8.950 EMPT TO E8 <u>R BLM); WO</u> MT. @ 8,650 G. @ 5,530'. 5,175'-5,025 EST. INJ. R 1,911. EST. INJ. R	e completion or reco equirements, include <u>BG. @ 9,220'(PI RC. WELL W/ M</u> ST. INJ. RATE IN C. (<u>PER BLM</u>); W(<u>Accepted</u> ATE - PRES. UF ATE - PRES. UF	mpletion in a ing reclamation ER BLM); I.L.F. VTO CSG. VTO CSG. Gor record P TO 800# P TO 800#	CUT -	PRES. UP PRES. UP RECL PRES. UP RECL PRES. UP REC PRES. UP	60-4 must be file and the operator AMATION PR ATTACHE	once has OCEDURE	
	Electronic Submission #4 For CIMAREX ENEI tted to AFMSS for processi	RGY COMPA	IY OF CO, sent to	o the Carlst	bad				
Signature (Electronic S	Signature (Electronic Submission)		Date 02/16/2019		ACCEPTED F		OR RECORD		
	THIS SPACE FO	R FEDERA	L OR STATE		SE				
Approved By Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any pe			Title Office	willfully to re	BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE			ENT	
States any false, fictitious or fraudulent s	tatements or representations as t	to any matter wi	thin its jurisdiction.						

(Instructions on page 2) ** BLM REVISED **

Additional data for EC transaction #454911 that would not fit on the form

32. Additional remarks, continued

SXS.CMT.@ 1,555'; WOC X TAG CMT. @ 1,392'; PERF.SQZ. HOLES @ 262'. 02/07/19 SQZ. X CIRC. TO SURF., FILLING ALL ANNULI, 120 SXS.CMT. @ 262'-3'; DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; VERIFY CMT. TO SURF. ON ALL ANNULI; WELD ON STEEL PLATE TO CSGS. X INSTALL DRY HOLE MARKER.

WELL PLUGGED AND ABANDONED 02/07/19.

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- 1 The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment. Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3 The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7 At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crystal Weaver Environmental Protection Specialist 575-234-5943

Shelly Tucker Environmental Protection Specialist 575-234-5979

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612