
	• •					
Form 3160-5 (June 2015) UNITED STATES NMOCD DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT			a t .	FORM APPROVED OMB No. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NM-29610		
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill of to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit of CA/Agreement, Name and/or No.		
Oil Well 🗹 Gas Well				8. Well Name and No. HUGGINS DRAW FED COM #2		
2. Name of Operator JALAPENO CORPORATION				9. API Well No. 30-005-61262		
3a. Address PO BOX 1608, ALBUQUERQUE NM, 87103-1608 3b. Phone No. (include area code) (505) 242-2050				10. Field and Pool or Exploratory Area UNDESIGNATED ABO		
4. Location of Well (Footage, Sec., T.,R.,M., 'or Survey Description)				11. Country or Parish, State		
660' FEL & 990' FNL. SEC 31, T5S, R24E				CHAVES, NEW MEXICO		
	CK THE APPROPRIATE BOX(ES) T				C DATA	
TYPE OF SUBMISSION						
✓ Notice of Intent	Alter Casing	Deepen Hydraulic Fracturing		luction (Start/Résume) amation	Water Shut-Off Well Integrity	
Subsequent Report	Casing Repair	New Construction		omplete	Other	
Final Abandonment Notice	Change Plans	Plug and Abandon Plug Back		nporarily Abandon ter Disposal		
the proposal is to deepen directionally or recomplete horizontally, give subsurface locating outstand and the or which the work will be perfonned or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has detennined that the site is ready for final inspection.) JALAPENO CORPORATION WOULD LIKE TO REQUEST A REVISION OF THE APPROVED PLAN TO PLUG THE HUGGINS DRAW #2 WELL. THE CHANGES ARE BETWEEN 903' TO THE SURFACE, BEGINNING AT POINT 6. COMPLETE PLAN AS FOLLOWS: CEMENT FROM 4181' TO 3557', WOC & TAG @ OR ABOVE 3557'. FILL HOLE WITH SALT WATER SPACING GEL FROM 3555' TO 1600'. PERFORATE AT 1600' AND SQUEEZE CEMENT BEHIND CASING TO 1400' TO ISOLATE GLORIETTA AND YESO FORMATIONS. CEMENT FROM 1600' TO 1400', WOC & TAG. FILL HOLE WITH SPACING GEL FROM 1400' TO BELOW 903'. FILL HOLE WITH SPACING GEL FROM 1400' TO BELOW 903'. FILL HOLE WITH SPACING GEL FROM 1400' TO BUC & 303', CEMENT TO 803', WOC & TAG. FILL HOLE WITH SPACING GEL FROM 1400' TO SURFACE, INSIDE AND OUTSIDE CASING. WOC & TAG. FILL HOLE WITH SPACING GEL FROM 803' TO 60'. PERFORATE AT 60' AND CIRCULATE CEMENT TO SURFACE, INSIDE AND OUTSIDE CASING. WOC & TAG. FILL HOLE WITH SPACING GEL FROM 803' TO 60'. PERFORATE AT 60' AND CIRCULATE CEMENT TO SURFACE, INSIDE AND OUTSIDE CASING. WOC & TAG. FILL HOLE WITH SPACING BEL FROM 803' TO 60'. PERFORATE AT 60' AND CIRCULATE CEMENT TO SURFACE, INSIDE AND OUTSIDE CASING. WOC. NSTALL DRY HOLE MARKER. THIS WORK WILL BE DONE BY THE APPROVED DEADLINE OF MARCH 29, 2019, PROVIDED THAT THE BLM IS REOPENED AND A REPRESENTATIVE OF THE BLM IS ABLE TO BE PRESENT TO WITNESS THE WORK DONE. SEE ATTACHEDYME						
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) JULIE A. PASCAL OIL AND CAS ASSI Title				OCIATE, JALAPENO CO	DRPORATION	
Signature Auch' (1)	Hascal	Date		AD011182010	+ - //	
THE SPACE FOR FEDERAL OR STATE OFICE USE NUMERAL						
Approved by Conditions of approval, if any, are attach certify that the applicant holds legal or e which would entitle the applicant to cond Title 18 U.S.C Section 1001 and Title 43 any false, fictitious or fraudulent stateme (Instructions on page 2)	quitable title to those rights in the subj duct operations thereon.	for any person knowing	y and will		AGEMENT AL	
					-	

Ċ

Schematic after P&A

1

Huggins Draw #2 API: 30-005-61262 S31-T5S-R24E, 990' FNL & 660' FEL Chaves County, New Mexico




NOT TO SCALE

Schematic before P&A

1

<u>Huggins Draw #2</u> API: 30-005-61262 S31-T5S-R24E, 990' FNL & 660' FEL Chaves County, New Mexico



NOT TO SCALE

Huggins Draw Fed Com 2 30-005-61262 Jalapeno Corporation January 31, 2019 Conditions of Approval

- 1. Operator shall set a Class C plug from 4,181'-3,557' to seal the producing formation and the Abo Formation. WOC and Tag as proposed.
- 2. Operator perf and squeeze at 1,600' as proposed and place a balanced Class C plug from 1,600'-1,400' to isolate the Glorietta Formation. WOC and tag as proposed.
- 3. Operator perf and squeeze at 903' as proposed and place a balanced Class C plug from 903'-surface.
- 4. See Attached for general plugging stipulations.

JAM 013119

BUREAU OF LAND MANAGEMENT Roswell Field Office 2909 W. Second Street Roswell, New Mexico 88201 575-627-0272

General Requirements for Plug Backs

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from this approval.

If you are unable to plug back the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. Call 575-627-0205.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Subsequent Plug back Reporting</u>: Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed</u>.

7. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.