
Form 2160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR ISDAO BUREAU OF LAND MANAGEMENT TO THE INTERIOR ISDAO BUREAU OF LAND MANAGEMENT BUREAU OF LAND MANAGEMENT TO THE INTERIOR ISDAO BUREAU OF LAND MANAGEMENT BUREAU OF LAND MANAGEMENT TO THE INTERIOR ISDAO BUREAU OF LAND MANAGEMENT BUREAU OF LAND MA

SUNDRY NOTICES AND REPORTS ON WELLS ATTESIE Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.						6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No.			
1. Type of Well ☑ Oil Well ☐ Gas Well ☐ Other						8. Well Name and No. GOVERNMENT AB FEDERAL 13		
Name of Operator						9. API Well No. 30-015-40920-00-S1		
3a. Address HOUSTON, TX 77210	3b. Phone No. (include area code) Ph: 432-685457474 CONSERVAT				10. Field and Pool or Exploratory Area ONOLD MILLMAN RANCH			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description Sec 10 T20S R28E SENW 2135FNL 1725FWL)	MAR 1 1			11. County or Parish, State EDDY COUNTY, NM		
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE,						REPORT OR OTH	IFR DATA	
	TROTIGITE BOX(ES)					TELL OK 1, OK OTT		
TYPE OF SUBMISSION								
■ Notice of Intent	☐ Acidize	☐ Dee	•	_	☐ Production (Start/Resume)		☐ Water Shut-C	
☐ Subsequent Report ☐ Casing Repair			☐ Hydraulic Fracturing ☐ New Construction		☐ Reclamation ☐ Recomplete		Other	/
☐ Final Abandonment Notice	Change Plans	_	g and Abandon	_	-		U Other	
	Convert to Injection				-			
Attach the Bond under which the wor following completion of the involved testing has been completed. Final At determined that the site is ready for fi TD-6710' PBTD-6667' Pe OXY USA WTP LP respectfull evaluated for future recomplet 1. POOH w/ prod equipment,	operations. If the operation re- pandonment Notices must be fil- inal inspection. erfs-6353-6494' y requests to temporarily ion in the Delaware.	sults in a multip ed only after all abandon this	le completion or re requirements, incl s well. It is curr	ecompl luding rently	detion in a reclamation	new interval, a Form 316 n, have been completed a	0-4 must be filed onc	e
2. Notify BLM/NMOCD of cas	ing integrity test 24hrs in	advance.	٠					•
3. RU pump truck, circulate w		essure test ca	sing to 500# fo	or 30	min.	v	,	·
	Electronic Submission # For OXY USA WI nmitted to AFMSS for proc	P LIMITED PT	NRSHIP, sent SCILLA PEREZ	to the	Carlsbac 2/14/2019	d (19PP1068SE)		
Name (Printed/Typed) DAVID ST	EWART		Title SR. R	REGU	LATORY	ADVISOR		
Signature (Electronic S	Submission)		Date 02/13	/2019) 			
	THIS SPACE FO	OR FEDERA	AL OR STATI	E OF	FICE U	SE		
Approved By /s/ Jon Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conduct the second of	uitable title to those rights in the act operations thereon.	subject lease	Carlsba	ad	Field	gineer d Office		2019
States any false, fictitious or fraudulent	statements or representations as	to any matter w	rithin its jurisdiction	mu WII. O <mark>n</mark> .	пану ю та	ake to any department or	agency of the United	

OXY USA WTP LP - Proposed Government AB #13 API No. 30-015-40920



14-3/4" hole @ 374' 11-3/4" csg @ 374' w/ 320sx-TOC-Surf-Circ

10-5/8" hole @ 3040' 8-5/8" csg @ 3040' w/ 2375sx-TOC-Surf-Circ


7-7/8" hole @ 6710' 5-1/2" csg @ 6710' w/ 930sx-TOC-Surf-Circ

Perfs @ 6353-6494'

CIBP @ 6320' w/ DB 4sx to 6285'

PB-6667'

OXY USA WTP LP - Current Government AB #13 API No. 30-015-40920



14-3/4" hole @ 374' 11-3/4" csg @ 374' w/ 320sx-TOC-Surf-Circ

10-5/8" hole @ 3040' 8-5/8" csg @ 3040' w/ 2375sx-TOC-Surf-Circ

7-7/8" hole @ 6710' 5-1/2" csg @ 6710' w/ 930sx-TOC-Surf-Circ

Perfs @ 6353-6494'

PB-6667'

TD-6710

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

Definition: A temporarily abandoned well is a completion that is not capable of production in paying quantities but which may have future value. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Note: TA status "will be effective for a period up to 1 year from the date of NOI approval and can be renewed annually thereafter" per IM NM-2016-017.

- 1. A bridge plug (CIBP) or packer must be installed 50 to 100 feet above any open perforations or open hole. A CIBP must be capped with either a minimum of 25 sacks of cement if placed with tubing or 35 feet of cement if placed with a bailer. The top of the cement must be verified by tagging.
- 2. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. If the well does not pass the casing integrity test, then the operator shall, within 30 days, submit a procedure to either repair the casing or to plug and abandon the well.
- 3. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 4. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if it is not isolated by a packer.
- 5. A bradenhead test must be conducted. If the test indicates a problem, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- 6. Submit a subsequent Sundry Notice (Form 3160-5) with the following information:
 - a. A well bore diagram with all perforations, CIBP's, and tops of cement on CIBP's.
 - b. A description of the temporary abandonment procedure.
 - c. A clear copy or the original of the pressure test chart.