

In Reply Refer to 3162.4 (P0220)

Gentlemen:

United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene Carlsbad, New Mexico 88220-6292 HOBBS Octuber blm.gov

OCT 1 0 2018

RECEIVED

Cimarex Energy Corporation 202 S. Cheyenne Ave, Suite 1000 Tulsa, OK 74103



September 24, 2018

Carlsbad Field Office OCD Hobbs

Your Application for Permit to Drill (APD) for the below referenced well has expired because drilling has not commenced per Onshore Order #1:

LEASE	WELL NAME & NUMBER	API#	ORIGINAL APD EXPIRATION	EXTENSION EXPIRATION
NM96835	LIBERTY 24 FED COM - 3H	3001542261	03/24/2016	03/24/2018

If a well has not been spud, but site construction activities have occurred please contact Jim Amos at (575) 234-5909 for surface reclamation instructions. If drilling operations have commenced on a well send all necessary reports (spud, casing/cementing, etc., 1 original and 3 copies) to the BLM so we may correct our records.

If you wish to drill this well at a later date, please submit a complete application (In AFMSS II data base) to this office. Since the original APD have expired, the resubmitted APD will be subject to all processing requirements including the \$9,790 application fee and the 30-day posting period. Please note on the resubmitted APD that they were previously approved and we will review the expired file for information which will help expedite the processing.

If you have any questions, please contact Duncan Whitlock at (575) 234-5926.

Sincerely,

Whitlork of

Cody Layton Assistant Field Manager, Lands and Minerals

RECEIVED

OCT 1.7 2018

DISTRICT II-ARTESIA O.C.D.

Page 1 of 1