Form 3150-5 (June 2015)

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT SPECIAL PROPERTY OF THE INTERIOR
BUREAU OF LAND MANAGEMENT SPECIAL PROPERTY OF THE INTERIOR OF THE INTERIOR

SUNDRY NUTICES AND REPORTS ON WELLS	_
Do not use this form for proposals to drill or to referren A	ക്കരുട്ടത
Do not use this form for proposals to drill or to receive an Abandoned well. Use form 3160-3 (APD) for such proposals.	uco na

6 If Indian Allottee or Tribe Name

abandoned wel	II. Use form 3160-3 (APE	)) for such/p	toposals.Lill C	cong.	o. If indian, Another of	·
SUBMIT IN 1	TRIPLICATE - Other inst	ructions on	page 2		7. If Unit or CA/Agree	ement, Name and/or No.
Type of Well     Oil Well	ner				8. Well Name and No. LIMESTONE DRA	W FEDERAL 1
2. Name of Operator MAMMOTH EXPLORATION L		GRIFFIN HA'			9. API Well No. 30-015-33211-0	0-S1
3a. Address 200 N LORAINE ST STE 1100 MIDLAND, TX 79701	)	3b. Phone No Ph: 432.30 Fx: 432.686			10. Field and Pool or I LIMESTONE DR	Exploratory Area RAW-MORROW
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)				11. County or Parish,	State
Sec 36 T20S R25E NWNW 65	50FNL 448FEL				EDDY COUNTY	, NM
12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE OI	F NOTICE,	REPORT, OR OTH	IER DATA
TYPE OF SUBMISSION		,	TYPE OF	ACTION		
Notice of Intent	☐ Acidize	☐ Dee	pen	☐ Product	ion (Start/Resume)	■ Water Shut-Off
Notice of Intent	☐ Alter Casing	☐ Hyd	raulic Fracturing	☐ Reclam	ation	■ Well Integrity
☐ Subsequent Report	□ Casing Repair	□ New	Construction	☐ Recomp	olete	☐ Other
☐ Final Abandonment Notice	☐ Change Plans	Plug	and Abandon	□ Tempor	arily Abandon	,
	☐ Convert to Injection	🔀 Plug	Back	☐ Water I	Disposal	
determined that the site is ready for f.  1) MIRU PU. ND WH, NU BOI 2) POOH w/ 2-3/8" tbg standir 3) MIRU Wireline Co. If neces cmt on top of CIBP. POOH. 4) Pick up & RIH w/ 3-1/8" gur wireline Co. 5) PU tbg and treating pkr and 6) MIRU acid co., spot acid, a co. Flow well back. 7) RU swab tools and comme 8) Release treating pkr and Po 9) If necessary, frac as per for	P. Ing back. Isary RIH & set secondary Ins and perf the Bonesprin I RIH to setting depth @ 4 Ind acidize Bonespring pe Ince swab testing the Bone	g formation ( 1370'. rfs w/ 4500 g espring.	⊕ 4422'-4490' @	& dump ba	IO acid AF	RECEIVED PR 2 5 2019 FILARTESIA O.C.D.
14. I hereby certify that the foregoing is	Electronic Submission #	EXPLORATION	N LLC, sent to th	ne Carlsbad	-	
Name (Printed/Typed) RICK PET	TIONS EN	GINEER				
Signature (Electronic	Submission)		Date 04/12/2	019		
	THIS SPACE FO	OR FEDERA			SE	
/9/ .1/	onathon Shepard	ŕ	Patral		nainaar	-7 APR 1 9 2019
		— — <del> </del>	TiPetrole		ngineer	Date
Conditions of approval, if any, are attache certify that the applicant holds legal or eq which would entitle the applicant to conduct the conduction of the	uitable title to those rights in the		Carlsba	ad Fie	ld Office	
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a statements or representations as	crime for any po	erson knowingly and ithin its jurisdiction.	willfully to m	ake to any department or	agency of the United


## Additional data for EC transaction #461316 that would not fit on the form

### 32. Additional remarks, continued

10) PU tbg & BHA and RIH to setting depth below perfs.
11) ND BOP, NU WH.
12) PU pump and rods and RIH to SN setting depth.
13) Space out pump, load and test for pump action.
14) Hang well on, turn to produciton, and commence testing.
15) RD and release all equipment. Clean location.

# Mammoth Exploration LLC


LIMES	STONE DRAW FE	DERAL NO	. 1 CURRE	NT					
Location: 650' FNL & 448' FEL		Field: LiM	ESTON		Format	ion: STRAV		NN/ATOKA	
County:	EDDY N	EW MEXICO	Sec 35 - T2	20S - R2	5E				
API# 30	-015-33211			Size	Wgt, lb/ft	Grade	Hole Size	Depth	Sx. Cmt.
GL:	3,578'		Surf. Csg:	13-3/8"	48		17-1/2"	395'	810
KB:	3,596'		Casing:	8-5/8"	32		11-	2,510'	820
Spud:	1/3/2006			5-1/2"	17		7-7/8"	10,202	900
PBTD:	10,087'								



OD	2 3/8"		Thread	WT	4.7#	Grade N-80
OD			Thread	WT		Grade
			and the second	a de la companya de La companya de la co	en anticonomica en en esta en en en entre en el como de la como de Como anticonomica en entre en	
Rods:	No.	Length		Pump:		
		0		Type:		
		0		Size		
	•	0		Barrel		
		0		Spaced (a)		
		0		Pumping Unit		
		0		Stroke:	Sheave:	Tbg Spoot:
K-Bar		0		SPM:	Belts:	
Subs:				Motor:	Size or	HP
			College Colleg	y dia magamatan kaban kaping menghali menghali melalah selatah kelalah kelalah kelalah kelalah kelalah kelalah Kelalah kelalah kelala	al factorist de la company de la company La company de la company d	
Tubing & BHA				TD 10,020'	PBTD 10,087'	KB 18.5
Joints	Description			Length	Set @	Formation:
266	2 3/8" Tubin	g		8390'	8390'	
1	2 3/8" API S	eat Nipple				
						Perforations:
		<del></del>				
				i i		

# Mammoth Exploration LLC

LIMEST	ONE DRAV	V FEDERAL NO	. 1 PROPC	SED					
Location: 6	550' FNL & 448	'FEL	Field: LIMESTONE Formation:		BONESPRING				
County: ED	DY	NEW MEXICO	Sec 35 - T2	20S - R2	5E.				
API# 30-01	5-33211			Size	Wgt, lb/ft	Grade	Hole Size	Depth	Sx. Cmt.
GL:	3,578'		Surf. Csg:	13-3/8"	48		17-1/2"	395'	810
KB:	3,596'		Casing:	8-5/8"	32		11-	2,510'	820
Spud:	1/3/20	06		5-1/2"	17		7-7/8"	10,202	900
PBTD:	10,087	,							



OD	. 2 3/8"		Thread	wr	4.7#	Grade N-80
OD			Thread	WT		Grade
Rods:	No.	Length	Туре	Pump: 1.5" I	Rod Pump	
7/8" & 3/4"	180	4500		Type:		
		_ 0		Size		
		0		Barrel		
		0		Spaced @		
		0		Pumping Unit		
		U		Stroke:	Sheave:	Thg Spool:
K-Bar		0		SPM:	Belts:	
Subs:				Motor:		or HP
material production of the section o	er kirki ki membangan Birangan Kabupatèn Kabupatèn	o service de la companya. La companya di service de la companya di service de la companya di service de la companya di service di servic	i kalindaga aksilis isa uni disertakan 13 Kalindaga kalindaga kalindaga kalindaga	region con relation per programmers.	ang da Abrahaman ang Kalabana Kalaban ang Kabupatèn Banahan B	
l'ubing & BHA				TD 10,020	0' PBTD 10,0	87' KB 18.5
loints	Description			Length	Set (a)	Formation:
140	2 3/8" Tubin	g		4490'	4490'	
1	2 3/8" API S	at Nipple				
		L				Perforations:
	<del></del>	L	<del></del>			4422'-4490'
			ļ			
	1		1	1	1	

#### **BUREAU OF LAND MANAGEMENT**

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

### Conditions of Approval for Permanent Abandonment of a Production Zone

- 1. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822. For wells in Lea County, call 575-393-3612
- 2. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,100 feet, a 3M system for a well not deeper than 13,600 feet, or a 5M system for a well not deeper than 22,700 feet (all depths are for measured well depth).
- 3. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.
- 4. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the approved depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours. In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement (or 35 feet with a bailer). Before pumping cement on top of CIBP, a tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary. Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.
- 5. <u>Subsequent Plug back Reporting:</u> Within 30 days after plug back work is completed, file a Subsequent Report (Form 3160-5) to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed.</u> If plugging back to a new zone submit a Completion Report (Form 3160-4) with the Subsequent Report.
- 6. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.
- 7. If well location is within the Timing Limitation Stipulation Area for Lesser Prairie-Chicken: From March 1<sup>st</sup> through June 15<sup>th</sup> annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted.