Submit 1 Copy To Appropriate District Office	State of New Mariso	Form C-103
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Re	sources Revised July 18, 2013 WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSER WAYI ON 2019	SION 30-015-31439
District III - (505) 334-6178	1220 South St. Francis D	L 5 Indicate Type of Leace
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	s energial s	G. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	•	
SUNDRY NOT	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLIC	SALS TO DRILL OR TO DEEPEN OR PLUG BAC CATION FOR PERMIT" (FORM C-101) FOR SUC	K TO A
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other	8. Well Number
2. Name of Operator		9. OGRID Number
OXY USA 3. Address of Operator	Inc.	16696 10. Pool name or Wildcat
P.O. Box 50250 Midland, TX 79710		Cetar Canyon Delaware
4. Well Location	1.	•
Unit Letter:	1650 feet from the south	
Section Zl	Township 245 Range 11. Elevation (Show whether DR, RKB,	
	2936	KI, GR, etc.)
12. Check A	Appropriate Box to Indicate Nature	of Notice, Report or Other Data
NOTICE OF IN		SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK		EDIAL WORK
TEMPORARILY ABANDON DULL OR ALTER CASING	l l	MENCE DRILLING OPNS.□ P AND A □ NG/CEMENT JOB □
DOWNHOLE COMMINGLE	MIDELII EE OOMI E	NG/CEMENT JOB
CLOSED-LOOP SYSTEM		
OTHER:	OTHI	
of starting any proposed wo	rk). SEE RULE 19.15.7.14 NMAC. For	nt details, and give pertinent dates, including estimated date Multiple Completions: Attach wellbore diagram of
proposed completion or rec	ompletion.	, ,
4/16-4/25/19		
MIRU PU, POOH w/ rods & pump. ND W	/H, NU BOP. POOH w/ tbg. RIH w/ CIBP & set	@ 4822'. RIH w/ tbg & tag CIBP @ 4822', circ hole w/ 10# MLF,
M&P 25sx CL C cmt, PUH, WOC. RIH & t	ag cmt @ 4640', PUH to 3070', M&P 36sx CL C	cmt, PUH, WOC. RIH & tag cmt @ 2770', POOH. RIH & perf @ NMOCD, appr spotting plug. RIH to 2750', M&P 25sx CL C cmt,
PUH, WOC. RIH & tag cmt @ 2464'. RIH	& perf @ 1670', RIH & set pkr @ 1366', attem	pt to EIR, pressure to 500#, no rate or loss. Notify NMOCD, appr
spotting plug. RIH to 1720', M&P 25sx C	L C cmt, PUH, WOC. RIH & tag cmt @ 1456'. I	RIH & perf @ 634', attempt to break circ w/ total of 145bw, no
signs of circ, SI w/ 400#. Notity NMOCD, 498'. Notify NMOCD, appr perf @ 400'.	appr sqz. RIH & set pkr @ 325, sqz 60sx CL C RIH & perf @ 400' attempt to break circ w/ tr	cmt down to perfs, displ to 525', SI w/ 400#. RIH & tag cmt @ otal of 65bw, no signs of circ, SI w/ 400#. Notify NMOCD, appr
sqz. ND BOP, NU flange, M&P 50sx CL C	cmt to perfs @ 400', SI w/ 300#. RIH & tag cm	it @ 80', Notify NMOCD, appr tag, perf & circ. RIH & perf @ 70',
EIR, M&P 30sx cmt, circ cmt to surf. Visu	ually verify cmt to surf. RDPU.	·
	•	Approved for plugging of well here only. Liability under band is retained pending receipt
Spud Date:	Rig Release Date:	of C-103 (Subsequent Report of Well Plugging)
Spud Date.	Rig Release Date.	which may be found at OCD Web Page under
I hereby certify that the information a	above is true and complete to the best of m	y knowledge and belief.
SIGNATURE / / /	TITLE Sr. Regula	atory Advisor DATE 517[19]
Type or print nameDavid Stewar	t E-mail address: <u>dav</u>	rid_stewart@oxy.comPHONE:432-685-5717
For State Use Only		
114	•	A
APPROVED BY:	TITLE STATE	DATE 5/13/19