Form 3160-5 (June 2015)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT


**OCD** Artesia


FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No. NMNM26105

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use form 3160-3 (APD) for such proposals.

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					INIVITATIVIZOTOS			
					6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No. NMNM130613			
1. Type of Well ☐ Oil Well ☐ Gas Well ☐ Other					8. Well Name and No. PINTAIL 23 FEDERAL COM 1			
Name of Operator Contact: DAVID A EYLER CIMAREX ENERGY COMPANY OF CO-Mail: DEYLER@MILAGRO-RES.COM					9. API Well No. 30-015-33431-00-S1			
3a. Address 600 N MARIENFELD STE 600 MIDLAND, TX 79701	(include area code) 7-3033		10. Field and Pool or Exploratory Area COTTONWOOD DRAW					
4. Location of Well (Footage, Sec., T			11. County or Parish, State					
Sec 23 T25S R26E SWNW 13			EDDY COUNTY, NM					
12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INDICAT	TE NATURE OI	F NOTICE,	REPORT, OR OTH	ŒR D	ATA	
TYPE OF SUBMISSION	TYPE OF ACTION							
Notice of Intent   ■ Notice of Intent	☐ Acidize	Deepen		□ Product	ion (Start/Resume)		ater Shut-Off	
_	☐ Alter Casing	☐ Hydraulic Fracturing		□ Reclams	ation		ell Integrity	
☐ Subsequent Report	□ Casing Repair	■ New Construction		☐ Recomp	olete		ther	
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon     □			orarily Abandon			
	Convert to Injection		Plug Back					
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.  1) SET 7" CIBP @ 10,230'; PUMP 25 SXS.CMT. @ 10,230'-10,430'; CIRC. WELL W/ MLF. **ID,O3D** 2) PUMP 55 SXS.CMT. @ 8,685'-8,505'(T/WCMP.); WOC X TAG CMT. PLUG. 3) PUMP 425 SXS.CMT. @ 5,465'-4,950'(T/BNSG.,7"DV TOOL); WOC X TAG CMT. PLUG. 4) PUMP 40 SXS.CMT. @ 3,491'-3,361'(9-5/8"CSG.SHOE); WOC X TAG CMT. PLUG. 5) PUMP 80 SXS.CMT. @ 1,941'-1,640'(T/DLWR., B/SALT); WOC X TAG CMT. PLUG. 6) MIX X CIRC. TO SURF. 70 SXS.CMT. @ 264'-3'(13-3/8"CSG.SHOE). 7) DIG OUT X CUT OFF WELLHEAD 3' B.G.L; WELD ON STEEL PLATE TO CSGS. X INSTALL DRY HOLE MARKER. DURING THIS PROCEDURE WE PLAN TO USE THE CLOSED-LOOP SYSTEM W/ A STEEL TANK AND HAUL CONTENTS TO THE REQUIRED DISPOSAL, PER OCD RULE 19.15.17.								
SEE ATTACHED FOR								
CONDITIONS OF APPROVAL								
	# Electronic Submission For CIMAREX ENE itted to AFMSS for process	ERGY COMPA	NY OF CO, sent to RAH MCKINNEY o	the Carlsb	n System ad 9 (19DLM0526SE)	JN <b>2</b> .	5 2019	
Name (Printed/Typed) DAVID A EYLER			Title AGENT	<del></del>	DISTHIC	THA	TESIAO.C.D.	
			DISILIE	2 16 11 71	. •			
Signature (Electronic S			Date 06/12/20	<del>"</del>				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved By James	almos_		Title SAET	-			6-22-19 Date	
Conditions of approval, if any, are attache certify that the applicant holds legal or equivicing yould entitle the applicant to condu	itable title to those rights in the	s not warrant or e subject lease	Office CFC	)				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a statements or representations as	crime for any pe to any matter wi	rson knowingly and thin its jurisdiction.	willfully to ma	ake to any department or	agency	of the United	





## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 38220 575-234-5972

## Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>minety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Dry Hole Marker: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged.</u>
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.