Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED

	OMB NO. 1004-0137 Expires: January 31, 2018
5.	Lease Serial No. NMNM53219

SUNDRY NOTICES AND REPORTS ON WELLS	
Do not use this form for proposals to drill or to re-enter an	
abandoned well. Use form 3160-3 (APD) for such proposals	

Do not use thi abandoned we	6. If Indian, Allottee or Tribe Name							
SUBMIT IN		7. If Unit or CA/Agreement, Name and/or No. NMNM90998						
Type of Well	ner	· · · · · · · · · · · · · · · · · · ·		Well Name and No. MCK!TTRICK 11 FEDERAL 2				
Name of Operator \ OXY USA WTP LIMITED PTN	Contact: IRSHIP E-Mail: david_stew	DAVID STEWART art@oxy.com		9. API Well No. 30-015-33270-00-S1				
3a. Address	3b. Phone No. (include area co Ph: 432-685-5717	de)	10. Field and Pool or Exploratory Area INDIAN BASIN-UPPER PENN ASSOC					
HOUSTON, TX 77210 4. Location of Well (Footage, Sec., T	., R., M., or Survey Description,			11. County or Parish, State				
Sec 11 T22S R24E NWNE 75	7FNL 1341FEL	•		EDDY COUNTY, NM '				
12. CHECK THE AR	PPROPRIATE BOX(ES)	TO INDICATE NATURE	OF NOTICE	E, REPORT, OR OTI	HER DATA			
TYPE OF SUBMISSION		ТҮРЕ	OF ACTION					
Notice of Intent ■ Notice of Intent Notice of Inten	☐ Acidize	□ Deepen	☐ Produc	ction (Start/Resume)	■ Water Shut-Off			
	☐ Alter Casing	☐ Hydraulic Fracturi	ig 🔲 Reclar	nation	■ Well Integrity			
☐ Subsequent Report	Casing Repair	■ New Construction	☐ Recon	•	Other			
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon		orarily Abandon				
	☐ Convert to Injection	☐ Plug Back	☐ Water	Disposal				
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. TD-8577'M 8469'V Perfs-8150-8278' 1. CIBP @ 8100' w/ 255x cmt to 8000' 7920								
 M&P 40sx cmt @ 7750-75 Perf @ 5975', sqz 60sx cm Perf @ 3170', sqz 50sx cm Perf @ 1620', sqz 45sx cm 	70' WOC-Tag It to 5815' WOC-Tag It to 3035' WOC-Tag It to 1500' WOC-Tag	JUN 2 .5 201	- CONDITIONS OF ALL NOVAL					
6. Perf @ 450', sqz 170sx cm 10# MLF between plugs-Abov	e ground steel tanks will b	oe Districti-Artesia	O.C.D.	Accepted for recor	26/19cd			
	#Lectronic Submission For OXY USA WT itted to AFMSS for process	163494 verified by the BLM P LIMITED PTNRSHIP, sen ing by DEBORAH MCKINNE	to the Carlsb Y on 04/30/20	ad 19 (19DLM0446SE)				
Name (Printed/Typed) DAVID ST	EVVARI	Title SR.	REGULATOR	Y ADVISOR				
Signature (Electronic S	Submission)	Date 04/3	0/2019					
	THIS SPACE FO	R FEDERAL OR STAT	E OFFICE (JSE				
Approved By	a. amos	Title 5	27		5-25-19 Date			
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to condition	iitable title to those rights in the		<i>D</i>					
Title 18 U.S.C. Section 1001 and Title 43		crime for any person knowingly		nake to any department or	r agency of the United			

OXY USA WTP LP - Proposed McKittrick 11 Federal #2 API No. 30-015-33270

170sx @ 450'-Surface

45sx @ 1620-1500' WOC-Tag

50sx @ 3170-3035' WOC-Tag

B S 3124


2 BS 5974 3 BS 7342

60sx @ 5975-5815' WOC-Tag

40sx @ 7750-7570' WOC-Tag いて、ファイム


CIBP @ 8100' W/ 25sx to 8000'
Cisco Cyn 8150

PB-8530'



14-3/4" hole @ 1567' 9-5/8" csg @ 1567' w/ 1300sx-TOC-Surf-Circ

Perf @ 3170'



Perf @ 5975'

8-3/4" hole @ 8577' 7" csg @ 8577' w/ 660sx-TOC-6110'-TS

Perfs @ 8150-8278'

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.