Form 3160-5 (June 2015)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

#### Lease Serial No. NMNM0557142

SUNDRY NOTICES AND REPORTS ON WELLSJUN 2.5 2019
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such

abandoned wel	l. Use form 3160-3 (APD) for s	ruch proposals.	SIAOCD	o. If indian, Anottee	or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Agreement, Name and/or No. NMNM106872		
Type of Well     Oil Well				8. Well Name and No. ROSS EG FED 7		
2. Name of Operator EOG Y RESOURCES INC	IUERTA esources.com		9. API Well No. 30-015-26945-00-C2			
3a. Address 104 S 4TH STREET ARTESIA, NM 88210	one No. (include area code) 575-748-4168	<del></del>	10. Field and Pool or Exploratory Area CEMETARY			
4. Location of Well (Footage, Sec., T.			11. County or Parish, State			
Sec 20 T19S R25E SENW 19			EDDY COUNTY, NM			
12. CHECK THE AF	PPROPRIATE BOX(ES) TO IN	DICATE NATURE O	F NOTICE,	REPORT, OR OT	HER DATA	
TYPE OF SUBMISSION						
□ Notice of Intent	☐ Acidize	☐ Deepen	☐ Producti	on (Start/Resume)	☐ Water Shut-Off	
	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclama	ation	■ Well Integrity	
Subsequent Report	·	■ New Construction	□ Recomp	lete	☐ Other	
Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	☐ Tempora	porarily Abandon		
	☐ Convert to Injection	🗖 Plug Back	□ Water D	isposal		
testing has been completed. Final Ab determined that the site is ready for fit 3/1/19 - MIRU all safety equipitubing. Pumped 100 bbls 10#3/4/19 - POOH with production 3/5/19 - RIH with GR/JB and to OK'd to set CIBP at tagged detop, no tag. 3/6/19 - Set a 7 inch CIBP at 7 at 6030 ft (per BLM). Tagged 03/7/19 - Circulated 235 bbls saft calc TOC. Spotted a 60 sx C Spotted a 25 sx Class C ceme 3/8/19 - Spotted a 30 sx Class	ment as needed. Opened well w brine down tubing. NU BOP. n equipment. agged hard at 8744 ft, couldn't g opth. Set a 4-1/2 inch CIBP at 87 7580 ft (per BLM) with 35 ft ceme CIBP at 6030 ft. alt gel. Spotted a 25 sx Class C (class C cement plug from 5820 ft. and plug from 3770 ft - 3601 ft. ta s C cement plug from 2292 ft - 21	ofter all requirements, including ith 1400 psi on tubing.  et through. Notified BL 44 ft with 35 ft Class Hent on top, no tag. Set a cement plug on top of Ct - 5440 ft, tagged. (BL ogged.	Bled down  M and Jim A cement on a 7 inch CIB  CIBP to 5877  M witnessed	n, have been completed  RECLA  MMQs  RECLA	AMATION PROCEDURE ATTACHED  CLAMATION E 9-12-19	
14. I hereby certify that the foregoing is  Comm Name (Printed/Typed) TINA HUE	Electronic Submission #465581 For EOG Y RESOUI nitted to AFMSS for processing by	RCES NC, sent to the C DEBORAH MCKINNEY	Haformation Arginal DT ALOS/16/201 ATORY SPE	ED-EDR-REC	CORD	
Name (17 mea/13/pea/) TINA FIOL	INTA	The REGUL	ATORT SPE			
Signature (Electronic S	Submission)	Date 05/15/20	019	AY 20 2019		
	THIS SPACE FOR FEI	DERAL OR STATE	OFFICE	GELAND MANAGE	IE MENT	
Ammound Pu		Tiel		SBAD FIELD OFFIC		
Approved By  Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conductive to conductive the applicant to conductive the				Date		
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a crime for statements or representations as to any m	r any person knowingly and natter within its jurisdiction.	willfully to ma	ke to any department of	or agency of the United	

### Additional data for EC transaction #465581 that would not fit on the form

#### 32. Additional remarks, continued

3/11/19 - Spotted a 30 sx Class C cement plug from 1201 ft - 980 ft, tagged. (BLM\_witnessed). Pumped a 30 sx Class C cement plug from 780 ft - 591 ft, tagged.

3/12/19a Perforated at 100 ft. Pressured up on casing to 500 psi for 5 min, held good. Spotted a 20 sx Class C cement plug from 150 ft up to surface.

5/14/19 - Cut off wellhead and installed dry hole marker. Cut off anchors and cleaned location. WELL IS PLUGGED AND ABANDONED.



# United States Department of the Interior

#### BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

## Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

- have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.
- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crystal Weaver Environmental Protection Specialist 575-234-5943

Melissa Hom Environmental Protection Specialist 575-234-5951

Kelsey Wade Evnironmental Protection Specialist 575-234-5996

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612