Form 3160-5 (August 2007)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

## NMOCD Artesia

FORM APPRO	VED
OMB No. 1004-	0131
Expires: July 31	201

Expires: July 31, 20


### SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

5. Lease Serial No. NMNM-4433 6. If Indian, Allottee or Tribe Name

abandoned wen. Ose i onn 5100-5	(APD) for such proposals.	
SUBMIT IN TRIPLICATE - Of	ner instructions on page 2.	7. If Unit of CA/Agreement, Name and/or No.
1. Type of Well  ☑ Oil Well ☐ Gas Well ☐ Other		8. Well Name and No. CALGARY FEDERAL #7
2. Name of Operator MACK ENERGY CORPORATION		9. API Well No. 30-005-64195
3a. Address P.O. BOX 960 ARTESIA, NM 88210-0960	3b. Phone No. (include area code) (575) 748-1288	10. Field and Pool or Exploratory Area ROUND TANK; SAN ANDRES
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description 2310 FNL & 1600 FWL, SEC. 24 T15S R28E	on)	11. Country or Parish, State CHAVES, NM
12. CHECK THE APPROPRIATE	BOX(ES) TO INDICATE NATURE OF NOTI	CE, REPORT OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION		
Notice of Intent  Acidize  Alter Casing  Casing Repair	Fracture Treat Rec	duction (Start/Resume)
Change Plans		nporarily Abandon
Final Abandonment Notice Convert to Injection  13. Describe Proposed or Completed Operation: Clearly state all proposed or Completed Operation: Clearly state a		er Disposal
Attach the Bond under which the work will be performed or following completion of the involved operations. If the oper testing has been completed. Final Abandonment Notices mudetermined that the site is ready for final inspection.)  1. SET 5.5" CIBP @ 2800', PRESSURE TEST CSG, CIRC 2. SPOT 25 SX CMT @ 2800' - 2550' - WOC & TAG 3. SPOT 50 SX CMT 500' - SURFACE 4. CUT OFF WELLHEAD, VERYFY CMT TO SURFACE, W (BELOW GROUND LEVEL DRY HOLE MARKER REQUIR	ation results in a multiple completion or recom st be filed only after all requirements, including	pletion in a new interval, a Form 3160-4 must be filed once
GC	8/22/19	
Accepted	for record - NMOCD	NM OIL CONSERVATION ARTESIA DISTRICT
		AUG 2 2 2019
14. I hereby certify that the foregoing is true and correct. Name (Prince)	nted/Typ <b>og</b> )	RECEIVED
Signature Lini A. Burk	Title AGENT  Date 07/31/2019	
	E FOR FEDERAL OR STATE OF	FIGE LINE
Approved by	C FOR FEDERAL OR STATE OF	FICE USE
Conditions of applicant olds legaller equitable title to those rights in the sub-entitle the applicant to enduct operations thereon.	or not warrant or certify office Office	Dat8/1(0/19
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make fictitious or traugulent statements or representations as to any matter	it a crime for any person knowingly and willfully within its jurisdiction.	to make to any department or agency of the United States any false,
(Instructions on page 2)	1/	

# MACK ENERGY CORPORATION CALGARY FEDERAL #7



### Calgary Federal 7 30-005-64195 Mack Energy Corporation August 16, 2019 Conditions of Approval

- 1. Operator shall place CIBP at 2,800' (50'-100' above top most perf) and place 25 sx of Class H cement on top as proposed. WOC and TAG.
- 2. Operator shall place a Class C cement plug from 780'-600" to seal the Yates Formation and the Bottom of the Salt.
- 3. Operator shall place a Class C cement plug from 500'-surface' to seal the 8-5/8' casing shoe.
- 4. See Attached for general plugging stipulations.

JAM 081619

#### BUREAU OF LAND MANAGEMENT Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 (575) 6270272

### Permanent Abandonment of Production Zone Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from this approval.

If you are unable to plug back the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

- 2. Notification: Contact the BLM Roswell Field Office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, during office hours or after office hours call (575) 627-0205. Engineer on call during office hours phone (575) 627-0237 or phone (after hours) call (575) 626-5871.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat Class "C"**, for up to 7,500 feet of depth or **Neat Class "H"**, for deeper than 7,500 feet plugs.

6. <u>Subsequent Plug back Reporting</u>: Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 31605 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed.</u>

7. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.