Form 3160-5 (June 2015)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

| FORM APPROVED             |
|---------------------------|
| OMB NO. 1004-0137         |
| Expires: January 31, 2018 |

| Expues. Ja       | anuai y | J |
|------------------|---------|---|
| Lease Serial No. |         |   |
| NIMI CO20721D    |         |   |

| SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an   |  |   |                    |   | 5. Lease Serial No.<br>NMLC028731B    |       |                 |  |
|--|--|---|--------------------|---|---------------------------------------|-------|-----------------|--|
| abandoned wel  |  | 6. If Indian, Allottee or Tribe Name                    |                    |   |                                       |       |                 |  |
| SUBMIT IN 1  | ,                                      | 7. If Unit or CA/Agreement, Name and/or No. NMNM111789X |                    |   |                                       |       |                 |  |
| 1. Type of Well Gas Well Oth   | ,                                      | 8. Well Name and No. DODD FEDERAL UNIT 23               |                    |   |                                       |       |                 |  |
| Name of Operator Contact: ABIGAIL ANDERSON COG OPERATING LLC E-Mail: abbym@bcmandassociates.com  |  |   |                    |   | 9. API Well No.<br>30-015-25790-00-S1 |       |                 |  |
| 3a. Address<br>600 W ILLINOIS AVENUE<br>MIDLAND, TX 79701  | 3b. Phone No.<br>Ph: 432-58            | (include area code)<br>0-7161                           |                    | 10. Field and Pool or Exploratory Area DODD-GLORIETA-UPPER YESO |                                       |       |                 |  |
| 4. Location of Well (Footage, Sec., T.   | , R., M., or Survey Description        | ) .   | •                  |   | 11. County or Parish, S               | State |                 |  |
| Sec 14 T17S R29E NWNW 12   | 25FNL 25FWL                            |   |                    |   | EDDY COUNTY                           | ′, NM |                 |  |
|  |  |   |                    |   |                                       |       |                 |  |
| 12. CHECK THE AF   | PROPRIATE BOX(ES)                      | TO INDICA   | TE NATURE OI       | F NOTICE, F   | REPORT, OR OTH                        | ŒR DA | TA              |  |
| TYPE OF SUBMISSION   |  |   | TYPE OF            | ACTION  |                                       | ,     |                 |  |
| Notice of Intent   | ☐ Acidize                              | Deep  | oen                | ☐ Production  | n (Start/Resume)                      | ■ Wat | ter Shut-Off    |  |
| _  | ☐ Alter Casing                         | ☐ Hyd:  | raulic Fracturing  | □ Reclamat  | ion .                                 | □ Wel | ll Integrity    |  |
| ☐ Subsequent Report  | □ Casing Repair                        | , 🔲 New   | Construction       | ☐ Recomple  | ete                                   | Oth   | er              |  |
| ☐ Final Abandonment Notice   | □ Change Plans                         | 🛛 Plug  | and Abandon        | ☐ Temporar  | emporarily Abandon                    |       |                 |  |
|  | ☐ Convert to Injection                 | . 🗖 Plug  | Back               | ☐ Water Di  | sposal                                |       |                 |  |
| Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.  1. Set 5 1/2" CIBP @ 4120'. Circ hole w/ MLF. Pressure test csg. Spot 25 sx cmt @ 4120-3920'. WOC & Tag 2. Spot 25 sx cmt @ 2000-2400'. (San Andres) S + C B R 2725. Spot 25 sx cmt @ 4120-3920'. WOC & Tag 3. Spot 25 sx cmt @ 1000-800'. WOC & Tag (B/Salt) Spot 25 sx S @ 925-725' 4. Spot 55 sx class C cmt @ 485'-Surface (T/Salt & Shoe) Spot 70 sx S @ 535 - Surface 5. Cut off well head, verify cmt to surface, weld on Below Ground Dry Hole Marker.  Carisbad Field Office  Accepted for record - NMOCD  APProved With Conditions. Pkase See Attached CoAs  DISTRICTMANTESIAOCD  |  |   |                    |   |                                       |       |                 |  |
| 14. I hereby certify that the foregoing is   |  |   |                    | ···   |                                       |       |                 |  |
| Comm   | For COG (<br>itted to AFMSS for proces | PERATING L  | .C, sent to the Ca | arisbad   |                                       |       |                 |  |
|  | ANDERSON                               | sing by DEBO  | Title AGENT        | •   | (10220 10 102)                        |       |                 |  |
| ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,  |  |   |                    |   |                                       |       |                 |  |
| Signature (Electronic S  | Submission)                            |   | Date 04/24/20      | 019   |                                       |       |                 |  |
|  | THIS SPACE FO                          | OR FEDERA   | L OR STATE         | OFFICE US   | E                                     |       |                 |  |
| Approved By JEROMY PORTER  |  |   | TitlePETROLE       | UM ENGINE   | ER                                    | D     | Date 05/03/2019 |  |
| Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conduct the conduction of th | uitable title to those rights in th    | s not warrant or<br>e subject lease                     | Office Carlsbac    | d   |                                       |       |                 |  |

(Instructions on page 2) \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



## Revisions to Operator-Submitted EC Data for Sundry Notice #462796

**Operator Submitted** 

ABD Sundry Type: NOI

Lease:

NMLC028731B

Agreement:

Operator:

COG OPERATING, LLC 600 W. ILLINOIS AVE MIDLAND, TX 79701 Ph: 432-683-7443

Admin Contact:

ABIGAIL ANDERSON

AGENT E-Mail: abbym@bcmandassociates.com

Ph: 432-580-7161

Tech Contact:

ABIGAIL ANDERSON

**AGENT** 

E-Mail: abbym@bcmandassociates.com

Ph: 432-580-7161

Location:

State:

NM EDDY CO

County:

Field/Pool:

DODD-GLORIETA-UPPER YESO

Well/Facility:

DODD FEDERAL UNIT 23WIW Sec 14 T17S R29E ODES 125FNL 25FWL 32.841564 N Lat, 104.053978 W Lon

**BLM Revised (AFMSS)** 

NOI

NMLC028731B

NMNM111789X (NMNM111789X)

COG OPERATING LLC 600 W ILLINOIS AVENUE MIDLAND, TX 79701 Ph: 432.685.4385

ABIGAIL ANDERSON

AGENT E-Mail: abbym@bcmandassociates.com

Ph: 432-580-7161

ABIGAIL ANDERSON AGENT

E-Mail: abbym@bcmandassociates.com

Ph: 432-580-7161

NM EDDY

DODD-GLORIETA-UPPER YESO

DODD FEDERAL UNIT 23 Sec 14 T17S R29E NWNW 125FNL 25FWL

## COG Operating, LLC

Lease & Well # Dodd Federal Unit #23 WIW 3001525790 Sec 14 T 17S R 29E, 125 FNL & 25 FWL UNIT D Spud date 9-13-87 EDDY CO., NM Completion date 12-1-87 - Elevation - 3619 GL 4. Spot 55 sx cmt @ 485' to Surface. (T/Salt & 8 5/8" Shoe) 8 5/8" 24# @ 333 w/250 sx. Circ 35 sxs. Topof Salt 485 3. Spot 25 sx cmt @ 1000-800'. WOC & Tag (B/Salt) 2. Spot 25 sx cmt @ 2600-2400'. (SA) Re-sqzd perfs w/250 sxs. (11-03-09) Spotzssxs Sqzd perfd @ 2,789-3405 w/2000 gals flo ck & 1500 sxs cmt. 2/5/2008 Perf'd @ 2789-3405' (Grbg-SA), A/ 4000 gals 15% Frac'd w/ 252K gals GBW, 50K # 20/40, 150K # 12/20 & 200K # 8/16 12-11-87 73Pof Gloricta-3991'
79P 20 BO, 38 MCF 12-2-87 Top of 1950-4055'
Set pkr @ 4081'. Converted to PDK WIW 2-8-08 1. Set 5 1/2" CIBP @ 4115'. Circ hole w/ MLF. Pressure test csg. Spot 25 sx cmt @ 4115-3915'. WOC & Tag Perfd 4166-4301', PDK, A/7000 gals HCL, 32,000 gals 20% 10/23/1987 7 7/8" hole

5 1/2" 17# csg @ 4477' w/2250 sx. Circ 210 sxs.

TD @ 4496'

PBTD - 4442'


## COG Operating, LLC

### Lease & Well #

#### Dodd Federal Unit #23 WIW

3001525790

Spud date 9-13-87 Completion date 12-1-87 Elevation - 3619 GL Sec 14 T 17S R 29E, 125 FNL & 25 FWL UNIT D EDDY CO., NM



12 1/4" hole

8 5/8" 24# @ 333 w/250 sx. Circ 35 sxs.

Re-sqzd perfs w/250 sxs. 11-03-09
Sqzd perfd @ 2,789-3405 w/2000 gals flo ck & 1500 sxs cmt. 2/5/2008
Perf'd @ 2789-3405' (Grbg-SA). A/ 4000 gals 15%
Frac'd w/ 252K gals GBW, 50K # 20/40, 150K # 12/20
& 200K # 8/16 12-11-87

IP P 20 BO, 38 MCF 12-2-87

Set pkr @ 4081'. Converted to PDK WIW 2-8-08

Perfd 4166-4301', PDK, A/7000 gais HCL, 32,000 gais 20% 10/23/1987

7 7/8" hole

5 1/2" 17# csg @ 4477' w/2250 sx. Circ 210 sxs. TD @ 4496'

PBTD - 4442'

32.8415642 -104.053978

## 30-015-25790-00-S1 COG OPERATING LLC Conditions of Approval

Due to being within the Lesser Prairie Chicken habitat, this workover activity will be restricted to the hours of 9:00am through 3:00am for the period of March 1 through June 15. Exceptions to these restrictions may be granted by BLM's Johnny Chopp <jchopp@blm.gov> 575.234.2227 or Bob Ballard <br/>
bballard@blm.gov> 575.234.5973.

Well is within Medium/High/Critical Cave/Karst. A cement plug is required from 400 feet (a minimum of 50 feet below cave depth) to surface.

Operator to have H2S monitoring equipment on location as H2S has been reported in the area.

#### Plugging Procedure:

- 1. Plug 1 Spot 25 sxs Class C neat at 4,115' on top of CIBP at 4,115'. Top of Glorieta 3991'. WOC and tag at 3915' or shallower.
- 2. Plug 2 Spot 25 sxs Class C neat at 2,725' on top of CIBP at 2,725'. WOC and tag plug at 2,525' or shallower. Top Perforation 2,789'.
- 3. Plug 3 Spot 25 sxs Class C neat at 925'. WOC tag plug at 725' or shallower. Top of Yates at 875'.
- 4. Plug 4 Spot 70 sxs Class C neat at 535'. Top of Salt at 485'.

JJP05032019

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. **Before** pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on

depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:</u>
From March 1<sup>st</sup> through June 15<sup>th</sup> annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted

# Requirements for ground level dry hole markers <u>Well Identification Markers</u> Conditions of Approval (COA)

The BLM Carlsbad Field Office (CFO) Conditions of Approval (COA) Require that ground level dry hole markers be placed on wells within the Lesser Prairie Chicken habitat area. The dry hole markers will be to the following specifications. The operator will construct the markers as follows:

- 1. An 8 inch X 8 inch steel plate 1/8 to 3/16 of an inch thick is to be placed on the dry hole marker stand pipe 2 inches from ground level, in the Lesser Prairie Chicken habitat area.
- 2. Steel plate may be welded or bolted approximately 2 inches from ground level on the stand pipes. If plates are bolted to the stand pipe, the person installing the plate will be required to weld a pipe collar on the plate and place a minimum of two set screws/bolts on each collar. Aluminum data plates may be bolted with minimum ¼ inch bolts and locking nuts or self tapping fine threaded screws. A minimum of one in each corner is to be installed on each plate.
- 3. An 8 inch x 8 inch aluminum plate, which is 12 gauge or .080 sign material (1/8 inch aluminum plate may be used in place of the .080 plate) with the required information for that well stamped or engraved in a minimum 3/8 inch tall letter or number.
- 4. The following information will be stamped or engraved on the 8 inch X 8 inch aluminum plate in the following order.
  - a. First row: Operator's name
  - b. Second row: Well name and number
  - c. Third row: Legal location to include ¼ ¼, Section, Township, and range. If the legal location cannot be placed on one row it can be split into two rows with the ¼ ¼ (example: 1980 FNL 1980 FWL) being on the top row.
  - d. Fourth row: Lease Number and API number.
    - i. Example marker plate: (attached)

NMOCD Order No. R-12965 also required the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a ground level dry hole marker was installed as required in the COAs from the BLM.