3160-5 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR

OCD Artesia

FURM APPROVED
OMB NO. 1004-0137
Expires: January 31, 201
Expires. Juliumy 51, 201

SUNDRY NOTICES AND REPORTS ON WELLS ARTESIA DISTRICT Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals CT 0 2 2019	15) Sease Serial No. NMNM94651 6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on page 2 RECEIVED	7. If Unit or CA/Agreement, Name

SUBMIT IN TRIPLICATE - Other instructions on page 2 RECEIVED		7. If Unit or CA/Agreement, Name and/or No.		
Type of Well ☐ Gas Well ☐ Other: INJECTION		8. Well Name and No. CEDAR CANYON 28 FEDERAL 4		
Name of Operator Contact: DAVID STEWART OXY USA INCORPORATED E-Mail: david_stewart@oxy.com		9. API Well No. 30-015-29118-00-S1		
3a. Address 5 GREENWAY PLAZA SUITE 110 HOUSTON, TX 77046-0521	3b. Phone No. (include area code) Ph: 432.685.5717	10. Field and Pool or Exploratory Area CEDAR CANYON		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description	n) ·	11. County or Parish, State		
Sec 28 T24S R29E NESW 1980FSL 1980FWL		EDDY COUNTY, NM		
12 CHECK THE APPROPRIATE ROY(ES) TO INDICATE NATURE OF NOTICE REPORT OR OTHER DATA				

TYPE OF SUBMISSION	TYPE OF ACTION			
□ Notice of Intent Subsequent Report	☐ Acidize ☐ Alter Casing ☐ Casing Repair	☐ Deepen ☐ Hydraulic Fracturing ☐ New Construction	☐ Production (Start/Resume) ☐ Reclamation ☐ Recomplete	☐ Water Shut-Off ☐ Well Integrity ☐ Other
☐ Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection	☑ Plug and Abandon ☐ Plug Back	☐ Temporarily Abandon ☐ Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

9/19/19 - Dig out cellar, MIRU PU. Csg-0# - Tbg-400#, M&P 10# BW, pressure still @ 400#. RIH w/ blk plug & set in pkr @ 3042', test plug to 1500#, tested good. NDWH, NU BOP. Get off on/off tool & start to POOH w/ tbg.

RECLAMATION PROCEDURI ATTACHED

9/20/19 - Continue to POOH w/ tbg. RIH w/ gauge ring & tag up @ 414', POOH & had scale & paraffin. RIH w/ tbg to 3000', circ well w/ 10# MLF, POOH. RIH w/ gauge ring to 3025', POOH. RIH & set CIBP @ 3020', POOH. RIH w/ tbg & tag CIBP @ 3015', notified BLM. M&P 30sx CL C cmt, calc TOC-2544'. PUH to 1733', M&P 25sx CL C cmt, PUH, WOC.


RECLAMATION DUE 3-24-20

9/23/19 - RIH & tag.cmt @ 1354', notified BLM. POOH, RIH & perf @ 555', POOH. RIH & set pkr, EIR w/ full circ out 4-1/2" X 7-5/8" annulus, POOH. ND BOP, NU flange, M&P 135sx Cl C cmt followed by 105sx CL C cmt, circ cmt to surf, displace to 450', WOC.

GC 10/10/19

vections on treate a total AutoCD						
14. I hereby certify the	hat the foregoing is true and correct. Electronic Submission #485423 verifie For OXY USA INCORPORA Committed to AFMSS for processing by DEBO	ILD. S	sent to the Carisbau		FOR RECO	ORD
Name (Printed/Typ	ped) DAVID STEWART	Title	REGULATORY ADVIS	SOR CED	0.7.0040	1
Signature	(Electronic Submission)	Date	09/26/2019	omerina	2 7 2019	
THIS SPACE FOR FEDERAL OR STATE OFFICE		STATE OFFICE USE	DUDENII OF LANDAMANA			
Approved By	,	Title			Date	
certify that the applican	, if any, are attached. Approval of this notice does not warrant or at holds legal or equitable title to those rights in the subject lease	Office	P			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



^{**} BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **



ூAdditional data for EC transaction #485423 that would not fit on the form

32. Additional remarks, continued

9/24/19 RIH & tag cmt @ 405', notified BLM. M&P 60sx CL C cmt, POOH, cmt to surf, notified BLM,



BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm

IN MENICA

In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909 (Office), 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crisha Morgan Environmental Protection Specialist 575-234-5987

Melissa Horn Environmental Protection Specialist 575-234-5951

Kelsey Wade Environmental Protection Specialist 575-234-2220

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612