Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NM OIL CONSERVATION

4009 Artestact

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018


	OOD / II toola				
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter a	OCT	17	2019		
Do not use this form for proposals to drill or to re-enter a	in T	_			

. Lease Serial No. NMNM20965

Do not use th	is form for proposals to	drill or to re-	enter an	8 2013		
abandoned well. Use form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name		
SUBMIT IN-	TRIPLICATE - Other ins	tructions on	page 2		7. If Unit or CA/Agree	ement, Name and/or No.
1. Type of Well Soil Well Gas Well Oth	her				8. Well Name and No. RDX FEDERAL 1	7 015
Name of Operator WPX ENERGY PERMIAN, LL	Contact: C E-Mail: caitlin.ohai	CAITLIN O'H ir@wpxenergy.o	AIR		9. API Well No. 30-015-39943	,
3a. Address 3500 ONE WILLIAMS CENTE TULSA, OK 74103	ER MD 35	3b. Phone No Ph: 539-57	(include area code) 3-3527	- 	10. Field and Pool or I BRUSHY DRAV	Exploratory Area W; DELAWARE, E
4. Location of Well (Footage, Sec., T	C., R., M., or Survey Description	1)			11. County or Parish,	State
Sec 17 T26S R30E 990FSL 2 32.037956 N Lat, 103.902381					EDDY COUNTY	′, NM
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	IER DATA
TYPE OF SUBMISSION			TYPE O	ACTION		
☑ Notice of Intent	☐ Acidize	Dee:	pen	☐ Product	tion (Start/Resume)	☐ Water Shut-Off
_	☐ Alter Casing	☐ Hyd	raulic Fracturing	☐ Reclam	ation	■ Well Integrity
☐ Subsequent Report	☐ Casing Repair	□ New	Construction	☐ Recom	plete	☐ Other
☐ Final Abandonment Notice	☐ Change Plans	🔀 Plug	and Abandon	☐ Tempor	orarily Abandon	
13. Describe Proposed or Completed Op	☐ Convert to Injection	☐ Plug		■ Water I	•	
determined that the site is ready for f WPX ENERGY PERMIAN, LL Please see the below for the p Procedure: 1. Set 5 1/2" CIBP @ 5,435'. (5,235'. 2. Spot 25 sx cmt @ 5,051 - 4 3. Spot 25 sx cmt @ 3,509 - 3 4. Perf & Sqz 35 sx cmt @ 1,4 5. Perf & Sqz 35 sx cmt @ 1,6 6. Perf & Sqz 35 sx cmt @ 15	C respectfully requests to procedure, and the attach Circulate hole w/ MLF. Procedure with the control of the c	ed for the curessure test cs	g. Spot 25 sx cn	ed WBDs. nt @ 5,435	-	S OF APPROVA
14. I hereby certify that the foregoing is	Electronic Submission #	RGY PERMIAN	l, LLC, sent to th	e Carlsbad	_	
Name (Printed/Typed) CAITLIN (O'HAIR		Title REGUL	ATORY TE	CH III	
Signature (Electronic S	Submission)		Date 09/11/2	019		
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE U	SE	
Approved By Lames Co	? Comes		Title SA	(T		10-10-19 Date
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to condu	uitable title to those rights in the		Office CFC	7		
litle 18 0.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a statements or representations as	crime for any pe to any matter w	rson knowingly and ithin its jurisdiction.	willfully to m	ake to any department or	agency of the United


X

CURRENT WELLBORE DIAGRAM



WPX Ene	rgy		
Author:	BCM & Associates, INC		
Weli Name	RDX Federal 17	Well No.	#15
Field	Brushy Draw/Delaware E	API#:	30-015-39943
County	Eddy	Location:	Sec 17, T26S, R30E
State	New Mexico	_	990' FSL 2310' FEL
Spud Date	3/29/2012	Formation:	Delaware
GL	3113·	_	

Description	O.D.	Grade	Weight	Depth	Hole	Cmt Sx	TOC
Surface Csg	13 3/8"	J55	54.5#	1,060	17 1/2"	800	0
Inter Csg	9 5/8"	J55	40#	3,459	12 1/4"	970	0
Prod Csg	5 1/2"	N80	17#	7,408	7 7/8"	800	3.165





United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- 1. The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909 (Office), 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crisha Morgan Environmental Protection Specialist 575-234-5987

Melissa Horn Environmental Protection Specialist 575-234-5951

Kelsey Wade Environmental Protection Specialist 575-234-2220

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612