SUNDR'	UNITED STATE: DEPARTMENT OF THE I BUREAU OF LAND MANA NOTICES AND REPO his form for proposals to rell. Use form 3160-3 (AP	NTERIOR OCD Artes GEMENT RTS ON WELLS drill or to resenter an	5	OMB :	A APPROVED NO. 1004-0137 January 31, 2018 or Tribe Name	
SUBMIT IN	7	7. If Unit or CA/Agreement, Name and/or No.				
1. Type of Well	8	8. Well Name and No. RDX FEDERAL 17 21				
2. Name of Operator Contact: CAITLIN O'HAIR WPX ENERGY PERMIAN LLC E-Mail: caitlin.ohair@wpxenergy.com				9. API Well No. 30-015-41088-00-S1		
3a. Address 3500 ONE WILLIAMS CENT TULSA, OK 74172		3b. Phone No. (include area code) Ph: 539-573-3527	1	10. Field and Pool or Exploratory Area BRUSHY DRAW-WOLFCAMP		
4. Location of Well (Footage, Sec., Sec 17 T26S R30E NESE 2	1	11. County or Parish, State EDDY COUNTY, NM				
12. CHECK THE A	APPROPRIATE BOX(ES)	TO INDICATE NATURE O	F NOTICE, RI	EPORT, OR OT	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
☐ Notice of Intent	☐ Acidize	☐ Deepen		(Start/Resume)	☐ Water Shut-Off	
Subsequent Report	☐ Alter Casing ☐ Casing Repair	☐ Hydraulic Fracturing☐ New Construction	☐ Reclamation		☐ Well Integrity ☐ Other	
☐ Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection	☑ Plug and Abandon ☐ Plug Back	☐ Temporari	ly Abandon	_ o.mei	
following completion of the involve testing has been completed. Final Adetermined that the site is ready for 10/02/19 MIRU Plugging equeblar. Worked rods free. 10/03/19 POH w/ 198 rods. N 10 weight bars, & pump. 10/04/19•Could not set 5.1/2/	peration: Clearly state all pertiner nally or recomplete horizontally, ork will be performed or provide doperations. If the operation restaudonment Notices must be file final inspection. Sippment. RU pump. Pump'd ND well head, NU BOP. PC	nt details, including estimated starting give subsurface locations and measur the Bond No. on file with BLM/BIA sults in a multiple completion or record only after all requirements, including 40 bbls H20, tbg did not presult by W/ 222 jts of tbg, 5 1/2" tbg	red and true vertice. Required subsection in a new mg reclamation, he sure test. Duganchor, 3 rods	osed work and approact the second sec	inent markers and zones. e filed within 30 days 60-4 must be filed once and the operator has AMATION PROCEDURE ATTACHED	
5140'. Spotted 25 sx class C 10/08/19 Tagged plug @ 32	cmt @ 3490-3237', WOC.	C cmt @ 5442-5189' WOC.] ueezed 140 sx class C cmt @ ged plug @ 830'. Perfd csg @ ated to surface on the 5 1/2" 8	42001 8 diame		CLAMATION F <u>4-8-'20'</u> Conservation	

SIW @ 500 PSI.

10/09/19 Verified cmt to surface. Rigged down & moved off. Moved in backhoe and welder, dug out

Accepted for record - NMOCD

ARYESIA DISTRICT

OCT 3.1 2019

14. I hereby certify that t	he foregoing is true and correct. Electronic Submission #488326 verific For WPX ENERGY PERMA	BI 1 I C		-	, u n	ECEIVED		;		
Name (Printed/Typed)	Committed to AFMSS for processing by DEBC	Title	REGULATORY TE	CHICA	CEPTED	OR RECO)RD			
Signature	(Electronic Submission)	Date	10/16/2019		0CT 1	6 20 19				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE										
Approved By		Title		Bl	UREAU OF LAND-MANAGEMENT Carlsbad field obfice					
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office	,				- Comment			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



⁽Instructions on page 2) ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

Additional data for EC transaction #488326 that would not fit on the form

32. Additional remarks, continued

cellar, cut off well head, & Bobby Firndt w/ BLM verified cement to surface. Welded on "Above Ground Dry Hole Marker". Backfilled cellar, cut off deadmen, cleaned location, and moved off.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
 Operations must include adequate measures for stabilization and reclamation of disturbed lands.
 Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
 process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909 (Office), 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crisha Morgan Environmental Protection Specialist 575-234-5987

Melissa Horn Environmental Protection Specialist 575-234-5951

Kelsey Wade Environmental Protection Specialist 575-234-2220

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612