UNITED STATES

FORM APPROVED

) DI		OMB NO. 1004-0137 Expires: January 31, 2018					
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					5. Lease Serial No. NMNM1005496. If Indian, Allottee or Tribe Name		
			7. If Unit or CA/Agreement, Name and/or No.				
SUBMIT IN	TRIPLICATE - Other ins	tructions on	page 2	•	/. If Unit or CA/Agr	reement, Name and/or No.	
Type of Well Oil Well					8. Well Name and No MultipleSee At		
Name of Operator CHEVRON USA INCORPOR	ERRA .COM		9. API Well No. MultipleSee	Attached			
3a. Address 6301 DEAUVILLE BLVD MIDLAND, TX 79706 3b. Phone No Ph: 432-68			(include area code) 7-7655 10. Field and Pool or Exploratory Area POKER LAKE-DELAWARE, EAST PURPLE SAGE-WOLFCAMP (GAS			-DÉLAWÅRE, EAST	
4. Location of Well (Footage, Sec., 7	<u> </u>		11. County or Parish	ı, State			
MultipleSee Attached	EDDY COUNTY			ΓY, NM			
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OT	THER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent	☐ Acidize	☐ Dee	pen	☐ Producti	on (Start/Resume)	☐ Water Shut-Off	
_	☐ Alter Casing	ing Hydraulic Fracturing Re		☐ Reclama	ition	■ Well Integrity	
☐ Subsequent Report	□ Casing Repair	□ New	Construction	on Recomplete		⊠ Other	
☐ Final Abandonment Notice	☐ Change Plans ☐ Plu		g and Abandon		arily Abandon	Onshore Order Varian ce	
	Convert to Injection	☐ Plug	Back	□ Water D	isposal		
13. Describe Proposed or Completed Op If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final Aldetermined that the site is ready for form	ally or recomplete horizontally, rk will be performed or provide I operations. If the operation re bandonment Notices must be fil inal inspection.	give subsurface the Bond No. or sults in a multipl led only after all	locations and measu of file with BLM/BIA e completion or reco requirements, includ	red and true ve Required sub- impletion in a n ing reclamation	rtical depths of all pert sequent reports must b ew interval, a Form 31 , have been completed	inent markers and zones. be filed within 30 days 60.4 must be filed once	
Chevron respectfully requests shall be performed: when initi broken."	where it states "A bject to test pres	A full BOP To ssure is	est	MEVEVED			
We propose to break test if at full BOP test. A break test will only be performed on operation Summary of changes is attact	not be performed on our ons where BLM document	last production	n section A bres	ak toet will	ad ri <i>d</i> h	NOV 0 5 2019	
This request applies to the fol			CD Artes	THE REPORT OF THE PROPERTY OF			
HH SO 8 5 FED 004 1H - 30-	,				- I Faile:		
TH SO 6 5 FED 004 TH - 30-1	See	ATI	ACHE)		ans.		
14. I hereby certify that the foregoing is	Electronic Submission #	489039 verifie	d by the BLM Wel	I Information	System		
Con	For CHEVRON L nmitted to AFMSS for proc		RATED, sent to t SCILLA PEREZ or		(20PP0198SE)		
Name (Printed/Typed) LAURA B				ATORY SPE	•		
Signature (Electronic	Submission)		Date 10/22/20	019			
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE US	BE		
_Approved_By_NDUNGU_KAMAU_			TitlePETROLE	UM ENGINE	ER	Date 11/04/2019	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease				•			
which would entitle the applicant to conduct operations thereon.			Office Carlsbad				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2) ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

Additional data for EC transaction #489039 that would not fit on the form

Wells/Facilities, continued

Agreement NMNM100549	Lease NMNM100549	Well/Fac Name, Number HH SO 8 5 FED 004 1H	API Number 30-015-45987-00-X1
NMNM100549	NMNM100549	HH SO 8 5 FED 004 2H	30-015-45988-00-X1
NMNM100549	NMNM100549	HH SO 8 5 FED 004 3H	30-015-45989-00-X1
NMNM100549	NMNM100549	HH SO 8 5 FED 004 4H	30-015-45990-00-X1
NMNM100549	NMNM100549	HH SO 8 5 FED 004 5H	30-015-45991-00-X1
NMNM100549	NMNM100549	HH SO 8 5 FED 004 6H	30-015-45992-00-X1

3.54

Location
Sec 17 T26S R27E NWNE 783FNL 1584FEL 32.047600 N Lat, 104.208832 W Lon Sec 17 T26S R27E NWNE 783FNL 1559FEL 32.047600 N Lat, 104.208755 W Lon Sec 17 T26S R27E NWNE 783FNL 1534FEL 32.047600 N Lat, 104.208672 W Lon Sec 17 T26S R27E NWNE 783FNL 1509FEL 32.047596 N Lat, 104.208588 W Lon Sec 17 T26S R27E NWNE 783FNL 1484FEL 32.047596 N Lat, 104.208511 W Lon Sec 17 T26S R27E NWNE 783FNL 1459FEL 32.047596 N Lat, 104.208427 W Lon Sec 17 T26S R27E NWNE 783FNL 1459FEL 32.047596 N Lat, 104.208427 W Lon

32. Additional remarks, continued

HH SO 8 5 FED 004 2H - 30-015-45988 HH SO 8 5 FED 004 3H - 30-015-45989 HH SO 8 5 FED 004 4H - 30-015-45990 HH SO 8 5 FED 004 5H - 30-015-45991 HH SO 8 5 FED 004 6H - 30-015-45992

Revisions to Operator-Submitted EC Data for Sundry Notice #489039

Operator Submitted

BLM Revised (AFMSS)

Sundry Type:

VARI NOI

NMNM118108

NMNM100549

VARI

NOI

Agreement:

Lease:

Operator:

CHEVRON USA INC 6301 DEAUVILLE BLVD MIDLAND, TX 79706 Ph: 432-687-7665

Admin Contact:

LAURA BECERRA

REGULATORY SPECIALIST E-Mail: LBECERRA@CHEVRON.COM

Ph: 432-687-7665

Tech Contact:

LAURA BECERRA

REGULATORY SPECIALIST E-Mail: LBECERRA@CHEVRON.COM

Ph: 432-687-7665

NM **EDDY**

Location: State:

County:

Field/Pool:

PURPLE SAGE; WOLFCAMP (GAS

Well/Facility:

HH SO 8 5 FED 004 1H

Sec 17 T26S R27E Mer NMP NWNE 783FNL 1584FEL

CHEVRON USA INCORPORATED

6301 DEAUVILLE BLVD MIDLAND, TX 79706 Ph: 432 687 7100

LAURA BECERRA REGULATORY SPECIALIST E-Mail: LBECERRA@CHEVRON.COM

Ph: 432-687-7655

LAURA BECERRA REGULATORY SPECIALIST E-Mail: LBECERRA@CHEVRON.COM

Ph: 432-687-7655

NM EDDY

POKER LAKE-DELAWARE, EAST PURPLE SAGE-WOLFCAMP (GAS)

HH SO 8 5 FED 004 1H

Sec 17 T26S R27E NWNE 783FNL 1584FEL

32.047600 N Lat, 104.208832 W Lon

32.047600 N Lat, 104.208832 W Lon HH SO 8 5 FED 004 2H Sec 17 T26S R27E NWNE 783FNL 1559FEL 32.047600 N Lat, 104.208755 W Lon HH SO 8 5 FED 004 3H Sec 17 T26S R27E NWNE 783FNL 1534FEL 32.047600 N Lat, 104.208672 W Lon HH SO 8 5 FED 004 4H Sec 17 T26S R27E NWNE 783FNL 1509FEL 32.047596 N Lat, 104.208588 W Lon HH SO 8 5 FED 004 5H Sec 17 T26S R27E NWNE 783FNL 1484FEL 32.047596 N Lat, 104.208511 W Lon HH SO 8 5 FED 004 6H Sec 17 T26S R27E NWNE 783FNL 1459FEL 32.047596 N Lat, 104.208511 W Lon HH SO 8 5 FED 004 6H Sec 17 T26S R27E NWNE 783FNL 1459FEL 32.047596 N Lat, 104.208427 W Lon 32.047596 N Lat, 104.208427 W Lon

PECOS DISTRICT DRILLING CONDITIONS OF APPROVAL

OPERATOR'S NAME: CHEVRON USA INCORPORATED

LEASE NO.: | NMNM118108

LOCATION: Section 17, T.26 S., R.27 E., NMPM

COUNTY: Eddy County, New Mexico

WELL NAME & NO.: HH SO 8 5 FED 004 1H

SURFACE HOLE FOOTAGE: 783'/N & 1584'/E **BOTTOM HOLE FOOTAGE** 280'/N & 1590'/E

WELL NAME & NO.: | HH SO 8 5 FED 004 2H

SURFACE HOLE FOOTAGE: 783'/N & 1559'/E **BOTTOM HOLE FOOTAGE** 280'/N & 1254'/E

WELL NAME & NO.: HH SO 8 5 FED 004 3H

SURFACE HOLE FOOTAGE: 783'/N & 1534'/E **BOTTOM HOLE FOOTAGE** 280'/N & 1170'/E

WELL NAME & NO.: HH SO 8 5 FED 004 4H

SURFACE HOLE FOOTAGE: 783'/N & 1509'/E **BOTTOM HOLE FOOTAGE** 280'/N & 750'/E

WELL NAME & NO.: HH SO 8 5 FED 004 5H

SURFACE HOLE FOOTAGE: 783'/N & 1484'/E **BOTTOM HOLE FOOTAGE** 280'/N & 30'/E

WELL NAME & NO.: HH SO 8 5 FED 004 6H

SURFACE HOLE FOOTAGE: 783'/N & 1459'/E **BOTTOM HOLE FOOTAGE** 280'/N & 330'/E

COA

ALL PREVIOUS COAs STILL APPLY

A. SPECIAL REQUIREMENT (S)

BOP Break Testing Variance

- While in transfer between wells, the BOPE shall be secured by the hydraulic carrier or cradle.
- Any well control event while drilling require notification to the BLM Petroleum Engineer prior to the commencement of any BOP Break Testing operations.
- A full BOP test is required prior to drilling the first deep intermediate hole section. If any subsequent hole interval is deeper than the first, a full BOP test will be required.

NMK1142019

Additional data for EC transaction #489039 that would not fit on the form

32. Additional remarks, continued

HH SO 8 5 FED 004 2H - 30-015-45988 HH SO 8 5 FED 004 3H - 30-015-45989 HH SO 8 5 FED 004 4H - 30-015-45990 HH SO 8 5 FED 004 5H - 30-015-45991 HH SO 8 5 FED 004 6H - 30-015-45992

Delaware Basin Changes to APD/COA for Federal Well



Well Names:

Well Name		API#
HH SO 8 5 FED 004	1H	30-015-45987
HH SO 8 5 FED 004	2H	30-015-45988
HH SO 8 5 FED 004	3H	30-015-45989
HH SO 8 5 FED 004	4H	30-015-45990
HH SO 8 5 FED 004	5H	30-015-45991
HH SO 8 5 FED 004	6H	30-015-45992

Rig: Patterson 815

CVX CONTACT:

John Lasley

MCBU D&C Engineer – Patterson 815 Chevron North America Exploration and Production Co.

MidContinent Business Unit

Office: (713) 372-3866 Cell: (832) 544-7023

Email: JLasley@Chevron.com

Summary of Changes to APD Submission

Chevron respectfully requests to vary from the Onshore Order 2 where it states "(A full BOP Test) shall be performed: when initially installed and whenever any seal subject to test pressure is broken." We propose to break test if able to finish the next hole section within 21 days of the previous full BOP test. Upon the first nipple up of the pad a full BOP test will be performed. A break test will consist of a 250 psi low $/ \ge 5,000$ psi high 10 min ea test against the connection that was broken when skidding the rig. A break test will not be performed on our last production section. A break test will only be performed on operations where BLM documentation states a 5M or less BOP can be utilized.

See drilling sequence below that indicates the potential hole sections break testing can be performed given they meet the above criteria.

