Submit One Copy To Appropria	State of New Mexico	Form C-103
Office <u>District I</u> 1625 N. French Dr., Hobbs, NM 8824AN 2 7 2U2U District II	gy, Minerals and Natural Re	sources Revised November 3, 2011 WELL API NO.
BILS. First St., Artesia EMSRD-OCD AR	CONSERVATION DIVI	SION 30-015-22079 5. Indicate Type of Lease
1000 RIO Brazos Rd., Aztec, NM 8/410	Santa Fe, NM 87505	STATE FEE
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa PC, 1111 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DR DIFFERENT RESERVOIR. USE "APPLICATION FOR	ILL OR TO DEEPEN OR PLUG BAC PERMIT" (FORM C-101) FOR SUCH	K TO A OLD INDIAN DRAW UNIT
PROPOSALS.) 1. Type of Well: Oil Well Gas Well		8. Well Number
2. Name of Operator		9. OGRID Number
CHEVRON USA, INC.		241333
3. Address of Operator6301 Deauville Blvd., Midland, TX 79706	,	10. Pool name or Wildcat INDIAN DRAW DELAWARE
4. Well Location:		
Unit Letter_K_: 1657_feet from the <u>SOUTH</u> line and <u>1750</u> feet from the <u>WEST</u> line		
Section <u>7</u> Township <u>22-S</u> Range <u>28-E</u> NMPM County EDDY 11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
TEMPORARILY ABANDON CHANGE	—	MENCE DRILLING OPNS. P AND A
		_
OTHER: All pits have been remediated in compliance	ce with OCD rules and the term	ocation is ready for OCD inspection after P&A
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.		
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR		
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment \mathbf{q}		
other production equipment. Burged Rower Lines Not Removed W. S. de + 5.5. de Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed		
from lease and well location. ρ	ermit and closure plan. All flow	w lines, production equipment and junk have been removed
from lease and well location. Buried Plastic Liner Not Removed. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have		
to be removed.)	en addressed as ner OCD rules	Trach
\square Pipelines and flow lines have been abandon	ned in accordance with 19.15.35	10 NMAC. All fluids have been removed from non-
retrieved flow lines and pipelines.	wall on langer all electrical com	vice poles and lines have been removed from lease and wel
location, except for utility's distribution infrastr		The poles and thes have been removed from lease and we
		· .
When all work has been completed, return this	form to the appropriate District	office to schedule an inspection.
SIGNATURE Katherine Papageo	rgeTITLEDecom	nmissioning Project ManagerDATE1.24.2020
TYPE OR PRINT NAMEKatherine Papageo	•	ageorge@chevron.comPHONE:832-854-5291
APPROVED BY:	}	GC C
APPROVED BY:	TITLE	DENIED DATE 2/3/20

١