Form 3160-5 (September 2001)

UNITED STATES N.M. DIV-Dist. 2 OMB N DEPARTMENT OF THE INTERIOR 1301 W. Grand Avenue Expires: J Artesia, NM 882 O Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED OMB No. 1004-0135 Expires: January 31, 2004

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

6. If Indian, Allottee or Tribe Name

Title

Date

1. Type of Well	SUBMIT IN TRIPLICATE - Other instructions on reverse side				7. If Unit or CA	/Agreement, Name and/or No.	
2. Name of Operator EXCO Resources, Inc.  3 Address  201Terri Street Eastland, Texas 76448  4. Location of Well (Footage, Sec., T, R, M, or Survey Description)  C-1980' FSL & 1980' FEL; See 19, T-5-S, R-25-E  12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA  TYPE OF SUBMISSION  TYPE OF ACTION    Acidize	1 Type of Well		(-0	0.212-			
2. Name of Operator EXCO Resources, Inc.  3 Address  201Terri Street Eastland, Texas 76448  4. Location of Well (Footage, Sec., T, R, M, or Survey Description)  C-1980' FSL & 1980' FEL; See 19, T-5-S, R-25-E  12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA  TYPE OF SUBMISSION  TYPE OF ACTION    Acidize			1819202122233		8. Well Name and No.		
EXCO Resources, Inc.  3a. Address  3b. PhoceNo. (Include and Pool, or Exploratory Area 201Terri Street Eastland, Texas 76448  4. Location of Well (Footage, Sec., T. R., M., or Survey Description) C-1980' FSL & 1980' FEL; Sec 19, T-5-S, R-25-E  12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA  TYPE OF SUBMISSION  TYPE OF SUBMISSION  Acidize Acidize Box Subsequent Report Alter Casing Brian Brian Abandonment Notice  Casing Repair Brian Abandonment Notice  Despon Brian Abandonment Notice  Despon Brian Abandonment Notice  Convert to Injection Brian Abandonment Notice  Despon Brian Abandonment Notice Brian Abandonment Notice  Despon Brian Abandonment Notice Brian Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection. If the operation results in a multiple completion or recomplete for all pertinent markers and zones. Attach the Bond under Which the work will be performed or provide the Bond No. on file with BLA/MBIA. Required subsequent reports shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.  Please see the attached map of the gathering flow lines of the Rose Federal #4, Rose Federal #6 located @ C-1980' FSL & 1980' FWL;  ACCEPTED FOR RECOLD  JUL 2 2 2003  Description Texture Texture Texture Texture Texture Texture Texture Textu			(a) 4 ×3				
201Terri Street Eastland, Texas 76448  4. Location of Well (Footage, Sec. T. R. M. or Survey Description) C-1980 FSL & 1980 FEL; Sec 19, T-5-S, R-25-E  12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA  TYPE OF SUBMISSION  TYPE OF ACTION    Acidize	-		(4) (b) (b)				
201Terri Street Eastland, Texas 76448  4. Location of Well (Footage, Sec. T. R. M. or Survey Description) C-1980 FSL & 1980 FEL; Sec 19, T-5-S, R-25-E  12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA  TYPE OF SUBMISSION  TYPE OF ACTION    Acidize	3a. Address		3b. Phone No. (include area (2019)		30-005-61928		
4. Location of Well (Footage, Sec. T. R., M., or Survey Description) C-1980 FSL & 1980 FEL; Sec 19, T-5-S, R-25-E  12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA  TYPE OF SUBMISSION  TYPE OF SUBMISSION  TYPE OF SUBMISSION  TYPE OF SUBMISSION  TYPE OF ACTION  Alter Casing Fracture Treat Recomplete Casing Repair New Construction Production (Start/Resume) Change Plans Plug and Abandon Temporarily Abandon gathering Line Final Abandonment Notice  3. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof fif the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed one testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  Please see the attached map of the gathering flow lines of the Rose Federal #3, Rose Federal #4, Rose Federal #6 located @ C-1980 FSL & 1980 FWL; Sec. 19, T-5-S, R-25-E.	201Terri Street, Fastland Texas 76448		254 629 399	Elve 25	10. Field and Po	ool, or Exploratory Area	
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA  TYPE OF SUBMISSION  TYPE OF ACTION    Acidize			702	PICO NO		<u> </u>	
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA  TYPE OF SUBMISSION  TYPE OF ACTION    Acidize	C-1980' FSL & 1980' FEL; Sec 19, T-5-S, R-25-E		\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	\\\ \(\varphi\)	11. County or P	arish, State	
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA  TYPE OF SUBMISSION  TYPE OF ACTION    Acidize			\Z60	So /			
TYPE OF SUBMISSION  TYPE OF ACTION    Acidize				11821			
Notice of Intent	12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA						
Notice of Intent    Alter Casing	TYPE OF SUBMISSION		TYP	E OF ACTION			
Subsequent Report    Casing Repair   New Construction   Recomplete   Other location & size of gathering Line		Acidize	Deepen	Production (Start	/Resume)	Water Shut-Off	
Change Plans   Plug and Abandon   Temporarily Abandon   gathering Line	Notice of Intent	Alter Casing	Fracture Treat	Reclamation		Well Integrity	
Change Plans Convert to Injection Plug Back Water Disposal  3. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleted. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  Please see the attached map of the gathering flow lines of the Rose Federal #3, Rose Federal #4, Rose Federal #7 and the Rose Federal #6 that goes into the sales meter #21320 located @ 1870' FSL & 2078' FWL, Sec. 19; T-5-S, R-25-E next to the Rose Federal #6 located @ C-1980' FSL & 1980' FWL; Sec. 19, T-5-S, R-25-E.	Subsequent Benert	Casing Repair	New Construction	Recomplete	abla	Other location & size of	
3. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLMBIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  Please see the attached map of the gathering flow lines of the Rose Federal #3, Rose Federal #4, Rose Federal #7 and the Rose Federal #6 that goes into the sales meter #21320 located @ 1870' FSL & 2078' FWL, Sec. 19; T-5-S, R-25-E next to the Rose Federal #6 located @ C-1980' FSL & 1980' FWL; Sec. 19, T-5-S, R-25-E.	Subsequent Report	Change Plans	Plug and Abandon	Temporarily Aba	ındon	gathering Line	
If the proposal is to deepen directionally or recomplete horizontally, give substriace locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  Please see the attached map of the gathering flow lines of the Rose Federal #3, Rose Federal #4, Rose Federal #7 and the Rose Federal #6 that goes into the sales meter #21320 located @ 1870' FSL & 2078' FWL, Sec. 19; T-5-S, R-25-E next to the Rose Federal #6 located @ C-1980' FSL & 1980' FWL; Sec. 19, T-5-S, R-25-E.	Final Abandonment Notice	=	Plug Back	Water Disposal			
the sales meter #21320 located @ 1870' FSL & 2078' FWL, Sec. 19; T-5-S, R-25-E next to the Rose Federal #6 located @ C-1980' FSL & 1980' FWL; Sec. 19, T-5-S, R-25-E.	If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has						
JUL 2 2 2003 Qc -	the sales meter #21320 located @ 1870' FSL & 2078' FWL, Sec. 19; T-5-S, R-25-E next to the Rose Federal #6 located @ C-1980' FSL & 1980' FWL;						
La -				ACC			
PETROLEUM ENGINEER				PE	ARMANDO A	Long	
14. 1 hereby certify that the foregoing is the and correct							
Name (PrintedlTyped)  Jim Pulis  Title Production Superintendent		Title pr	Title Production Superintendent				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Date July 15, 2003

Name

Office

(Printed/Typed)

Approved by (Signature)

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Signature

