

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Minerals and Natural Resources
RECEIVED
JAN 13 2020
CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505
EMNRD-OCD ARTESIA

Form C-103
Revised August 1, 2011

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-26213
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other Injection <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator Chevron USA, Inc.		6. State Oil & Gas Lease No.
3. Address of Operator 6301 Deauville Blvd., Midland, TX 79706		7. Lease Name or Unit Agreement Name South Culebra 23
4. Well Location Unit Letter L : 1920 feet from the South line and 660 feet from the West line Section 23 Township 23S Range 28E NMPM Eddy County		8. Well Number 2
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3019 RKB		9. OGRID Number 4323
		10. Pool name or Wildcat East Loving Brushy Canyon

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: TEMPORARILY ABANDON ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion

Chevron USA INC abandoned this well as follows:

01/02/19 Move in P&A equipment, TOH and L/D rods.
01/03/20 N/U BOP, pull tubing, set CIBP @ 6000'.
01/06/20 TIH and tag CIBP, spot 25 sx class c, 1.32 yld, 14.8 ppg cmt @ 6000'-5756', WOC, tag TOC @ 5998'. Set CIBP @ 5679'.
01/07/20 Pressure test casing t/ 1000 psi f/ 15 minutes, spot MLF, spot 130 sx class c, 1.32 yld, 14.8 ppg cmt @ 5679'-4394', WOC, tag TOC @ 4493', spot 30 sx class c, 1.32 yld, 14.8 ppg cmt @ 3520'-3222', spot 50 sx cmt @ 2658'-2165'.
01/08/20 Perforate at 600', circulate through surface casing annulus until clean, circulate 165 sx cmt @ 600'-surf inside and out of production casing. RDMO. P&A complete.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

1/10/2020

SIGNATURE

Howie Lucas
Well Abandonment Engineer, Attorney in Fact

E-mail address: howie.lucas@chevron.com PHONE 432-687-7216

For State Use Only

APPROVED BY:  TITLE: Staff DATE: 1/16/20

Conditions of Approval (if any):

28