Submit 3 Copies To Appropriate District	State of New Mexico		Form C-103
Office District I	Energy, Minerals and Natural Resources		Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
<u>District II</u> 811 South First, Artesia, NM 88210	OIL CONSERVATI	ON DIVISION	30-005-60697
District III	1220 South St. 1	Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NN	M 87505	STATE FEE X
1220 S. St. Francis Dr., Santa Fe, NM			6. State Oil & Gas Lease No.
87505 SUNDRY NOT	ICES AND REPORTS ON WE	SIIS	7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPO			7. Dease Ivalie of Olicing Content value.
DIFFERENT RESERVOIR. USE "APPLI			Twin Lakes San Andres Unit
PROPOSALS.) 1. Type of Well:			
Oil Well Gas Well	☐ Other	DEACH /= 5	
2. Name of Operator		RECEIVED	8. Well No.
Tipton Oil & Gas Acquisitions, In	C.	FEB 2 1 2006	48
3. Address of Operator		-	9. Pool name or Wildcat
P.O. Box 1234, Lovington, NM 8	8260	JUU-ARTESIA -	Twin Lake, San Andres (Assoc)
4. Well Location			
Unit Letter M 570	feet from the South	line and <u>330</u> fee	et from the <u>West</u> line
Soution 21	Taramahin 80	D 20E	NIM (DM Change County)
Section 31 Township 8S Range 29E NMPM Chaves, County 10. Elevation (Show whether DR, RKB, RT, GR, etc.)			
	10. Elevation (Snow wheth	er DR, KKB, K1, GK, et	<i>C.)</i>
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
		*	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	」 PLUG AND ABANDON	REMEDIAL WOF	RK
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR	RILLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST A	
OTHER:	<u></u>	OTHER: CONVE	ERT TO PRODUCER X
			, –
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompilation.			
•			
1. POOH with pkr. and plastic coated tbg.			
 RIH w/csg. scraper. RIH with 2 3/8" tbg., pump and rods. 			
4. Set pumping unit.			
5. Hang on, space out.			
6. Convert to production 1	/5/06		
24-hr. test 4 BO and 10 l	ЗW	•	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE Ochri Mily TITLE Agent, For Clay Tipton (Sec-Treas.), Principal DATE 2/16/06			
Type or print name Lon Clay?	Tipton Telephone No.	505-631-4121	
(This space for State (ise)			kind a g good
	OR RECORDS ONLY		MAY 2 3 2006
APPPROVED BY Conditions of approval, if any:	ALI ESPACIONA ALASILI	LE	DATE
Conditions of approval, it ally.			