#### Form 3160-5 (February 2005)

1. Type of Well

3a. Address

Öil Well

2. Name of Operator LCX ENERGY, LLC

## OCD-ARTESIA

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007

### SUNDRY NOTICES AND REPORTS ON WELLS

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

Other

✓ Gas Well

110 N. MARIENFELD, SUITE 200, MIDLAND, TX 79701

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1880' FSL & 660' FEL, SEC 32, T16S, R25E

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

LAPITOS. IVIARCII 31, 2007				
5. Lease Serial No.				
6. If Indian, Allottee or Tribe Name				
7. If Unit or CA/Agreement, Name and/or No.				
8. Well Name and No.				
1625 FED COM #322				
9. API Well No.				
30-015-34443				
10. Field and Pool, or Exploratory Area				
Cottonwood Creek - Wolfcamp				
11. County or Parish, State				
EDDY, NM				

12. CHECK A	PPROPRIATE BOX(ES) T	O INDICATE NATUR	E OF NOTICE, REPORT, O	R OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent  ✓ Subsequent Report  ☐ Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Start/Resume) Reclamation Recomplete Temporarily Abandon Water Disposal	Water Shut-Off Well Integrity Other		

3b. Phone No. (include area code)

432-687-1575

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones.


Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

PLEASE FIND THE ATTACHED DIAGRAM SHOWING THE PAD SITE AND PRODUCTION EQUIPMENT LOCATION.

RECEIVED

MAY 1 8 2006

UUU-MATECIA



14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)	<del></del>	· · · · · · · · · · · · · · · · · · ·						
KANICIA DAVID Title		e REGULATORY ANALYST						
Signature Kanicia Dand	Date		04/07/2006					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved by		Title	Date					
Conditions of approval, if any, are attached. Approval of this notice does not warr certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon.	Office							
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212 make it a crime for any person knowingly and willfully to make to any department or agency of the United								

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

**1625 Fed Com 322**API # 30 - 015 - 34443
1880' FSL & 660' FEL, Sec 32, T16S, R25E Eddy Co., New Mexico

## Production Equipment and current location.

