Submit 3 Copies To Appropriate District Office	State of New Mo	exico	Form C-103			
District I	Energy, Minerals and Nati	ural Resources	WELL ADINO		May 27, 2004	
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.			
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION	I DIVISION	30-015-05365 5. Indicate Type of Lease			
District III	1220 South St. Fra	ncis Dr.	STATE FEE			
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 8	6. State Oil & O				
1220 S. St. Francis Dr., Santa Fe, NM	,		5. 5 511 65 5	340 20400		
87505 CLDIDDAY NO.	PICES AND DEPONTS ON WELL	2	7 I N	T T A		
1	SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			or Unit A	greement Name	
	ICATION FOR PERMIT" (FORM C-101) F		Skelly Unit		ĺ	
PROPOSALS.)				8. Well Number 70		
1. Type of Well: Oil Well	Gas Well Other Injection	9. OGRID Number				
2. Name of Operator Forest Oil Corporation		0041				
3. Address of Operator		10. Pool name or Wildcat				
3504 NW County Road		OCU-PATTERIA			/S QN GB SA	
4. Well Location						
	1980 feet from the South	line and 660	feet from the	Fact	line	
Section 23	Township 17S	Range 31E	leet from the _ NMPM	Eddy		
Section 25	11. Elevation (Show whether DE		NIVIPIVI	Eddy	County	
3881' DF						
Pit or Below-grade Tank Application						
Pit type Depth to Grounds	waterDistance from nearest fresh	water well Dista	nce from nearest su	rface water		
Pit Liner Thickness: mi			struction Material	-		
				D .		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:						
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐						
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A						
PULL OR ALTER CASING		CASING/CEMENT				
OTHER: Temporary Abandon		OTHER:				
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date						
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion						
or recompletion.						
The annulus will be pressured to 500 PSI to check its integrity. If it is ok, a pulling unit will be rigged up. The packer						
will be released and pulled out of the hole, laying down tubing and packer. A CIBP will be set where packer was						
set. The Artesia OCD office will be notified before start of work and casing test. The casing will be pressured to 500						
PSI and tested again with	a 30 minute chart.					
Estimated data of starting	means and words will be as soon as me	aaibla				
Estimated date of starting	proposed work will be as soon as po	issible.				
CIBP must	be within 100' of Top					
Perforations. Notify OCD 24 hrs. prior is						
any work done.						
I handby contify that the information	- abassa ia tunia and a annulate to the l		11 11 6			
grade tank has been/will be constructed of	n above is true and complete to the bor closed according to NMOCD guidelines	Dest of my knowledge	and beliet. I fur an (attached) alte	ther certify t rnative OCI	that any pit or below-	
			ar (armeneu) arre		> approved plan	
SIGNATURE Many Co June	TITLE_	Production Analyst		_DATE	June 26, 2006	
Tyme on mint areas No. 1. The		O	T. 1	(605) 5	00.0505	
Type or print name Mary Jo Turn	er E-mail address: mjtur	ner@torestoil.com	Telephone No.	(505) 39	3 2-9797	
For State Use Only	Burn	Gerry Gu	iye			
APPROVED BY: / LILY TITLE Deputy Field Inspector DATE 2 8 2006						
Conditions of Approval (if any)					. 20 2000	
Conditions of Approval (if ally k		District II - A	rtesia			