NMOCD

Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR PURE ALL OF LAND MANAGEMENT

BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

FORM APPROVED
OMB No. 1004-0137
Expires: March 31, 2007

5. Lease Serial No.

	NM111398						
5.	If Indian, Allottee or Tribe Name						

SUBMIT IN TRIPLICATE- Other instructions on reverse side.							7. If Unit or CA/Agreement, Name and/or No.				
1. Type of Well Gas Well Other			JUL 1 0 2006			8. Well Name and No.					
2. Name of Operator Yates Energy Corporation			NORTHW-DOD			North Hess Federal "23" No. 1 9. API Well No.					
3a Address			3b. Phone No. (include area code)			30-025-34509					
P. O. Box 2323, Roswell, New M	432-683-5511			10. Field and Pool, or Exploratory Area							
4. Location of Well (Footage, Sec., 7				Hess Morrow East 11. County or Parish, State							
1550 FSL and 660' FEL of Sec				Eddy, New Mexico							
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA											
TYPE OF SUBMISSION	SUBMISSION TYPE OF ACTION										
Notice of Intent Subsequent Report Final Abandonment Notice	ent Report Casing Repair			reat truction Abandon	Production (Statement of Statement of Statem	candon	Walter Shut-Off Well Integrity ✓ Other Test into Lonesome Dove #2 Production facilities				
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) The following Procedure is to test the above captioned well. 1. Lay a 2000' steel line from this lease along the right-of-way down road and tie into the Lonesome Dove Federal No. 2 facilities located 660' FNL and 660' FEL of Sec. 26, T23S, R23E. 2. The Lonesome Dove well will be shut in and the North Hess well will be tested through these facilities. 3. The oil tank will be gauged prior to test liquids going to tank.											
14 I hereby certify that the foreg Name (Printed/Typed)	going is true and	correct				/			,		
Sheryl Jonas				Title Ag	ent for Yates Energ	gy Corp	·- <u>-</u>				
Signature & hur	us Oc	ZN AS		Date	0	6/30/2006					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE											
Approved by (ORIG. Conditions of approval, if any, are a certify that the applicant holds legal	SGD.) ALEX	l of this notice of	does not warrar	nt or	TROLEUM E	ENGINEE	ש שו	L 07	2006		
which would entitle the applicant to	which would entitle the applicant to conduct operations thereon. Office Office Office Office										
Title 18 U.S.C. Section 1001 and Title States any false, fictitious or fraudule	: 43 U.S.C. Section 1 ent statements or i	1212, make it a representations	crime for any as to any matter	person kno within its	wingly and willfully turisdiction.	to make to any d	epartment or	igency of th	e United		