UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT 1301 W. Grand Avenus enaling

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212

Oil Cons. N.M. DIV-Dist. 2

FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLARTESIA, NM 88210 Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No. 8910085280 SUBMIT IN TRIPLICATE - Other Instructions on reverse side X IMAGNOTI 8. Well Name and No. Type of Weil Other Oil Well Gas Well WLHU TRACT 13 #12 9. API Well No. Name of Operator 30-015-27446 Yates Petroleum Corporation 10. Field and Pool, or Exploratory Area 3a Address 3b. Phone No. (include area code) 505-748-1471 105 S. 4th Street - Artesia, NM 88210 LOCO HILLS Queen Grayburg S/A 4. Location of Well (Footage, Sec., T.,R., M., or Survey Description) 11. County or Parish, State UNIT H 1408' FNL & 440' FEL Section 12-T18S-R29E EDDY COUNTY, NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORTS OFFICER DATA TYPE OF SUBMISSION Notice of Intent Acidize Production (Start/Resume) Water Shut-Off Deepen Well Integrity Subsequent Report Alter Casing Fracture Treat Reclamation Other Final Abandonment Notice Casing Repair New Construction Recomplete Change Plans Temporarily Abandon X Plug and Abandon Plug Back Convert to Injection Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLWBIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operations results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspecition.) Call OCD in Artesia w/ 24 hour notice before commencing operations - 505-748-1283. 1. MIRU WSU & all safety equipment. No casing recovery will be attempted. TOH w/ tubing, if any. 2. TIH w/ tubing. Spot 25 sk Class C cement plug from 2662'-2852'. Pull tubing up hole & reverse circ clean. WOC & tag plug; reset if necessary. Load hole w/ plugging mud. 3. Pull up to 1310' & spot 25 sk Class C cement plug from 1120' - 1310'. Pull tubing up hole & reverse circ clean & WOC. Tag plug, reset if necessary. Load hole with plugging mud. 4. Pull up to 525' & spot 25 sk Class C plug from 285'-475'. Pull up hole & reverse circ clean & WOC. Tag plug, reset if needed. Load hole W/ mud. 5. TIH w/ tubing to 150' to spot 15 sk Class C cement plug @ surface. Fill any voids in the annulus & WOC 24 hrs to tag plug; reset if necessary. 6. Remove all surface equipment & weld dry hole marker per regulations. APPROVED APPROVAL SUBJECT TO AUG 18 2003 GENERAL REQUIREMENTS AND SPECIAL STIPULATIONS ATTACHED LES BABYAK PETROLEUM ENGINEER I hereby certify that the foregoing is true and correct Name (Printed/Typed) Title Operations Technician Donna Clack Signature 8-12-03 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Title Date Conditions of approval, if any, are attached. Approval of this notice does not w Office the applicant noids legal or equitable title to those rights in the subject if applicant to conduct operations thereon

it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious