<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

Energy Minerals and Natural Resources
Oil Conservation Division

State of New Mexico
Minerals and Natural Resources
Division 4

Div 1220 South St. Francis Dev.

May 27, 2004 Submit to appropriate District Office

☐ AMENDED REPORT

Form C-101

1220 S. St. Fi						T.C. 1418 '0		કેં .જ	57/ 			
APPI	ICATI	ON FO	R PERMIT			ENTER,	DEEPE	N, PLU	<b>GBA</b>	CK, OR	ADD	A ZONE
		N	ladel and Gussma 601 N. Marienfo	n Permian, I	LC		75 W	15561	5	3 API Nur		
	. 6.1.		Midland, T			NI		30 –	015-	35337	Well N	
	erty Code				Property Big Chie	Name f Fee					#10	10.
	<del>ио ф</del>	9	Proposed Pool 1		-				10 Prope	osed Pool 2		
			ublin Ranch Morrow		<u>-</u>							
				_	<sup>7</sup> Surface	Location						
UL or lot no. D	Section 22	Township 22 S	Range 28 E	_Lot Id	in Feet fro		th/South line North	Feet from		East/West	line	County Eddy
L	22	22.3	<del></del>	and Potto	om Hole Loca	<del></del>				East		Eddy
UL or lot no.	Section	Township	Range	Lot lo			th/South line	Feet from	n the	East/West	line	County
										<u> </u>		
ll yr 1	T. C.1		12 11/11/25 0		ditional We	e/Rotary		14 7	0.1.	·	15.0	T I El i
,	Type Code N		<sup>12</sup> Well Type Co G	de		e/Kotary R		14 Lease Type P	Code	15 Ground Level Elevati 3,091'		
<sup>16</sup> M	Iultiple No		17 Proposed Dep 12,900'	th		mation rrow			19 Contractor Patterson - UTI		<sup>20</sup> Spud Date 02/01/07	
Depth to Grou		0' or Less		Distance f	rom nearest fresh w	ater well: 200' or	Less	Dista	nce from t	nearest surface	water: Les	ss than 200'
<u>Pit:</u> Liner	: Synthetic	<b>⊠</b> 20_r	nils thick Clay	☐ Pit Vo	olume: _15,000_	bbls Drilling Method:						
Close	ed-Loop Sys	tem 🗌					Fresh Wate	r 🛛 Brine	⊠ Die	esel/Oil-base	d 🗌 Ga	as/Air 🔲
			21	Propos	ed Casing a	nd Cemer	nt Progra	ım				
Hole S	Size	Cas	sing Size	Casing	weight/foot	Setting	Depth	Sac	ks of Ce	ement	Es	stimated TOC
17 1/2	ί"	1	3 3/8"	48# H-40		300'			300sx			Circ. to Surf.
12 ¼	;;;		9 5/8"	40# N	I-80, P-110	6,1	00'	1200sx		x		Circ. to Surf.
8 3/4	"		5 ½"	17#, 20	# HCP-110	12,9	900'		1500sx TOC		OC @ +/-6000'	
ļ		<u> </u>			-	ļ		<u> </u>				
22 Describe t	he proposed	nrogram	If this application	is to DEEP	EN or PLUG BA	CK give the	data on the	present prod	luctive z	one and pror	nosed nev	w productive zone.
			ogram, if any. Us				data on the	present prod	iuctive z	one and prop	Joseu He	w productive zone.
will be install	led on the 9	5/8" and tes	roposes to drill the sted. Cement to cogs can be witness	over all wa	ter, oil and gas p	roducing zone	s. NGP wil	l notify NM				fcamp. A BOP ting times so the
			n given above is				OIL	CONSE	RVAT	TION DI	VISIO	N
best of my knowledge and belief. I further certify that the drilling pit will be constructed according to NMOCD guidelines , a general permit , or an (attached) alternative OCD-approved plan .				Approved by:								
Signature: Twww Nast				BRYAN G. ARRANT DISTRICT II GEOLOGIST								
Printed name	: Terry Wes	1//		**		Title:	·····	- DIO	+ KHC	<del>1 11 GE</del> (	<del>)LOC</del>	HSI
Title: Staff E		<u> </u>			-	Approval Da	neDFC	2 8 2008	E	xpiration Da	ite:	EC 2 8 2007
		@naguss.co	m		<del></del>			o SAAE	,			
E-mail Address: TerryW@naguss.com  Date: 12/26/06 Phone: 432-682-4429					Conditions of Approval Attached							

DISTRICT I 1625 N. French Dr., Hobbs, NM 68240 DISTRICT II 1301 W. Grand Avenue, Artesia, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 DISTRICT IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

Energy, Minerals and Natural Resources Department

Torm C-102
31 123456 Form C-102
Cover 12, 2005

Appropriate District Office

State Lease - 4 Copies

MENDED REPORT

Lease - 3 Copies

#### OIL CONSERVATION DIVISIONS 1220 South St. Francis Dr. Santa Fe, New Mexico 87505

	WELL LOCATION AND	ACREAGE DEDICAT	TION PLAT	
API Number	Pool Code	DUBLIN	MORROW	
Property Code	Prope BIG	Well Number		
OGRID No.	1	tor Name JSSMAN PERMIAN		Elevation 3091'

#### Surface Location

UL or lot No.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County
D	22	22 S	28 E		990	NORTH	990	WEST	EDDY

#### Bottom Hole Location If Different From Surface

bottom note bottom in billorent from Surface									
UL or lot No.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County
Dedicated Acre	s Joint o	or Infill Co	nsolidation (	Code Or	der No.			L	

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

			OPERATOR CERTIFICATION
990'	   Lat.: N32*22'58.3"   Long.: W104*04'51.0"   (NAD-83)		I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.
			Signature Date  TERRY WEST
	   	i	Printed Name
			SURVEYOR CERTIFICATION
			I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervison and that the same is true and correct to the best of my belief.
		 	OCTOBER 26, 2006  Date Surveyor  Signature to Seal of Ness  Professional Surveyor
	 		Profesional Support
	1	1	Certificity No. Gary L. Hours 7977

### NADEL AND GUSSMAN PERMIAN, L.L.C. 601 N. Marienfeld, Suite 508 Midland, TX 79701 (432) 682-4429 (Office) (432) 682-4325 (Fax)

012/26/06

Mr. Bryan Arrant District 2 Geologist New Mexico Oil and Gas Division 1301 West Grand Avenue Artesia, NM 88210

Re: Big Chief Fee #10 990' FNL & 990' FWL Unit Letter D, Sec. 22-T22S-R28E Eddy, NM Rule 118 H2S Exposure

Dear Mr. Arrant,

Nadel and Gussman Permian have evaluated this well and we do not expect to encounter hydrogen sulfide. However, we will employ a third party monitoring system. We will begin monitoring prior to drilling out the intermediate casing and will continue monitoring the remainder of the well.

Please contact me if you have any additional questions.

Sincerely,

Terry West Staff Engineer


#### Hydrogen Sulfide Drilling Operations Plan


- 1. Company and Contract personnel admitted on location should be trained by a qualified H<sub>2</sub>S safety instructor to the following:
  - A. Characteristics of H<sub>2</sub>S.
  - B. Physical Effects and Hazards.
  - C. Proper Use of Safety Equipment and Life Support Systems.
  - D. Principle and Operation of H<sub>2</sub>S Detectors, Warning System and Briefing.
  - E. Evacuation Procedure, Routes and First Aid.
  - F. Proper Use of 30 minute Pressure Demand Air Pack.

#### 2. H<sub>2</sub>S Detection and Alarm Systems

- A. H<sub>2</sub>S Detectors and Audio Alarm System to be Located at Bell Nipple, End of Blooie Line (mud pit) and on Derrick floor or doghouse.
- 3. Windsock and/or Wind Streamers
  - A. Windsock at Mud Pit Area Should be High Enough to be Visible.
  - B. Windsock at Briefing Area Should be High Enough to be Visible.
  - C. There Should be a Windsock at Entrance to Location.
- 4. Condition Flags and Signs
  - A. Warning Sign on Access Road to Location.
  - B. Flags to be Displayed on Sign at Entrance to Location.
    - 1. Green Flag, Normal Safe Condition.
    - 2. Yellow Flag, Indicates Potential Pressure and Danger.
    - 3. Red Flag, Danger H<sub>2</sub>S Present in Dangerous Concentration Only Emergency Personnel Admitted to Location.
- 5. Well Control Equipment
  - A. See Attached Diagram.
- 6. Communication
  - A. While Working Under Masks Chalkboards Will be Used for Communication.
  - B. Hand Signals will be Used Where Chalk Board is Inappropriate.
  - C. Two Way Radio or Cell Phone will be Used to Communicate off Location in Case of Available at Most Drilling Foreman's Trailer or Living Quarters.
- 7. Drillstem Testing
  - A. Exhausts will be Watered.
  - B. Flare Line will be Equipped with an Electric Igniter or a propane pilot light in case gas reaches the surface.
  - C. If Location is near any Dwelling a Closed DST will be Performed.
- 8. Drilling Contractor Supervisor will be Required to be Familiar with the Effects H<sub>2</sub>S has on tubular goods and other mechanical equipment.
- 9. If H<sub>2</sub>S Encountered, Mud system will be Altered if Necessary to Maintain Control of Formation. A Mud Gas Separator will be Brought into Service Along with H<sub>2</sub>S Scavengers if Necessary.

### Nadel and Gussman Permian MINIMUM BLOWOUT PREVENTER REQUIREMENTS





- Cameron "F", Halliburton Low Torque or Shaffer Flo-Seal.
- 2. 2" flanged adjustable chokes, min. 1" full opening & equiped with hard trim.
- 3. 4" x 2" flanged steel cross.
- 4. 4" flanged steel tee.
- 5. 4" flanged all steel valve (Type as in no. 1).
  6. Drilling Spool with 2" x 4" flanged outlet.
  7. Drilling Spool with 2" x 2" flanged outlet.

- 8. 2" x 2" flanged steel cross.
- 9. 4" pressure operated gate valve.
- 10. 2" flanged steel tee.

position. Use all steel fittings throughout. Make 90° turns with bull plugged tees only. No field welding will be permitted on any of the components of the choke manifold and related equipment upstream of the chokes. The choke spool and all lines and fittings must be at least equivalent to the test pressure of the preventers required. Independent closing control unit with clearly marked controls to be located on derrick floor near driller's position.

(10-31-96) WTXBOPS.PPT

# PROPOSED MUD PROGRAM

# **CASING DESIGN**

13 3/8"	Surface Casing	at	<b>3</b> 00'
9 5/8"	Intermediate Casing	at	6,100°
8 3/4"	Open Hole	to	12,900'

# RECOMMENDED MUD PROPERTIES

<b>DEPTH</b>	<b>MUD WEIGHT</b>	<u>VISCOSITY</u>	FLUID LOSS
Spud	8.6- 8.7	32-34	No Control
<b>3</b> 00'	8.9- 9.2	32-34	No Control
Set 13 3/8" Surface	Casing at <b>3</b> 00'. Drill ou	t with Brine Water.	
500'	9.8-10.0	28-30	No Control
1,500'	10.0-10.1	28-30	No Control
3,000°	10.0-10.1	28-30	No Control
4,500°	10.0-10.1	28-30	No Control
6,100°	10.0-10.1	28-30	No Control
Set 9 5/8" Intermed	liate Casing at 6,100°. D	rill out with Fresh W	ater.
6,200'	8.4- 8.5	28-29	No Control
7,000'	8.4- 8.5	28-29	No Control
8,000'	8.4- 8.5	28-29	No Control
9,000'	8.4- 8.5	28-29	No Control
9,500°	9.2- 9.4	28-29	No Control
10,000'	9.4- 9.6	28-29	No Control

11,000'	9.8- 10.0	32-34	<12
11,400°	10.0-12.0	32-34	<12
11,800'	10.0-12.0	45-50	<12
12,300'	10.0-12.0	45-50	<12
12,900'	10.0-12.0	45-50	<12

# RECOMMENDED MUD PROGRAM BY CASING INTERVAL

### Surface Hole 0 -300'

Spud with a Horizon Gel/Lime slurry, mixing one Lime per ten Gel for a 32-34 viscosity. Lost circulation is common in this area. Should lost circulation occur and cannot be re-gained with one LCM pill, dry drill to total depth.

### Intermediate Hole 300'-6,100'

Drill out from under the surface casing with brine water, circulating through the reserve pit to allow maximum time for settling drilled-solids.

Severe lost circulation is possible while drilling this interval. Seepage can be controlled with additions of Paper. Should complete loss of returns occur while drilling, we recommend pulling up above the loss zone to avoid differential sticking and spotting a 100-200 barrel pill containing 15-25 lb/bbl lost circulation material. Spot the pill from above at a reduced pump rate before returning to bottom to commence drilling operations. If lost circulation is not regained with one or two LCM pills, some blind drilling may be required. If partial returns are maintained, use only brine for volume to avoid severe washouts.

Crooked hole can be a problem in this area.

Allow hole conditions to dictate the need for any additional viscosity or hole sweeps at total depth to clean the hole and insure smooth casing operations.

### Open Hole-6,100'-12,900'

Drill out from under the intermediate casing with fresh water, circulating through the outer reserve pit to, once again, allow maximum time for settling drilled-solids. A flocculent (MF-1) can be used to aid in dropping solids, providing a clear fluid and maximum penetration rates.

# We recommend that the surface pit system include the following:

⇒ Flo-line Cleaner – This will allow removal of a wider range of solids and will assist in optimizing the efficiency of the de-sander and de-silter (or scale shaker).

- ⇒ Centrifuge—This will allow for fine solids removal and barite recovery.
- ⇒ Shale and settling pit by-pass Canal To reduce volumes when conditioning mud for DST's or added hole cleaning at total depth.
- ⇒ Pit Volume Totalizers To more accurately monitor pit gains and losses.
- ⇒ One 1000 sack Barite Bin- For barite storage on location.

We recommend maintaining a 9.0 - 9.5 pH with Caustic.

As drilling progresses post 6,000', some loss of fluid should occur. Minor seepage can be controlled with additions of Paper. Complete lost circulation is also possible during this interval. Should complete loss of returns occur while drilling, we recommend following the same procedure described in the previous section.

Severe seepage in the **Delaware** and **Bone Springs** may require alternative methods of combating losses, such as:

- ⇒ Heavy bentonite pills
- ⇒ Diesel/Loloss pills
- ⇒ Drill-out pills spotted or squeezed

Crooked hole can also be a problem in this section past 8,000'.

Utilize Horizon Poly-Vis II and Prehydrated Gel for periodic sweeps while drilling, prior to mud-up.

At a depth of  $9,500^{\circ}$  or the top of the Wolfcamp, we recommend returning to the working pits and displacing with brine weighing 9.2 - 9.4 ppg.

By 11,000' or the top of the Strawn, we recommend displacing with brine and mudding-up with an XC Polymer/MF-55 system to achieve the following properties:

Mud Weight 9.8–10.0 Viscosity 32 – 34 Fluid Loss <12

It is also possible to encounter abnormal pressure in the Atoka formation. Drilling slightly under-balanced has proven successful at maximizing penetration rates, however, it may be necessary to increase the mud weight to 10.5 –12.0 ppg to control formation pressure. It may be possible to avoid increasing the weigh of the entire system by spotting heavy pills on bottom for trips.

If higher mud weights are required, 7" casing may be necessary to cover the Bone Springs formation.

XCD Polymer at higher concentrations has the unique ability to increase the "low-shear rate viscosity" of the fluid. This property has proven to minimize losses in the **Delaware** and **Bone Springs**. On two wells in the immediate area, this fluid has eliminated the need for 7" casing while formation pressures required as high as an 11.8 ppg mud weight to control.

We recommend adding MF-55 to the system in this particular area to minimize potential sloughing shale. MF-55 is a non-ionic emulsion polymer that will chemically tie up water. This "taking on of water" effect has proven to significantly minimize fluid invasion. MF-55 also has the ability to inhibit through encapsulation, or coating of the wellbore.

Lost circulation could occur after mud-up. We recommend using fibrous-type LCM to control seepage. Should complete loss of returns occur, we recommend following the same procedure as described in the previous section.

### REDUCED FORMATION DAMAGE WITH XC POLYMER

At 11,800' or the top of the Morrow, we recommend increasing the concentration of XC Polymer to 1 3/4 to 2 ppb to achieve low shear-rate viscosity (LSRV). This concentration of XC Polymer is necessary to accomplish the networking effect of the polymers. It is this networking effect of the Zanthan Gum polymer that gives it its unique ability to increase the LSRV.

By achieving elevated viscosity in the low shear region of the flow profile, lateral penetration of fluid into the formation is reduced. This will minimize damage to the Morrow formation caused by the migration of clays once the kaolinite booklets have been broken. Also, an additional benefit of reaching this flow profile is that hole cleaning is maximized.

LSRV is monitored by measuring the gel strength and the relaxation time of the fluid. Minimum gel strength values of 40 - 60 (.2 spring) and a relaxation measurement of 3 to 4 minutes are essential to provide the proper flow profile. The "relaxation measurement" directly measures the LSRV of the fluid. The **Brookfield Rheometer** is also used in the field to correlate with the relaxation measurement.

This fluid, adjusted as shown in the "RECOMMENDED MUD PROPERTIES" section, or as hole conditions dictate, should provide good hole conditions for any testing, logging and casing operations.

#### SECTION 22, TOWNSHIP 22 SOUTH, RANGE 28 EAST, N.M.P.M., EDDY COUNTY. NEW MEXICO.

150' NORTH OFF SET 3092.1 П

NADEL & GUSSMAN PERMIAN BIG CHIEF #10 ELEV. - 3091'

150' WEST OFF SET □ 3091.4'

0

150' EAST □ OFF SET 3092.0'

LAT. N32\*22'58.3" LONG. W104\*04'51.0" (NAD~83)

150' SOUTH OFF SET 3092.7

PROP LEASE ROAD 650.0' CO. RO. 605 5.0 MILL

Directions to Location:

FROM THE JUNCTION OF CO. RD. 605 (U.S. REFINERY) AND CO. RD. 607 (OLD POST), PROCEED NORTHEAST 1.4 MILE TO PROPOSED LEASE ROAD.

BASIN SURVEYS P.O. BOX 1786 - HOBBS, NEW MEXICO

Drawn By: J. M. SMALL W.O. Number: 17341

17341W Disk: JMS Date: 10-27-2006

100 100 200 FEET SCALE: 1" = 100'

### NADEL AND GUSSMAN PERMIAN


BIG CHIEF #10 / Well Pad Topo

BIG CHIEF, No. 10 LOCATED 990' FROM

THE NORTH LINE AND 990' FROM THE WEST LINE OF SECTION 22, TOWNSHIP 22 SOUTH, RANGE 28 EAST,

N.M.P.M., EDDY COUNTY, NEW MEXICO.

Survey Date: 10-26-2006 Sheet




BIG CHIEF #10 Located at 990' FNL & 990' FWL Section 22, Township 22 South, Range 28 East, N.M.P.M., Eddy County, New Mexico.



P.O. Box 1786 1120 N. West County Rd. Hobbs, New Mexico 88241 (505) 393-7316 - Office (505) 392-3074 - Fax basinsurveys.com

W.O. Number:	JMS	17341T	
Survey Date:	10-2	6-2006	
Scale: 1" = 2	000'		
Date: 10-27-	-2006		

NADEL AND GUSSMAN PERMIAN



BIG CHIEF #10 Located at 990' FNL & 990' FWL Section 22, Township 22 South, Range 28 East, N.M.P.M., Eddy County, New Mexico.



P.O. Box 1786 1120 N. West County Rd. Hobbs, New Mexico 88241 (505) 393-7316 - Office (505) 392-3074 - Fax basinsurveys.com

<b>W</b> .O.	Number:	JMS	17341T	
Surv	ey Date:	10-2	6-2006	
Scal	e: 1" = 2	MILES		
Date	: 10–27-	-2006		

NADEL AND GUSSMAN PERMIAN

