Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

OCD-ARTESIA

FORM APROVED

OMB NO. 1004-0135
EXPIRES: NOVEMBER 30, 2000
ease Serial No.
LC-067849

abandoned well. Use Form 3160-3 (APD) for such proposals				6. If Indian, Allottee	or Tribe Name
SU	JBMIT IN TRIPLICATE	1 de 1	7		
1a. Type of Well ☑ Oil Well ☑ Ga	a Well Other	The state of the s	, 1	7. Unit or CA Agree	ment Name and No.
1a. Type of Well Oil Well Gas Well Other				8 Well Name and N	0.
2. Name of Operator				EAGLE 34 K FEDERAL 21	
DEVON ENERGY PRODUCTION COMPANY, LP				9. API Well No.	
3. Address and Telephone No.				3	0-015-29112
20 North Broadway, Ste 150	00, Oklahoma City, OK 73102	405-552-8198	<u> </u>	10. Field and Pool,	or Exploratory
4. Location of Well (Report location clearly and in accordance with Federal requirements)*				Red Lake; Queen-Grayburg-SA 12. County or Parish 13. State	
SEC 34 T 17S R 27E, Unit	 	OATE NATURE OF NOT	05 05007	EDDY	NM
TYPE OS SUBMISSION	APPROPRIATE BOX(s) TO INDI		OF ACTION	OR OTHER DATA	· · · · · · · · · · · · · · · · · · ·
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Production Reclamati	n (Start/Resume) on	☐ Water Shut-Off ☐ Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomple		Other Add Pay
Final Abandonment Notice	☐ Change Plans☐ Convert to Injection	Plug and Abandon Plug Back	☐ Temporar	ily Abandon	
Devon Energy Production Company, L 11/13/06 MIRU PU. POOH with rods, p 11/14/06 MIRU W/L truck. RIH with Cl 1546'; 25 SPF; 0.40 EHD; 26 holes. RD 11/15/06 Acidize with 3000 gallons 15' 11/16/06 Swab well. POOH with packe 11/19/06 Unset packer and POOH with 11/20/06 Frac 1414-1546' with 19,572 g	oump, and tubing. RIH with bit BP and set at 1890'. Test to 20 MO W/L. RIH with packer and % NEFE. Release packer and r er. Pick up RBP and set at 150 n packer. RIH with retrieving he	and scraper to 2164'. Po 00 psi - ok. Dumped 35' set at 1409'. est at 1504'. 4'. RIH with packer and sead and recovered plug a	OOH with bit on top of CIE set at 1409'. and POOH wi	and scraper. BP. RIH with casing Swab well. th plug.	
11/22/06 Turn well over to production. 14. Thereby certify that the foregoing is Signed (This page for Foderal or State Office we	Name	Norvella Adar Sr. Staff Engineering		Date	1/8/2007
(This space for Federal or State Office us	;e)			ACCEP	TED FOR RECORD
Approved by	Title	 		Date	
Conditions of approval, if any:					4 0007
WIR IN U.S. SHOWN DR. WARREN TO ANY THE RESERVE TO A SHOWN THE PARTY OF THE PARTY O			n stance and ra		FR 1 200/ ements or representations to any matter w
its jurisdiction.	person knowingly and willium to make any	asparation of agency of the Unite	o oraces any raise	, notificasion frauducent state	M May Man Start I Make I Was I
	*See I	nstruction on Reverse S	ide	INIE	SLEY W. INGRAM
				PETR	OLEUM ENGINEER

405/07