Form 3160-5 (April 2004)

UNITED STATES

ECDM ADDDOVED

	OCD - ARTESIA A		OM B No. 1004-0137 Expires: March 31, 2007				
1T			5. Lease Serial No.				

	DEPARTMENT OF THE I		WIN YES	Expires: March 31, 2007			
ŀ	BUREAU OF LAND MANA	AGEMENI \	\ /	5. Lease Serial No.			
SUNDRY	NOTICES AND REPO	ORTS ON WE	LLS	NM-38463			
Do not use th	6. If Indian, Allottee or Tribe Name						
abandoneu we	ell. Use Form 3160-3 (Al	r b) for such pro					
SUBMIT IN TRI	7. If Unit or CA/Agreement, Name and/or No. 8. Well Name and No.						
1. Type of Well X Oil Well							
2. Name of Operator				Pure Gold B Federal #12			
Pogo Producing Compar	ıy			9. API Well No.			
3a Address	30-015-35304						
P. O. Box 10340, Midl	10. Field and Pool, or Exploratory Area Sand Dunes Delaware West						
4. Location of Well (Footage, Sec., 7	^r ., R., M., or Survey Description)						
16501 FM 9 19201 FM	11. County or Parish, State						
1650' FNL & 1820' FWL	Eddy County, NM						
12. CHECK AP	PROPRIATE BOX(ES) TO I	NDICATE NATUR	RE OF NOTICE, RE	EPORT, OR OTHER DATA			
TYPE OF SUBMISSION							
	Acidize	Deepen	Production (Star	t/Resume) Water Shut-Off			
Notice of Intent	Alter Casing	Fracture Treat	Reclamation	Well Integrity			
Subsequent Report	Casing Repair	New Construction	Recomplete	x Other Spud			
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily Aba	undon			
rinai Abandonmeni Notice	Convert to Injection						

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Spud & Set Surface Csg - MIRU Capstar #14. Spud well @ 06:00 hrs 12/30/06. Drld 17-1/2" hole to 803'. TD reached @ 12:00 hrs 12/31/06. Ran 20 jts 13-3/8" 48# ST&C csg. Cmt'd w/ 650 sks 35:65 Cl C @ 12.8 ppg followed by 200 sks Cl "C" + 2% CaCl2 @ 14.8 ppg. Circ 247 sks to surface. Plug down @ 23:30 hrs 12/31/06. WOC 24 hrs. Make cut-off. Weld on WH. NU BOP's & test to 1000# ok. Test csg to 1000# for 30 mins ok.

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)				**************************************			
Cathy Wright Title		le Sr. Eng Tech					
Signature Star Much Date THIS SPACE FOR FEDERAL OR		STATE OFFICE USE ACCEPTED FOR RECORD					
Approved by		Γitle		Day! AN	3 1	2007	
Conditions of approval, if any, are attached. Approval of this notice does not warrant of certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	;	Office		FREDE	RICK	WRIGHT	R.
which would entitle the applicant to conduct operations thereon. FREDERICA VILINEER Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to provide United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.							

(Instructions on page 2)

2/5/07