

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUNDRY NOTICES AND REPORTS ON WELLS

OCD-ARTESIA

FORM APPROVED
OMB NO. 1004-0135
EXPIRES: NOVEMBER 30, 2000

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

SUBMIT IN TRIPLICATE

1a. Type of Well ☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
DEVON ENERGY PRODUCTION COMPANY, LP

3. Address and Telephone No.
20 North Broadway, Oklahoma City, OK 73102 405-552-8198

4. Location of Well (Report location clearly and in accordance with Federal requirements)*
330 FNL 1650 FEL B 3 18S 27E

5. Lease Serial No.

NMLC065478B

6. If Indian, Allottee or Tribe Name

7. Unit or CA Agreement Name and No.

8. Well Name and No.

Falcon 3B Federal 20

9. API Well No.

30-015-33193

10. Field and Pool, or Exploratory

Red Lake; Queen-Grayburg San Andres

12. County or Parish 13. State

Eddy

NM

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- | | | | |
|---|---|--|---|
| <input type="checkbox"/> Acidize | <input type="checkbox"/> Deepen | <input type="checkbox"/> Production (Start/Resume) | <input type="checkbox"/> Water Shut-Off |
| <input type="checkbox"/> Alter Casing | <input type="checkbox"/> Fracture Treat | <input type="checkbox"/> Reclamation | <input type="checkbox"/> Well Integrity |
| <input type="checkbox"/> Casing Repair | <input type="checkbox"/> New Construction | <input checked="" type="checkbox"/> Recomplete | <input type="checkbox"/> Other |
| <input type="checkbox"/> Change Plans | <input type="checkbox"/> Plug and Abandon | <input type="checkbox"/> Temporarily Abandon | |
| <input type="checkbox"/> Convert to Injection | <input type="checkbox"/> Plug Back | <input type="checkbox"/> Water Disposal | |

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work and approximate duration thereof. If the proposal deepens directionally or recompletes horizontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection)

1/02/07 MIRU PU.

1/03/07 POOH with rods and pump. ND WH and NU BOP. POOH with tubing. RIH with RBP and set at 2875'. Pump 10' sand on RBP. Test casing to 3000 psi - held good.

1/04/07 MIRU W/L. RIH with casing gun and perforate from 1952-2206'; 1 SPF, 0.40 EHD; 28 holes. RIH with packer and set at 1886'.

1/07/07 Acidize with 3000 gallons 15% HCl. Flow well back. Released packer and POOH with tubing and packer.

1/08/07 Frac with 213,086 gallons Aqua Frac 1000, 125,695# brown 20/40 sand, and 22,401# Siberprop 16/30.

1/09/07 Flow well back. RIH with rods and pump. Hang well on production.

14. I hereby certify that the foregoing is true and correct

Signed 

Name **Norvella Adams**
Title **Sr. Staff Engineering Technician**

Date **3/14/2007**

(This space for Federal or State Office use)

Approved by _____ Title _____
Conditions of approval, if any:

Date

ACCEPTED FOR RECORD
MAR 21 2007
FREDERICK WRIGHT
PETROLEUM ENGINEER