If earthen pits are used in association with the drilling of this well, an OCD pit permit must be obtained prior to pit construction.

Form 3160-3 (April 2004)

UNITED STATES

FORM APPROVED OMB No. 1004-0137 Expires March 31, 2007

DEPARTMENT OF T BUREAU OF LAND N	LC-028784-C	LC-028784-C 6. If Indian, Allotee or Tribe Name					
APPLICATION FOR PERMIT 1	TO DRILL OR R	EENTER					
	ENTER			7. If Unit or CA Agre	7. If Unit or CA Agreement, Name and No.		
				Grayburg Deep U	J nit		
				8. Lease Name and W	all No		
1b. Type of Well: X Oil Well Gas Well Other	X Sir	ngle Zone Multiple	e Zone	Grayburg Deep Unit No. 22			
2. Name of Operator				9. API Well No.			
Cimarex Energy Co. of Colorado //	268	3		30-015-	5598		
3a. Address	3b. Phone No.	(include area code)		10. Field and Pool, or Exploratory			
PO Box 140907; Irving, TX 75014-0907	972-401-31	11	Le	O Hills; Wolfcame, NE			
4. Location of Well (Report location clearly and in accordance	with any State req	uirements.*)		11. Sec., T. R.M. or Blk.			
At Surface 1990 FWL 2	B. Ava	le de					
At proposed prod. Zone 1650 FNL & FWL	Per.	54 dated 4	4-16-0	25-17S-29E			
14. Distance in miles and direction from nearest town or post of	ffice*			12. County or Parish	13. State		
2 miles NW of Loco Hills				Eddy	NM		
15 Distance from proposed*	16. No of acres	in lease	17. Spaci	ng Unit dedicated to this w	rell		
location to nearest			ļ				
property or lease line, ft.							
(Also to nearest drig. unit line if any) 750'		1440		40 acre	c		
any) 750' 18 Distance from proposed location*	19. Proposed D		20. BLM	/BIA Bond No. on File			
to nearest well, drilling, completed,		•					
applied for, on this lease, ft.							
n/a	9400'			NM-257	5		
21. Elevations (Show whether DF, KDB, RT, GL, etc.)	22. Approxima	te date work will start*	•	23. Estimated duration			
3589' GR	5	/15/2007	- 1	35-45	davs		
3307 GR		24. Attachments			days		
The following, completed in accordance with the requirements of 0			e attached to	this form:			
The following, completed in accordance with the requirements of c	onshore on and c	ias Order 140. 1, shall o	c attached ic	uns tom.			
Well plat certified by a registered surveyor		1 -,	-	ns unless covered by an exi	sting bond on file (see		
 A Drilling Plan A Surface Use Plan (if the location is on National Forest Syster 	m Lands the	Item 20 above 5. Operator Certi					
SUPO shall be filed with the appropriate Forest Service Office	•			ormation and/or plans as m	ay be required by the		
		authorized offi	icer.				
25. Signature	Name (P	rinted/Typed)			Date		
Zero Farin	Zeno	Zeno Farris			04.03.07		
Title							
Manager Operations Administration							
Approved By (Signature)	Name (P	rinted/Typed)		***	Date		
	ļ	/s/ James	Stoval	1			
Title FIELD MANAGER	Office		310141		MAY 0 4 2007		
	C	ARLSBAD F	TELD C	DFFICE			
Application approval does not warrant or certify that the applicant holds leg conduct operations thereon.	gal or equitable title t	o those rights in the subje	ct lease which	would entitle the applicant to	DIVEAD		
conduct operations thereon. Conditions of approval, if any, are attached.			A	YYKUVAL TU	KIIDAN		
Title 18 U.S.S. Section 1001 and Title 43 U.S.C. Section 1212, make it a cri	ime for any person k	nowingly and willfully to	make to any d	epartment or agency of the Un	ited		

States any false, fictitious, or fraudulent statements or representations as to any matter within its jurisdiction.

* (Instructions on page 2) SEE ATTACHED FOR CONDITIONS OF APPROVAL

APPROVAL SUBJECT TO GENERAL REQUIREMENTS AND SPECIAL STIPULATIONS **ATTACHED**

Roswell Controlled Water Basin

Form 3160-5 (November 1994)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT OCD-ARTESIA

FORM APPROVED OMB No. 1004-0135 Expires July 31, 1996

Lease Serial No.

LC-028784-C

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

If Indian, Allottee or Tribe Name

		, ,		7. If Unit or CA	V/Agreement, Name and/or No.		
SUBMIT IN TRIF	LICATE - Other instructions	on reverse side					
1. Type of Well					Grayburg Deep Unit		
	Other			8. Well Name and No.			
Name of Operator Cimarex Energy Co. of Colorad				9. API Well No	ep Unit No. 22		
3a. Address	<u> </u>	3b. Phone No. (include	area code)	30-015-	<i>.</i> .		
PO Box 140907; Irving, TX 750)14-0907	972-401-3111	a, ou 5000)		ool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M.,	or Survey Description)	<u> </u>		Wolfcamp W	ildcat		
1940' FNL & 330' FEL				11. County or Parish, State			
25-17S-29E				Eddy County,			
	ROPRIATE BOX(ES) TO			, REPORT, OF	ROTHER DATA		
TYPE OF SUBMISSION		IYP	E OF ACTION	,			
X Notice of Intent	Acidize	Deepen	Production (Start/F	Resume)	Water Shut-Off		
	Alter Casing	Fracture Treat	Reclamation		Well Integrity		
Subsequent Report	Casing Repair	New Construction	Recomplete		Other		
	X Change Plans	Plug and Abandon	Temporarily Aband	don			
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal				
Due to arc in the area, Cimarex FEL. Please see attached revisor		cation for this well <u>F</u>	ROM 1650' FNI	∠ & 750' FWL]	<u>ro</u> 1940' FNL & 330'		
14. I hereby certify that the foregoing is true an Name (<i>Printed/Typed</i>)	d correct	Title					
Natalie Krueger		Reg Analyst	1				
Signature Date							
(Natali Sine	gr	April 16, 200)7				
	THIS SPACE FOR	FEDERAL OR STATE					
Approved by	nes Stovan		FIELD MA	NAGER	Date		
Conditions of Approval, if any, are attached certify that the applicant holds legal or equit which would entitle the applicant to conduct	Approval of this notice does not wable title to those rights in the subje operations thereon.	ct lease			J OFFICE		
Title 18 U.S.C. Section 1001, makes it a crir	ne for any person knowingly and wi	ilifully to make to any depar	tment or agency of th	e United States any	false fictitious or		

fraudulent statements or representations as to any matter within its jurisdiction.

DISTRICT I 1625 N. French Dr., Hobbs, NM 58240 DISTRICT II 1301 W. Grand Avenue, Artesia, NM 65210

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-102 Ravised October 12, 2005

Submit to Appropriate District Office

State Lease - 4 Copies Fee Lease - 3 Copies

1000 Rio Brazos Rd., Aztec, NM 87410

DISTRICT IV 1220 S. St. Francis Br., Santa Fe, HM 87506

N


OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, New Mexico 87505


☐ AMENDED REPORT

WELL LOCATION AND ACREAGE DEDICATION PLAT

API	Number	ſ	\sim	Pool Code			Pool Name		
			C	1601	Loca	Hills; We	elframp"	NE-	
Property	Code				Property Next	10		Well Number	
		GRAYBURG DEEP UNIT				22	22		
OGRID N			Operator Name				Elevat	Elevation	
1626	83		CIM	AREX E	NERGY CO.	OF COLORADO)	358	4'
					Surface Loc	ation			
UL or lot No.	Section	Township	Range	Lot idn	Feet from the	North/South line	Feet from the	East/West line	County
Ε	25	17 S	29 E		1940	NORTH	330	WEST	EDDY
			Bottom	Hole Lo	cation If Diffe	erent From Sur	face		
UL or lot No.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County
		<u> </u>							
Dedicated Acre	s Joint	or Infill Co	nsolidation	Code Or	der No.				-

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED







Specification Sheet Choke & Kill Hose

The Midwest Hose & Specialty Choke & Kill hose is manufactured with only premium componets. The reinforcement cables, inner liner and cover are made of the highest quality material to handle the tough drilling applications of today's industry. The end connections are available with API flanges, API male threads, hubs, hammer unions or other special fittings upon request. Hose assembly is manufactured to API 7K. This assembly is wrapped with fire resistant vermculite coated fiberglass insulation, rated at 2000 degrees with stainless steel armor cover.

Working Pressure:

5,000 or 10,000 psi working pressure

Test Pressure:

10,000 or 15,000 psi test pressure

Reinforcement:

Multiple steel cables

Cover:

Stainless Steel Armor

inner Tube:

Petroleum resistant, Abrasion resistant

End Fitting:

API flanges, API male threads, threaded or butt weld hammer

unions, unibolt and other special connections


Maximum Length:

110 Feet

ID:

2-1/2", 3", 3-1/2". 4"

Operating Temperature: -22 deg F to +180 deg F (-30 deg C to +82 deg C)



ORLLING OPERATIONS CHOKE MANIPOLD 5M SERVICE




Exhibit E-1 – Choke Manifold Grayburg Deep Unit No. 22 Cimarex Energy Co. of Colorado 25-17S-29E 1940' FNL & 330' FEL Eddy County, NM

Application to Drill

In response to questions asked under Section II B of Bulletin NTL-6 the following information is provided for your consideration:

1 Location:

1940, N & 330, M

2 Elevation above sea level:

3589' GR

3 Geologic name of surface formation:

Quaternery Alluvium Deposits

4 Drilling tools and associated equipment:

Conventional rotary drilling rig using fluid as a circulating medium for solids removal.

5 Proposed drilling depth:

9400'

6 Estimated tops of geological markers:

San Andres 2600' Yeso 4100' Wolfcamp 7500' Lower Wolfcamp 9100'

7 Possible mineral bearing formation:

Wolfcamp

oil

8 Casing program:

Hole Size	Interval	Casing OD	Weight	Thread	Collar	Grade
17-1/2"	0-350' to 500'	13-3/8"	48	8-R	ST&C	H-40
12-1/4"	0-4700'	9-5/8"	40	8-R	LT&C	J-55
8-3/4"	0-9400'	5-1/2"	17	8-R	LT&C	P-110

Application to Drill

9 Cementing & Setting Depth:

13-3/8"	Surface	Set 350' - 500'* of 13-3/8" H-40 48 # ST&C casing. Cement with 500 sx Class C cement + additives, circulate cement to surface.
9-5/8"	Intermediate	Set 4700' of 9-5/8" J-55 40# LT&C casing. Cement with 1700 sx POZ/C + additives, circulate cement to surface.
5-1/2"	Production	Set 9400' of 5-1/2" P-110 17# LT&C casing. Cement with 1460 sx Super H + additives. TOC 8600.'
		*Set surface casing 25' into the top of the Rustler, which is estimated to be between 350' and 500'.

10 Pressure control Equipment:

Exhibit "E". A 13 3/8" 5000 PSI working pressure B.O.P. consisting of one set of blind rams and one set of pipe rams and a 5000 # annular type preventer. A choke manifold and 120 gallon accumulator with floor and remote operating stations and auxiliary power system. Rotating head below 6000'. A kelly cock will be installed and maintained in operable condition and a drill string safety valve in the open position will be available on the rig floor. BOP unit will be hydraulically operated. BOP will be nippled up on the 9 5/8" casing and will be operated at least once a day while drilling and the blind rams will be operated when out of hole during trips. No abnormal pressure or temperature is expected while drilling. From the base of the surface pipe through the running of production casing, the well will be equipped with a 500 psi BOP system.

We are requesting a variance for the 13-3/8" surface casing and BOP testing from Onshore Order No. 2, which states that all casing strings below the conductor shall be pressure tested to 0.22 psi per foot or 1500 psi, whichever is greater, but not to exceed 70% of the manufacturer's stated maximum internal yield. We are requesting a variance to test the 13-3/8" casing to 1000 psi using rig pumps. The BOP will be tested to 5000 PSI by an independent service company.

11 Proposed Mud Circulating System:

	Depth	Mud Wt	Viscosity	Fluid Loss	Type Mud
	0 - 500'	8.4 - 8.6	30 - 32	May lose circ.	Fresh water spud mud. Add paper to control seepage and high viscosity sweeps to clean hole.
z	500' - 4700'	9.7 - 10.0	28 - 29	May lose circ.	Brine water. Add paper as needed to control seepage and add lime to control pH (9-10). Use high viscosity sweeps to clean hole.
	4700' - 9400'	8.4 - 10.0	28 - 29	NC	Brine water. Paper for seepage. Lime for PH (9 - 9.5).

Sufficient mud materials will be kept on location at all times in order to combat lost circulation, or unexpected kicks. In order to run DSTs, open hole logs, and casing, the viscosity and water loss may have to be adjusted in order to meet these needs. Mud system monitoring equipment with derrick floor indicators and visual/audio alarms shall be installed and operative prior to drilling into the Wolfcamp formation. This equipment will remain in use until production casing is run and cemented.

Application to Drill

12 <u>Testing, Logging and Coring Program:</u>

- A. Mud logging program: Two-man unit from 4700' to TD
- B. Electric logging program: CNL/LDT/CAL/GR, DLL/CAL/GR
- C. No DSTs or cores are planned at this time.

13 Potential Hazards:

No abnormal pressures or temperatures are expected. The area has a potiential H2S hazard. An H2S drilling plan is attached. Adequate flare lines will be installed off the mud / gas separator where gas may be flared safely. All personnel will be familiar with all aspects of safe operation of equipment being used. Estimated BHP 4000 PSI, estimated BHT 175.

14 Anticipated Starting Date and Duration of Operations:

Road and location construction will begin after BLM approval of APD. Anticipated spud date as soon as approved. Drilling expected to take <u>35-45</u> days. If production casing is run an additional 30 days will be required to complete and construct surface facilities.

15 Other Facets of Operations:

After running casing, cased hole gamma ray neutron collar logs will be run from total depth over possible pay intervals. The <u>Wolfcamp</u> pay will be perforated and stimulated. The well will be tested and potentialed as a gas well.

Hydrogen Sulfide Drilling Operations Plan

- 1 All Company and Contract personnel admitted on location must be trained by a qualified H2S safety instructor to the following:
 - A. Characteristics of H2S
 - B. Physical effects and hazards
 - C. Proper use of safety equipment and life support systems.
 - D. Principle and operation of H2S detectors, warning system and briefing areas.
 - E. Evacuation procedure, routes and first aid.
 - F. Proper use of 30 minute pressure demand air pack.
- 2 H2S Detection and Alarm Systems
 - A. H2S detectors and audio alarm system to be located at bell nipple, end of flow line (mud pit) and on derrick floor or doghouse.
- 3 Windsock and/or wind streamers
 - A. Windsock at mudpit area should be high enough to be visible.
 - B. Windsock at briefing area should be high enough to be visible.
- 4 Condition Flags and Signs
 - A. Warning sign on access road to location.
 - B. Flags to be displayed on sign at entrance to location. Green flag indicates normal safe condition. Yellow flag indicates potential pressure and danger. Red flag indicates danger (H2S present in dangerous concentration). Only emergency personnel admitted to location.
- 5 Well control equipment
 - A. See exhibit "E"
- 6 Communication
 - A. While working under masks chalkboards will be used for communication.
 - B. Hand signals will be used where chalk board is inappropriate.
 - C. Two way radio will be used to communicate off location in case of emergency help is required. In most cases cellular telephones will be available at most drilling foreman's trailer or living quarters.
- 7 Drillstem Testing not anticipated.

A DST is planned for 9100' - 9250.'

Hydrogen Sulfide Drilling Operations Plan

	i
8	Drilling contractor supervisor will be required to be familiar with the effects H2S has on tubular goods and other mechanical equipment.
9	If H2S is encountered, mud system will be altered if necessary to maintain control of formation. A mud gas seperator will be brought into service along with H2S scavengers if necessary.

Surface Use Plan

- 1 Existing Roads: Area maps, Exhibit "B" is a reproduction of Lea Co. General Highway Map. Exhibit "C" is a reproduction of a USGS Topographic Map, showing existing roads and proposed roads. All existing roads will be maintained in a condition equal to or better than current conditions. Any new roads will be constructed to BLM specifications.
 - A. Exhibit "A" shows the proposed well site as staked.
 - B. From mile marker 129 on US Hwy 82, go West 0.3 miles to lease road. On lease road, go South 0.8 miles to lease road. Thence East on lease road to proposed location.
- 2 PLANNED ACCESS ROADS: No access roads will be constructed.
- 3 LOCATION OF EXISTING WELLS IN A ONE-MILE RADIUS EXHIBIT "A"

A. Water wells -

None known

B. Disposal wells -

None known

C. Drilling wells -

None known

D. Producing wells -

As shown on Exhibit "A"

E. Abandoned wells -

As shown on Exhibit "A"

CONDITIONS OF APPROVAL - DRILLING

Operator's Name:

Cimarex Energy Co. of Colorado

Well Name & No.

22-Grayburg Deep Unit

Location:

1940FNL, 0330FWL, Sec. 25, T-17-S, R-29-E, Eddy County, NM

Lease:

LC-028784-C

I. DRILLING OPERATIONS REQUIREMENTS:

- A. The Bureau of Land Management (BLM) is to be notified a minimum of 4 hours in advance for a representative to witness:
 - 1. Spudding well
 - 2. Setting and/or Cementing of all casing strings
 - 3. BOPE tests
 - Eddy County call the Carlsbad Field Office, 620 East Greene St., Carlsbad, NM 88220, (505) 361-2822
- B. Although Hydrogen Sulfide has not been reported in this section, it has been reported numerous times in the Township to the East. The operator has attached a hydrogen sulfide drilling plan to the APD.
- C. Unless the production casing has been run and cemented or the well has been properly plugged, the drilling rig shall not be removed from over the hole without prior approval.
- **D.** If floor controls are required, (3M or Greater) controls will be on the rig floor, unobstructed, readily accessible to the driller and will be operational at all times during drilling and/or completion activities. Rig floor is defined as the area immediately around the rotary table; the area immediately above the substructure on which the draw works are located, this does not include the dog house or stairway area.

II. CASING:

- A. The 13-3/8 inch surface casing shall be set a minimum of 25 feet into the Rustler Anhydrite between 350-500 feet and cemented to the surface.
 - 1. If cement does not circulate to the surface, the appropriate BLM office shall be notified and a temperature survey utilizing an electronic type temperature survey with a surface log readout will be used or a cement bond log shall be run to verify the top of the cement.
 - 2. Wait on cement (WOC) time for a primary cement job will be a minimum of 12 hours for a non-water basin, 18 hours for a water basin, 24 hours in the potash area, or 500 pounds compression strength, whichever is greater. (This is to include the lead cement)
 - 3. Wait on cement (WOC) time for a remedial job will be a minimum of 4 hours after bringing cement to surface or 500 pounds compression strength, whichever is greater.
 - 4. If cement falls back, remedial action will be done prior to drilling out that string.

Possible lost circulation in the Grayburg and San Andres formations. Possible water flows in the Salado and Artesia Groups. Possibility of high pressure gas bursts from the Wolfcamp.

- B. The minimum required fill of cement behind the <u>9-5/8</u> inch intermediate casing is cement to circulate to surface. If cement does not circulate see A.1 thru 4.
- C. The minimum required fill of cement behind the <u>5-1/2</u> inch production casing is cement is to extend a minimum of 200' inside the intermediate casing.
- **D.** If hardband drill pipe is rotated inside casing; returns will be monitored for metal. If metal is found in samples, drill pipe will be pulled and rubber protectors which have a larger diameter than the tool joints of the drill pipe will be installed prior to continuing drilling operations.

III. PRESSURE CONTROL:

- A. All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53. Check condition of 4 1/16" flexible line from BOP to BOPE, replace if exterior is damaged or if line fails test. Line to be as straight as possible. Sundry requesting variance for flex line attached to APD.
- **B.** Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be **2000 (2M)** PSI.
- C. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the <u>9-5/8 inch</u> intermediate casing shoe shall be 3000 (3M) PSI.
- **D.** The appropriate BLM office shall be notified a minimum of 4 hours in advance for a representative to witness the tests.
 - 1. The tests shall be done by an independent service company.
 - 2. The results of the test shall be reported to the appropriate BLM office.
 - 3. All tests are required to be recorded on a calibrated test chart. A copy of the BOP/BOPE test chart and a copy of independent service company test will be submitted to the appropriate BLM office.
 - 4. The BOP/BOPE test shall include a low pressure test from 250 to 300 psi in accordance with API RP 53. The test will be held for a minimum of 10 minutes if test is done with a test plug and 30 minutes without a test plug.
 - 5. BOP/BOPE must be tested by an independent service company within 500 feet of the top of the <u>Wolfcamp</u> formation. This test does not exclude the test prior to drilling out the casing shoe as per Onshore Order No. 2.
 - 6. A variance to test the **surface casing** to the reduced pressure of <u>1000</u> psi with the rig pumps is approved.

IV. DRILLING MUD:

Mud system monitoring equipment, with derrick floor indicators and visual and audio alarms, shall be operating before drilling into the <u>Wolfcamp</u> formation, and shall be used until production casing is run and cemented.

Engineer on call phone: 505-706-2779

WWI 042407