

Submit 3 Copies  
to Appropriate  
District Office

Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P. O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P. O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P. O. Box 2088  
Santa Fe, New Mexico 87504-2088

Month - Year  
APR 30 2007  
OCCD - ARTESIA, NM

WELL API NO. 30-015-277
5. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
6. State Oil & Gas Lease No. V-3479
7. Lease Name or Unit Agreement Name  PINNACLE STATE #13
8. Well No. V-3479
9. Pool Name or Wildcat Herradura Bend, Delaware

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator: RKI Exploration and Production LLC
3. Address of Operator: 3817 N.W. Expressway, Suite 950, Oklahoma City, OK. 73112	4. Well Location Unit Letter <u>0</u> : <u>330'</u> Feet From The <u>South</u> Line and <u>2310'</u> Feet From The <u>East</u> Line Section <u>36</u> Township <u>22S</u> Range <u>28E</u> NMPM <u>EDDY</u> County

10. Elevation (Show whether DF, RKB, RT, GR, ect.)  
3095' RKB

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work (SEE RULE 1103).  
ADD ADDITIONAL DELAWARE ZONE

Work commenced on 3-13-07. Pulled rods & insert pump. Pulled tubing, pump barrel & equipment. Set composite frac plug @ 6125'. Pressure tested casing & plug to 2000# - good. Perforated Delaware zone 5964'-5984' & 6008'-6020'.  
Acidized with 2000 gals. 10% HCL acid. Frac'd at 30 bpm with 71,379 gals. brine water, 14,000 lbs. 14/30 LiteProp 125, & 4000 lbs. 14/30 LiteProp 125C, and 1000 lbs. 20/40 sand. Drilled out frac plug @ 6125' and cleaned out to 6316'. Installed tubing, rod pump, and tubing.

Placed well on production.

Work completed on 4-6-07.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Gene Simer TITLE Superintendent DATE 4/27/07

TYPED OR PRINT NAME Gene Simer TELEPHONE NO. 505-885-1313

(This space for State Use)

APPROVED BY DENIED TITLE Re Submit on current Forms DATE JUN 05 2007

CONDITIONS OF APPROVAL, IF ANY: