



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop
Cabinet Secretary

September 8, 2003

Lori Wrotenbery


Director

Oil Conservation Division

Marbob Energy Corporation
P.O. Box 227
Artesia, New Mexico 88211-0227

Attn: Mr. Brian Collins

**RE: Injection Pressure Increase
Burch-Keely Cooperative Waterflood Project
Eddy County, New Mexico**



Dear Mr. Collins:

Reference is made to your request dated July 25, 2003, to increase the surface injection pressure on ten injection wells within the Burch-Keely Cooperative Waterflood Project, Grayburg-Jackson Pool, Eddy County, New Mexico. This request is based on step rate test data previously obtained within the project area. The data has been reviewed by my staff and we feel an increase in injection pressure on these wells is justified at this time.


You are therefore authorized to increase the surface injection pressure on the following wells:

WELL NAME & NUMBER	MAXIMUM SURFACE INJECTION PRESSURE
Burch Keely Unit No. 95, Unit J, Section 19, T-17S, R-30E API No. 30-015-04204	900 psi
Burch Keely Unit No. 97, Unit I, Section 19, T-17S, R-30E API No. 30-015-04209	900 psi
Burch Keely Unit No. 104, Unit N, Section 19, T-17S, R-30E API No. 30-015-04210	900 psi
Burch Keely Unit No. 102, Unit O, Section 19, T-17S, R-30E API No. 30-015-04212	900 psi
Burch Keely Unit No. 100, Unit P, Section 19, T-17S, R-30E API No. 30-015-04213	900 psi
Burch Keely Unit No. 101, Unit O, Section 19, T-17S, R-30E API No. 30-015-20794	900 psi

WELL NAME & NUMBER	MAXIMUM SURFACE INJECTION PRESSURE
Burch Keely Unit No. 98, Unit I, Section 19, T-17S, R-30E API No. 30-015-21366	900 psi
Burch Keely Unit No. 94, Unit K, Section 19, T-17S, R-30E API No. 30-015-22092	900 psi
Burch Keely Unit No. 142, Lot 1, Section 30, T-17S, R-30E API No. 30-015-04388	900 psi
Burch Keely Unit No. 146, Unit B, Section 30, T-17S, R-30E API No. 30-015-04394	900 psi

The Division Director may rescind this injection pressure increase if it becomes apparent that the injected fluid is not being confined to the injection zone or is endangering any fresh water aquifers.

Sincerely,



Lori Wrotenberg
Director

LW/DRC

cc: Oil Conservation Division - Artesia
Files: WFX-682, WFX-555, WFX-743
IP-207