

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APPROVED  
OMB NO 1004-0137  
Expires March 31, 2007

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

## 1 Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

AUG 02 2007

## 2 Name of Operator

Forest Oil Corporation

OCD-ARTESIA

## 3a. Address

707 17th Street, Suite 3600 Denver, CO 80202

## 3b Phone No (include area code)

303-812-1554

## 4 Location of Well (Footage, Sec., T., R., M., or Survey Description)

K, 1980' FSL & 1980 FWL  
Sec. 1, T23S, R31E

## 5 Lease Serial No

NM22080

## 6. If Indian, Allottee or Tribe Name

## 7 If Unit or CA/Agreement, Name and/or No

## 8 Well Name and No

Barclay Federal 10

## 9 API Well No.

30-015-30239

## 10 Field and Pool, or Exploratory Area

Livingston Ridge Delaware

## 11. County or Parish, State

Eddy NM

## 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

## TYPE OF SUBMISSION

☐ Notice of Intent☒ Subsequent Report☐ Final Abandonment Notice

## TYPE OF ACTION

☐ Acidize☐ Deepen☐ Production (Start/Resume)☐ Water Shut-Off☐ Alter Casing☐ Fracture Treat☐ Reclamation☐ Well Integrity☐ Casing Repair☐ New Construction☐ Recomplete☒ Other☐ Change Plans☐ Plug and Abandon☐ Temporarily AbandonRod Repair☐ Convert to Injection☐ Plug Back☐ Water Disposal

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

3-29-2007

RU PU bled well down, unhung well head, POH rods the 14 F.G. body break. Unseat Tac POH 18 jts 2 7/8 tbg, start POH rods, on the 34 F.G. rod was cracked, lay down, POH rest of rods & Pmp. RBLH tbg set TAC flange WH run happy tools twice to 3500' & run 1 time swab cups put back tbg valve. SI Well.

3-30-07

Pick up new Pmp, RIH w/rods, hung well head RU hot oiler, load tbg w/32 bbls wtr. Press to 500# psi hold good. RD hot oiler, RD PU Clean location. Turn Unit on, but had to S.I Unit, bad wrist pin. MO location

ACCEPTED FOR RECORD

JUL 28 2007

BUREAU OF LAND MANAGEMENT  
CARLSBAD FIELD OFFICE14 I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

Cindy Bush

## Title

Sr. Regulatory Tech

## Signature

Date 5-2-07

## THIS SPACE FOR FEDERAL OR STATE OFFICE USE

## Approved by

## Title

## Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

## Office

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Accepted for record - NMOCD

8/3/07