Form 3160-5 (August 1999)

applicant to conduct operations thereon.

or fraudulent statements or representations as to any matter within its jurisdiction

UNITED STATES
DEPARTMENT OF THE INTERIOR N.M. DIV-Dist. 2
BUREAU OF LAND MANAGEMEN 301 W. Grand Avenue
SUNDRY NOTICES AND REPORTS ON WARTESIA, NM 88210

Department of the interior of the int

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				NM-100831
				6. If Indian, Allottee or Tribe Name
				N/A
	<u></u>			7. If Unit or CA/Agreement, Name and/or No.
SU	BMIT IN TRIPLICATE - (	Other Instructions on rev	rerse side , r	
Type of Well	-		Injection 70	8. Well Name and No.
Oil Well	X Gas Well	Other	Injection	BAT ARO FEDERAL #1
2. Name of Operator	:	\g	Op # 6\	9. API Well No.
Yates Petroleum Co	rporation	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	00 Pr 300 00	30-015-25874
3a Address		3b. Phone No. (include	area obde) Co	10. Field and Pool, or Exploratory Area
105 S. 4th Street - A		505-748-1471	Apr (50 55)	
4. Location of Well (Footage, Sec	c., T.,R., M., or Survey Desci	ription)	5/2 5	CROOKED CREEK UPPER PENN
00401 5411 0 0001 51411		\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	25 25 25 25 25 25 25 25 25 25 25 25 25 2	11. County or Parish, State
2210' FNL & 660' FWL	Section 34-T2	23S-R24E	E>2717076	EDDY COUNTY, NM
42 CHECK ADD	DODDIATE BOY/ES) TO	INDICATE MATURE OF	NOTICE, REPORT, OR OTHER DA	
TYPE OF SUBMISSION	ROPRIATE BOX(ES) TO	INDICATE NATURE OF	TYPE OF ACTION	NA .
				Water Shut-Off
X Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off
Subsequent Report	Alter Casing	Fracture Treat	Reclamation	Well Integrity
Final Abandonment Notice	Casing Repair	New Construction	Recomplete	Other
	Change Plans	X Plug and Abandon	Temporarily Abandon	
	Change Plans	A Plug and Abandon		
	Convert to Injection	Plug Back	Water Disposal	
reclamation, have been completed CALL BLM WITH 24 HOL 1. MIRU WSU; ND wellhed set @ 7919' w/ a left han 2. MIRU WL, set CIBP @ 3. Tally tubing & TIH opeclean out tubing. POH. 4. TIH open ended to 26' will leave a plug across to 5. TIH open ended to 45' This will leave a plug acr	d, and the operator has determing UR NOTICE BEFORE Colored, NU BOP; RU all h2s digay & the RBP is @ 82 at 25	ed that the site is ready for final ins OMMENCING OPERATIO  s & safety equipment. No c 45'.  ient. Set a second CIBP @ nole w/ plugging mud & spo g mud & spot 25 sk plug fro hoe. WOC & tag; reset plu mud & spot 25 sk plug fro hoe. WOC & tag - reset plu mud & spot 15 sk plug fro hoe. WOC & tag - reset plu mud & spot 15 sk plug fro	casing recovery will be attempted. Fig. 7986' & cap w/ 35' cement. This soft 25 sk plug from 5220'-5420'. Pull om 2450'-2650'. Pull 5 stands & revig if necessary.	POH w/ tubing & packer - packer is eals off Strawn & Cisco perfs. 5 stands & reverse circ to rerse circ to clean tubing. POH. This se circ to clean out tubing. POH.
I hereby certify that the foregoing Name (Printed/Typed)  Donna Clack  Signature		& Japan Octo	Title Operations Technician Date 10-03-03	APPROVED
THIS SPACE FOR FEDERAL OR STATE OFFICE USE 0CT 9 2003				
INIO SPACE FOR PEDERAL OR STATE OF THE USE				
Approved by	Epied Re.		Title	Date
Conditions of approval if any or	e attached concording this set	ice does not warrant or certify that	Office	LES BABYAK PETROLEUM ENGINEER
approval, il ally, al	under this danis min min mor	iss associate manifest or centry that	10000	FEIROLLOW LIVERY

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious



