

District I  
1625 N French Dr, Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505



State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

OCT 02 2007

OCD-ARTESIA

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

30-015-30743

OPERATOR

Initial Report

X Final Report

Name of Company Chevron USA	Contact Larry Ridenour
Address HCR 60 Box 423 Lovington, N.M. 88260	Telephone No. 505-396-4414 X 102
Facility Name TexMack 36 State Com #1	Facility Type Production Facility

Surface Owner State of NM	Mineral Owner State of NM	Lease No.
---------------------------	---------------------------	-----------

LOCATION OF RELEASE

Unit Letter C	Section 36	Township 16S	Range 31E	Feet from the 1143	North Line	Feet from the 1980	West Line	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	------------	-----------------------	-----------	----------------

Latitude 32.8822957392 Longitude 103.825326449

NATURE OF RELEASE API #30-015-30743

Type of Release Fire	Volume of Release ??	Volume Recovered NA
Source of Release Water tank	Date and Hour of Occurrence 09/30/07 AM	Date and Hour of Discovery 09/30/07 11:15 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Tejay Simpson	Date and Hour 9/30/2007 11:55 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Lightning storm early AM on Sept 30, 2007. Lightning apparently lit the gas vapors from vent line on the water tank resulting in a small flame. Maljamar Fire Department was called upon discovery and had the flame extinguished shortly after arrival. There was no damage to any equipment.

Describe Area Affected and Cleanup Action Taken.\*

NA

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Larry D. Ridenour	Approved by District Supervisor:	
Title: Operations Representative	Approval Date: OCT 4 2007	Expiration Date:
E-mail Address: LRidenour1@chevron.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/01/2007	Phone: 396-4414 X 102	

\* Attach Additional Sheets If Necessary