Form 3160-5 (February 2005)

UNITED STATES UNITED

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: March 31, 2007

Expires: March : 5. Lease Serial No.

NM-074935 6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

abanaonea wen.	00010111101000	b) 101 cuo p	. + p +				
SUBMIT IN TRIPLICATE - Other instructions on page 2.					7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well				ļ	0 107-1131		
			njection		8. Well Name and No. LOCO Hills A Federal 5		
					9. API Well No. 30-015-20610		
			(ınclude area code)		10. Field and Pool or Exploratory Area		
		432/685-	85-0878		Grayburg Jackson SR QN G SA		
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)			11. Country or Parish, State				
1980' FSL & 660' FWL UL L Sec, 10 T17S R30E					Eddy NM		
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA							
TYPE OF SUBMISSION	ION			TYPE OF ACTION			
Notice of Intent	Acidize	Deepen	<u> </u>		Production (Start/Resume) Water Shut-Off Reclamation Well Integrity		
	Alter Casing Casing Repair	Fracture Tr				Well Integrity	
Subsequent Report					porarily Abandon		
Final Abandonment Notice Convert to Injection		Plug and Al Plug Back	- <u>- </u>		er Disposal		
· · · · · · · · · · · · · · · · · · ·	l					ork and approximate duration thereof. If	
testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) MI&RU Mayo Marrs 10-24-2007. ND wellhead. NU BOP. POH with tubing and packer. RIH with mule shoe, could not get past 540'. Called BLM, BLM okayed plugging well from 540' after pulling casing. Pulled and cut casing. RIH with packer to 270'. Pumped 70 sx cement. WOC. Small flow. Tag @355'. Pump 70 sx cement @355'. WOC. Tag @ 74'. Circulate 60 sx to surface. WOC. Tag @ 20'. POH. Circulate 20 sx cement to surface. Dig out cellar, remove anchors and clean location. Set dry hole marker 10-31-2007. APPROVED AS TO PLUGGING OF THIS WELL BORE. LUBBLITY LUBBLISHED. SCOMPLETED.							
14. I hereby certify that the foregoing is t	rue and correct.						
Name (Printed/Typed) M. A. Sirgo, III			Title Engineer				
Signature L. M. Jugo ID			Date November 1, 2007				
	THIS SPACE	FOR FEDERAL	OR STA	TE OFF	ICE USE		
Approved by /S/DAVID R. GLASS Conditions of approval, if any, are attached. Approval of this notice does not warrant or ce that the applicant holds legal or equitable title to those rights in the subject lease which wo			Title PET	ROLEUN	I ENGINEER	NOV (7 2007	
entitle the applicant to conduct operations			<u> </u>	'110 44			
Title 18 U.S.C. Section 1001 and Title 43	U.S.C. Section 1212, make it	a crime for any person l	cnowingly and	willfully to	make to any departme	ent or agency of the United States any false,	

fictitious or fraudulent statements Or representations as to any matter within its jurisdiction