
## OCD-ARTESIA



## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137

Expures: March 31, 2007

Lease Serial No. LC-068064 6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an-ARIESIA

abandoned well.	Use Form 3160-3 (APD) for s	uch proposals.			
SUBMIT IN TRIPLICATE – Other instructions on page 2.				7. If Unit of CA/Agreement, Name and/or No. NMNM101360X	
1. Type of Well Oil Well Gas V	Injection	8. Well Name and No. North Squar	8. Well Name and No. North Square Lake Unit 127		
2. Name of Operator CBS Operating Corp.			9. API Well No. 30-015-0		
3a. Address P O Box 2236	o. (ınclude area code)	10. Field and Pool or E	10. Field and Pool or Exploratory Area		
		685-0878		Square Lake GB SA	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 3300' FSL & 675' FEL UL H Sec 31		Tl6s R3lE	11. Country or Parish, S Eddy NM		
12. CHEC	CK THE APPROPRIATE BOX(ES) TO IN	DICATE NATURE OF 1	NOTICE, REPORT OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent		epen	Production (Start/Resume) Reclamation	<ul><li> Water Shut-Off</li><li> Well Integrity</li></ul>	
Subsequent Report	Casing Repair New	w Construction	Recomplete	Other	
		g and Abandon	Temporarily Abandon		
Final Abandonment Notice	Convert to Injection Plu	g Back	Water Disposal		
<ul> <li>MI &amp; RU Mayo Mar</li> <li>RIH open ended and</li> <li>RIH and tag plug @</li> <li>RIH and perforate @</li> <li>RIH and spot 35 sx c</li> <li>RIH and tag @ 1050 60 sx cement. POH.</li> <li>RIH and tag @ 319'.</li> <li>RIH and tag @ 319'.</li> <li>55 sx cement, no circ WOC. No tag. Pump</li> <li>Tag @ 91'. RIH and and circulate 40 sx cement.</li> </ul>	rs 10-16-2007. TOH with injection spot 35 sx cement @ 3091'. WOC 2619'. Plug okay per BLM. 1410'. POH. RIH and circulate howement @ 1498'. WOC. SDFN. '. RIH and perforate @ 600'. RIH WOC Pump another 50 sx cement. WOC RIH and perforate @ 60'. POH. Rigulation. WOC. No tag. Pump 40 sx 20 40 sx cement with LCM WOC. Sperforate @ 91' Nipple down BOF ement to surface. Dig out cellar. Rean and level location. Well plugged.	n tubing and packer. SDFN.  Sole with plugging much with packer and pum C. SDFN.  H with packer. Pump coment with LCM. SDFN.  Nipple up wellhead emove anchors. Instal	d ap	epted for record NMOCD	
Name (Printed/Typed) M.A. Sirgo, III	I N	Tide Engine	eer		
Signature . A	· Jugo 19		er 26, 2007		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Conditions of approval, if any, are attached.	PR. GLASS Approval of this notice does not warrant or o	Title pertify	EUM ENGINEER Dat	NOV 0 1 2007	
that the applicant holds legal or equitable tit. entitle the applicant to conduct operations th	le to those rights in the subject lease which we tereon.	ould Office			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction