• Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR

I	FORM APPROVE
İ	OMB NO. 1004-01
D-ARTESIA_	Expires March 31, 20

ED 137

BUREAU OF LAND MANAGEME	ENT OCD-AKI	5. Lease Serial No
SUNDRY NOTICES AND REPORTS O	ON WELLS	3. Boase Serial No
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.		6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions	on reverse side	7. If Unit or CA/Agreement, Name and/or No
1. Type of Well X Oil Well Gas Well Other	JAN -8 2008	8. Well Name and No.
2. Name of Operator	OCD-ARTESIA	BAXTER "B" FEDERAL #1
MACK ENERGY CORP. 3a. Address	3b. Phone No (include area code)	9. API Well No. 30-015-04876
P.O. BOX 960, Artesia, NM 88210		10. Field and Pool, or Exploratory Area
4 Location of Well (Footage, Sec., T., R., M., or Survey Description) U-P SEC. 25 TOWNSHIP 16S, RANGE 31 E, 560' FROM THE		
660' FROM THE EAST/WEST LINE	s ream/somming,	11. County or Parish, State
		EDDY COUNTY NM
12. CHECK APPROPRIATE BOX(ES) TO IND	DICATE NATURE OF NOTICE, R	EPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Deepen Produ	action (Start/Resume) Water Shut-Off
Subsequent Report		mation Well Integrity
Casing Repair		mplete Other
Final Abandonment Notice Change Plans		orarily Abandon
Convert to Injectio Describe Proposed or Completed Operation (clearly state all pertinent details)		r Disposal
If the proposal is to deepen directionally or recomplete horizontally, give su Attach the Bond under which the work will be performed or provide the E following completion of the involved operations. If the operation results in testing has been completed. Final Abandonment Notices shall be filed onl determined that the final site is ready for final inspection.) 11-16-07 MIRU	Bond No. on file with BLM/BIA. Require a multiple completion or recompletion in	red subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once
11-19-07 Set CIBP @3,680'. T.I.H. w/tbg. Tag CIF of CIBP. Calculate T.O.C. @3,434'. Pull		
11-20-07 Tag T.O.C. @2,463'. Perf. @2,100'. Set Slowly loosing pressure. W.O.C. & tag @ test. Perf. @2,000#. P.O.O.H. w/pkr. & & tag @826'. Darrell Carter, N.M. B.L.N	01,832'. Perf. well 01,000' & go in hole. O.E. to 1,050 M. witnesses & o.k. Tag & r	. Pkr. Set @696'. Pressure O'. Spot 25 sx. cmt. W.O.C.
& circulate cmt. to surface 5 X 8 5/8 v		ACCEPTED FOR RECORD
11-21-07 Tag @100'. Fill csg. to surface w/10 sa	x. cmt.	
11-26-07 R.D. M.O. ACCE	NMOCD	JAN 5 2008
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) RANDALL MINEAR	Title P&ASUPV.	BURFAU OF LAND MANAGEMENT
Signature Randall Mines	Date 9-10-07	/
THIS SPACE FOR FED	ERAL OR STATE OFFICE USE	
Approved by	Title	Date
Conditions of approval, if any, are attached. Approval of this notice does not wa	arrant or Office	
certify that the applicant holds legal or equitable title to those rights in the subjection		

which would entitle the applicant to conduct operations thereon.

Title 18 U S C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.