# N.M. Oil-Cons. DIV-Dist. 2 1301 W. Grand Avenue UNITED STATES Artesia NIM 88210

Form 3160-5

FORM APPROVED

		INTERIOR IS, INIVI 002	
	BUREAU OF LAND MAN.  / NOTICES AND REF		5. Lease Serial No. NM NM 115997
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160 - 3 (APD) for such proposals.			6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE- Other instructions on reverse side.			7 If Unit or CA/Agreement, Name and/or No
1. Type of Well Oil Well	✓ Gas Well Other	JAN 28 2008	8. Well Name and No.
2. Name of Operator Parallel Petroleum Corporation		OCD-ARTESIA	Hoss Cartwright 2020-5 Federal #1H  9. API Well No.
3a Address 1004 N. Big Spring St., Suite 400, Midland, Texas 79701		3b. Phone No (include area code) 432/684-3727	30-005-63901
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		432/004-3727	10 Field and Pool, or Exploratory Area Wildcat; Wolfcamp
SL 1598' FSL and 94' FWL, Sec 4, T20S-R20E BHL 1598' FSL and 660' FWL, Sec 5, T20S-R20E			11. County or Parish, State  Chaves, New Mexico
12. CHECK	APPROPRIATE BOX(ES) TO	INDICATE NATURE OF NOTICE, R	EPORT, OR OTHER DATA
TYPE OF SUBMISSION		TYPE OF ACTION	
Notice of Intent	Acidize Alter Casing Casing Repair	Deepen Production (St Fracture Treat Reclamation New Construction Recomplete	art/Resume) Water Shut-Off Well Integrity Other Extension of
Subsequent Report  Final Abandonment Notice	Change Plans	Plug and Abandon Temporarily A	-
Final Abandonment Notice	Convert to Injection	Plug Back Water Disposal	permit
following completion of the testing has been completed determined that the site is rea	involved operations. If the operation Final Abandonment Notices shall be	results in a multiple completion or recompletion filed only after all requirements, including reclans for 2 years.	PPROVED FOR MONTH PERIOR NDING 2-16-10
14. I hereby certify that the for Name (Printed/Typed)	oregoing is true and correct	1	
Deane Durhai	m /	Title Engineer	
Signature Lear	e Kunham	Date	12/17/2007
	THIS SPACE FOR	FEDERAL OR STATE OFFICE	
Approved by	/S/ DAVID D. EVA	INS FOR TITLE FIELD M	ANAGER JAN 2 2 2008
Conditions of approval, if any, a	re attached. Approval of this notice egal or equitable title to those rights		BAD FIELD OFFICE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

which would entitle the applicant to conduct operations thereon.

## PECOS DISTRICT CONDITIONS OF APPROVAL

OPERATOR'S NAME: Parallel Petroleum Corp.

LEASE NO.: | NM115997

WELL NAME & NO.: | Hoss Cartwright 2020-5 Federal #1

SURFACE HOLE FOOTAGE: 1598' FSL & 94' FWL Sec. 4 T20S, R20E

BOTTOM HOLE FOOTAGE | 1598' FSL & 660' FWL

LOCATION: Section 5, T. 20 S., R 20 E., NMPM

COUNTY: | Chavez County, New Mexico

## I. DRILLING

## A. DRILLING OPERATIONS REQUIREMENTS

The BLM is to be notified a minimum of 4 hours in advance for a representative to witness:

- a. Spudding well
- b. Setting and/or Cementing of all casing strings
- c. BOPE tests

## **Eddy County**

Call the Carlsbad Field Office, 620 East Greene St., Carlsbad, NM 88220, (575) 361-2822

- 1. Although Hydrogen Sulfide has not been reported in this section, it is always a possible hazard. Only minor concentrations of H2S have been measured in the area, in three wells producing from the Little Box Canyon Morrow in the Section 7. If Hydrogen Sulfide is encountered, please report measured amounts to the BLM.
- 2. Unless the production casing has been run and cemented or the well has been properly plugged, the drilling rig shall not be removed from over the hole without prior approval.
- 3. Floor controls are required for 3M or Greater systems. These controls will be on the rig floor, unobstructed, readily accessible to the driller and will be operational at all times during drilling and/or completion activities. Rig floor is defined as the area immediately around the rotary table; the area immediately above the substructure on which the draw works are located, this does not include the dog house or stairway area.

#### B. CASING

1. The 8 5/8 inch surface casing shall be set at 1500 feet and cemented to the surface.

#### Possible loss of circulation in the San Andres, Glorieta, and Wolfcamp Formations.

- a. If cement does not circulate to the surface, the appropriate BLM office shall be notified and a temperature survey utilizing an electronic type temperature survey with surface log readout will be used or a cement bond log shall be run to verify the top of the cement.
- b. Wait on cement (WOC) time for a primary cement job will be a minimum 18 hours for a water basin, 24 hours in the potash area, or 500 pounds compressive strength, whichever is greater. (This is to include the lead cement).
- c. Please provide WOC times to inspector for cement slurries.
- d. Wait on cement (WOC) time for a remedial job will be a minimum of 4 hours after bringing cement to surface or 500 pounds compressive strength, whichever is greater.
- e. If cement falls back, remedial action will be done prior to drilling out that string.
- 2. The minimum required fill of cement behind the 5 1/2 inch production casing is:
  - Cement should tie-back at least 200 feet into previous casing string. Operator shall provide method of verification.
  - a. Please provide WOC times to inspector for cement slurries.
- 3. If hardband drill pipe is rotated inside casing, returns will be monitored for metal. If metal is found in samples, drill pipe will be pulled and rubber protectors which have a larger diameter than the tool joints of the drill pipe will be installed prior to continuing drilling operations.

## C. PRESSURE CONTROL

1. All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53 Sec. 17.

- 2. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be 3000 (3M) psi. As submitted in APD.
- 3. The appropriate BLM office shall be notified a minimum of 4 hours in advance for a representative to witness the tests.
  - a. The tests shall be done by an independent service company.
  - b. The results of the test shall be reported to the appropriate BLM office.
  - c. All tests are required to be recorded on a calibrated test chart. A copy of the BOP/BOPE test chart and a copy of independent service company test will be submitted to the appropriate BLM office.
  - d. The BOP/BOPE test shall include a low pressure test from 250 to 300 psi. The test will be held for a minimum of 10 minutes if test is done with a test plug and 30 minutes without a test plug.

## D. DRILL STEM TEST

If drill stem tests are performed, Onshore Order 2.III.D shall be followed.

Engineer on call phone (after hours only): Carlsbad: (575) 706-2779

JDW/1/15/2008 (date)