District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV
1320 S. St. Francis Dr. Santa Fe. NM 87505

## State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. FEB 2 2 2008

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate OCDARTES A District Office in accordance with Rule 116 on back

1220 5 51, 11ai		a PC, 14141 8750	J	Santa Fe, NM 87505					Side of form		
24159	8		Rel	ease Notific	cation and Co	orrective A	ction	<u>, , , , , , , , , , , , , , , , , , , </u>	to the second se		
nseb 0803737626					<b>OPERA</b>	OPERATOR 🖂 In			Final Report		
Name of Company Fairway Resources Operating, LLC					Contact 1	Kenneth Pearce					
Address 538 Silicon Drive, Ste. 101, Southlake, TX 76092					2 Telephone	Telephone No. 817-416-1946					
Facility Nat	me Midni	ght Matador	"A" #4	30.015-01	131 Facility Typ	oe Oil well					
Surface Owner US-BLM Mineral Own					Owner US-BLM	US-BLM Leas			se No. NM LC-055561		
				LOCA	ATION OF RE	LEASE					
Unit Letter B	Section 35	Township 17S	Range 27E	Feet from the 990'	North/South Line North	Feet from the 1,650	East/West Line East	County Eddy			
	<u>i</u>	L.at	itude 32	degrees 47' 42	4" Longi	tude 104 dec	orees 14' 44 9"	1	- <del> </del>		

## NATURE OF RELEASE Volume of Release Unknown Type of Release Oil and produced water Volume Recovered 0 Source of Release wellhead Date and Hour of Occurrence Date and Hour of Discovery Unknown 1/16/08 8:00 a.m. MST Was Immediate Notice Given? If YES, To Whom? ☐ Yes ☐ No ☒ Not Required By Whom? Date and Hour Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. ☐ Yes 🛛 No If a Watercourse was Impacted, Describe Fully.\* Describe Cause of Problem and Remedial Action Taken.\* This is a corrected initial report - A BLM inspection on 1-16-2008 found evidence of old leakage and soil contamination on the north side of the wellhead area and location. No free liquids were found, no current leakage was detected. Describe Area Affected and Cleanup Action Taken.\* The affected area is on well pad and off of the north side. No free liquids were present so no liquids were recovered. Cleanup actions have not begun. A work plan proposal is being prepared for the clean-up of contaminates and will be submitted by March 6, 2008, as per email instructions from Sherry Bonham dated 2-6-2008. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Approved by District Supervisor Gum by SB Printed Name: Kenneth Pearce Approval Date: 2-27-68 Title: Engineer Conditions of Approval: REMEDIATION E-mail Address: kpearce@fairwayresources.com Plan Due ON ORBEFORE 3-6-08 -- 124 Phone: 817-416-1946

Attach Additional Sheets If Necessary **13EB**0&D3739564