MAF

MAR 1.4 2008 UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON Do not use this form for proposals to drill or to abandoned well. Use Form 3160-3 (APD) for such	re-enter an 6, 11 Indian, Allottee or I noe Name
SUBMIT IN TRIPLICATE- Other instructions on re	
Oil Well Gas Well Other Name of Operator McKay Oil Corporation	8. Well Name and No. Terry Federal #4 9. API Well No.
3a. Address PO Box 2014, Roswell, NM 88202-2014 3b. Phonc No. (ii 505-623-4735) 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Unit O, 660FSL, 1780' FEL, SEC13, T6S, R22E	
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	
TYPE OF SUBMISSION TYPE OF ACTION	
□ Notice of Intent □ Acidize □ Deepen □ Alter Casing □ Fracture Treat □ Casing Repair □ New Construct □ Change Plans □ Plug and Abant □ Convert to Injection □ Plug Back	
13. Describe Proposed or Completed Operation (clearly state all pertinent details, including lift the proposal is to deepen directionally or recomplete horizontally, give subsurface to Attach the Bond under which the work will be performed or provide the Bond No. or	ocations and measured and true vertical depths of all pertinent markers and zones.

McKay Oil Corporation brought well back to production on 10-14-06 @ 2:00 p.m.

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Carol Shanks	Title Productin Analyst	
Signature WW Sharles	Date 10/30/06	
ACCEPTED HIS SPACE POR FEDERAL OR STATE OFFICE USE		
Approved by SI DAVID R GLASS Conditions of approval if any, are attached. Approval of this notice does not warra certify that the applicant holds legal or equitable the orthose rights in the subject lewhich would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any States any false fictitious or franchical statements and operations as to any matter (Instructions on page 2) ROLLUM ENGINEER	Production And Keeping Well On Continuous Production Or Plugging Well With An	