(Instructions on page 2)

OCD-ARTESIA

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

FORM APPROVED
OM B No 1004-0137
Expires, March 31, 2007

		•	
-	5	Lease Serial No	
		NMLC028731A	
	6	If Indian, Allottee or Tribe Name	

SUBMIT IN TRIPLICATE- Other instructions on reverse side.					CA/Agreement, Name and/or No.			
1. Type of Well Gas Well Other					ne and No			
					8. Well Name and No. Dodd Federal Unit #85			
2. Name of Operator Marbob Energy Corporation					ll No. 03046			
3a. Address PO Box 227, Artesia, NM 882	3b. Phone No. (include area code) 575-748-3303		10. Field and Pool, or Exploratory Area					
4. Location of Well (Footage, Sec., 7	APR 1 0 2008		Grbg Jackson SR Q Grbg SA					
1650 FSL 330 FEL, Sec. 22-T17S-R29E, Unit I		OCD-ARTESIA		11. County or Parish, State				
			Eddy C	o., NM				
12. CHECK AF	PPROPRIATE BOX(ES) TO	INDICATE NA	TURE OF NOTICE, I	REPORT, OR	OTHER DATA			
TYPE OF SUBMISSION			TYPE OF ACTION					
Notice of Intent	Acidize Alter Casing Casing Repair	Deepen Fracture Treat New Construct	Production (S Reclamation	tart/Resume)	Water Shut-Off Well Integrity Other			
Subsequent Report	Change Plans	Plug and Aband	· ·	bandon				
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposa					
testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Plugged & abandoned as follows: 2/8/08 - POOH w/ rods & tbg. 2/11/08 - Set CIBP @ 2300'. RIH w/ tbg pushed down to 2496'. Circ plugging mud. Spot 40 sx (35') Class C cmt on top of CIBP. WOC. 2/12/08 - RIH & tag @ 2283'. Perf 4 shots @ 780'. Sqz 35 sx Class C cmt. WOC. Tag green cmt. Held 500#. Left shut-in overnight per BLM. 2/13/08 - RIH & tag @ 370'. Perf 4 shots & 370'. Pump 50 sx Class C cmt. WOC. RIH & tag @ 155'. Perf 4 shots & 155'. Circ 30 sx Class C cmt to surface. 2/14/08 - RIH & tag @ 24'. Circ 10 sx Class C to surface. Dig out cellar. Cut off wellhead. Cut off anchors. Install dry hole marker.								
	ACCEPTED FOR RECORD							
APR 1 0 2008								
14. Thereby certify that the foregoing is true and correct Name (Printed/Typed) Diana J. Briggs Gerry Guye, Deputy Field Inspector NMOCD-District II ARTESIA								
1/ //		- 11						
Signature LUU	(assured	Da	te	03/18/2008) F	PTFD FOR RECORD			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved by Conditions of approval, if any, are a certify that the applicant holds legal which would entitle the applicant to	or equitable title to those rights in conduct operations thereon.	n the subject lease	Office Office		APR 8 2008 J. Amas Abadicilangana nagentini			
States any false, ficutious or fraudule	ent statements or representations		ARLSBAD FIELD OFFICE					