Form 3160-5 (April2004)

## UNITEDSTATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORMAPPROVED	
OM B No 1004-0137	
Expires: March 31,	200



## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160 - 3 (APD) for such proposals.

5 Lease Serial No.	
NMLC-069219	
6 If Indian Allottee or Tribe Name	

abandoned well. Use Form 3160-3 (APD) for such propos	ais.
SUBMIT IN TRIPLICATE - Other instructions on reverse s	7 If Unit or CA/Agreement, Name and/or No NMNM-68294X
I Type of Well	
2 Nameof Operator BEPCO, L.P. OCD-ARTE	Big Eddy Unit # 152  9. API Well No.
3a Address         3b PhoneNo (include area           P.O BOX 2760 MIDLAND TX 79702-2760         (432)683-2277	10. Field and Pool, or Exploratory Area
4 Location of Well (Footage, Sec, T, R, M, or Survey Description)	Indian Flats (Morrow)
NESE 1980' FSL, 660' FEL Unit I Sec 26, T21S, R28E Mer NMP	11 County or Parish, State Eddy NM
12. CHECK APPROPRIATE BOX(ES)TO INDICATE NATURE O	OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION					
X Notice of Intent  ☐ Subsequent Report ☐ Γinal Abandonment Notice	Acidize Acidize AlterCasing Casing Repair Change Plans Convert to Injection	Deepen FractureTreat New Construction Plug and Abandon Plug Back	Production (Start/Resume) Reclamation Recomplete Temporarily Abandon Water Disposal	Water Shut-Off Well Integrity Other		

Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof if the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

BEPCO, L.P. RESPECTFULLY REQUESTS APPROVAL OF THE FOLLOWING REMEDIAL CEMENT PROCEDURE:

- 1. RU WL & RUN CBL.
- 2. SHOOT SQUEEZE HOLES IN 5-1/2" PRODUCTION CASING 10' ABOVE TOC BASED ON CBL. (TOC BEHIND 5-1/2" AT 4400' FROM TS). ESTABLISH CIRC ON 9-5/8" X 5-1/2" ANNULUS.
- 3. SET RBP AT ~ 4600". CAP W/SAND. TEST RBP TO 1500 PSI.
- 4. RIH W/CEMENT RETAINTER & SET AT 30' ABOVE CIRC/SQUEEZE PERFS.
- 5 CIRC THRU RETAINER AND CEMENT W/ADEQUATE CMT TO BRING CMT TO 2340' (400' ABOVE 9-5/8" SHOE) PLUS 50 SXS. SQUEEZE TO 1500 PSI.
- 6. DRILL OUT RETAINER & CEMENT.
- 7. TEST SQUEEZE TO 1000 PSI. IF SQUEEZE HOLDS, CIRC CLEAN W/ KCL WATER. IF SQUEEZE DOES NOT HOLD, PREP TO RE-SQUEEZE AS DIRECTED.
- 8. RETRIEVE RBP. RETURN WELL TO PREVIOUS CONDITION.

BEPCO ALSO REQUESTS PERMISSION TO WAIT UNTIL THE MORROW AND ATOKA ZONES HAVE BEEN PERFED AND TESTED, AS REPRESENTED ON THE NOI APPROVED ON APRIL 23, 2008.

14 I hereby certify that the foregoing is true and correct Name (Printed/Typed)  ANN MOORE	Title	PRODUCTION	I CLERK		
Signature am Moore	Date	05/14/2008	Δ	PPROVED	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved by		Title Office		MPAY 1 9 2008	
Title 18 U S C Section 1001 and Title 43 U S C Section 1212, make it a crime for any person knowingly and willfully to make to any department of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction					

(Instructions on page 2)