Form 3160-5

UNITED STATES Form 3160-5 UNITED STATES (February 2005) DEPARTMENT OF THE INTERIOR

FORM APROVED OMB NO. 1004-0135

BUREAU OF LAND MANAGEMENT				EXPIRES: March 30, 2007	
SUNDRY NOTICES AND REPORTS ON WELLS				5. Lease Serial No.	
Do not use this form for proposals to drill or to re-enter an apangoneg weii. Use וועסיב (APU) for such proposals				NM 77046 6. If Indian, Allottee of Tribe Name	
					,
50	BMIT IN TRIPLICATE	JUL 252	UUB	7. Unit or CA Agreen	nent Name and No.
to Tune of Wall College II Co.	- Mall Other	OCD-ART	501A	r. om or or rigroom	Tone Hamb and Ho.
1a. Type of Well 🔽 Oil Well 🔲 Ga	Well Other	A CONTINUED OF		8 Well Name and No).
2. Name of Operator				North Pur	e Gold 8 Federal 3
DEVON ENERGY PRODUCTION COMPANY, LP				9. API Well No.	
3. Address and Telephone No.				30	-015-27610
20 North Broadway, Oklahoma City, OK 73102 405-235-3611				10. Field and Pool, or Exploratory	
				Los Medanos; Delaware	
 Location of Well (Report location clearly and in accordance with Federal requirements)* 1780 FNL 660 FEL H SEC 8 T23S R31E 				11. County or Parish State	
11001112001120				Eddy NM	
	·				
TYPE OS SUBMISSION	APPROPRIATE BOX(s) TO	INDICATE NATURE OF NO	OF ACTION		<u> </u>
THE GO GEDMICOION	[7]				□ Weter Chut Off
☐ Notice of Intent	Acidize Alter Casing	☐ Deepen ☐ Fracture Treat	Reclamati	n (Start/Resume)	☐ Water Shut-Off ☐ Well Integrity
✓ Subsequent Report	Casing Repair	New Construction	Recomple		Other Add Pay
_ ' '	Change Plans Dlug and Ahanden Tempo			rarily Abandon	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Dis	sposal	
13 . Describe Proposed or Completed Operations (C					
deepen directionally or recomplete horizontally, give si the Bond No. on file with BLM/BIA. Required subsequi					
interval, a Form 3160-4 shall be filed once testing has					
determined that the site is ready for final inspection)		•			
7/09/08-7/16/08					
17/09/06-17 10/08					
MIRU PU. ND WH. NU BOP. 1	TOOH w/ 2/3 ita 2 7/8"	tha TAC 3' Blact Sub 8	NO NO	II DII Schlumbo	rgor 2 porf interval 7722
90' @ 1 spf & 120 deg phasing. RD WL. TIH w/ RBP, BC & RBP. Set RBP & load w/ 39 bbls 2% KCL. Test to 2000#. Set pkr @ 7815'. Pump 50 bbls wtr. OWU. RU BJ Services & acidize. Test to 3000#. Pump 5K g 7 1/2% Pentafax 2 w/ Xylene & 85 BS.					
Flush w/ 58 bbls 2% KCL. RD BJ. Rlse RBP & pkr. OWU. TIH w/ Mud jt, SN, 3' Blast Sub, 5 1/2 x 2 7/8" TAC & 243 jts. Tag btm @ 7972'. PBTD @ 8134'.162' of fill. EOT @ 7947.72. ND BOP. Set TAC. NU WH. HWO. LH & test w/ 31 bbls wtr to 500#.					
RDMO. POP.	IIII. EUI @ 1941.12.	ND BOP. SELIAC. NO	J VVM. MVV	O. LIT & lest w/ s	of DDIS WIF to 500#.
RDWO. FOP.					
İ					
					00 0000
			ΙΔ1	CEPTED F	OR RECORD
				UULIILDI	ON NEODIND
	•				
		•	1	JUL 2	2 2008
	1			10	
	ì			Alm	
		*		BUREAU OF LAN	D MANAGEMENT
				CARLSBAD F	
	•		<u> </u>	& AILLOUAU I	ILLO VILIOL
14. Thereby certify that the foregoing is t	rue and correct				
The state of the s			. 44		
Signed Sud Sar	Nam Title			Date	7/16/2008
(This space for Federal or State Office us	e)			,	
Approved by	Title			Date	
Conditions of approval, if any:					

This To U.S.C. Securit 1001, makes it a crime for any person knowingly and willingly to make any department or agency or the officer States any false, ficultions or maddleff statements or representations to any matter