Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

JUL	31	0 :	201	18	
UUL	9	•	LUU	R I	_

FORM APPROVED 35)10

JL	3	0	20UB	OMB NO. 1004-013 Expires: July 31, 20	
-				5	Lease Serial No.

is form for proposals to		Lease Serial No. JARTES AMNM105217 6. If Indian, Allottee	or Tribe Name			
PLICATE - Other instru	ctions on reverse side.	7. If Unit or CA/Agr	reement, Name and/or No			
ner		8. Well Name and No BLUE THUNDE	o R 4 FEDERAL COM 1			
Name of Operator Contact KANICIA CARRILLO COG OPERATING LLC E-Mail: kcarrillo@conchoresources.com						
3a Address 550 WEST TEXAS AVE STE 1300 MIDLAND, TX 79701 3b Phone No (include area code) Ph: 432-685-4332						
., R , M , or Survey Description	n)	11. County or Parish	11. County or Parish, and State			
Sec 4 T19S R31E 810FSL 660FWL EDD						
ROPRIATE BOX(ES) TO	O INDICATE NATURE OF 1	NOTICE, REPORT, OR OTHI	ER DATA			
	ТҮРЕ ОІ	FACTION				
☐ Acidize	Deepen	☐ Production (Start/Resume)	■ Water Shut-Off			
☐ Alter Casing	☐ Fracture Treat	□ Reclamation	■ Well Integrity			
Casing Repair	☐ New Construction	Recomplete	☐ Other			
☐ Change Plans	Plug and Abandon	☐ Temporarily Abandon				
Convert to Injection	□ Plug Back	■ Water Disposal				
Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof if the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)						
5/27/08 MIRU. Ran gauge ring to x-nipple. TOH. Ran 2.313 plug & set x-nipple @ 11,820'. Test plugt o 2000 psi, ok. Test annulus to 2000 psi, ok. Spot 2 sx sand down tbg. 5/28/08 TOH w/201 jts 2-7/8 tbg. Load hole w/ 34 bbls 6% KCI Acid. Perforate wollfcamp 10,160' WLM to 10,214' WLM, 1 JSPF, 55 holes. TIH w/ Arrow set 1x10k pkr w/2.313" x-nipple. w/6' sub. Set with middle rubber @ 10,100' WLM. RDMO 5/29/08 TIH w/ on-off tool, 309 jts 2-7/8 tbg EUE 8rd P-110 tbg, 1x6', 8', 10' - 2-7/8 tgb. Space out pkr. Latch onto pkr. ND BOP. NU wellhead. Test annulus to 2000 psi, ok. Pressure on tbg to 2200 psi, pressure dropped to 12000 psi. Swab well. 5/30/08 Swab well. 6/02/08 Pressure test csg & pkr to 1000 psi. Acidize w/4000 gals NEFE acid. Open well to tank on 48/64" choke. Well flowing. Closed choke to 24/64.						
	is form for proposals to II. Use form 3160-3 (AP) PLICATE - Other instruction Contact: E-Mail: kcarrillo@ 1300 C. R. M. or Survey Description OFWL ROPRIATE BOX(ES) To Acidize Casing Repair Change Plans Convert to Injection eration (clearly state all pertine ally or recomplete horizontally rk will be performed or provided operations. If the operation rebandonment Notices shall be final inspection) g to x-nipple. TOH. Ran 2 o 2000 psi, ok. Spot 2 sx bg. Load hole w/ 34 bbls noles. TIH w/ Arrow set 1: M. RDMO 9 jts 2-7/8 tbg EUE 8rd P-OP. NU wellhead. Test and 100 psi. Swab well.	PLICATE - Other instructions on reverse side. Contact KANICIA CARRILLO E-Mail: kcarrillo@conchoresources.com 3b Phone No (include area code) Ph: 432-685-4332 CR. M. or Survey Description) OFWL ROPRIATE BOX(ES) TO INDICATE NATURE OF N TYPE OF Acidize Deepen Alter Casing Fracture Treat Casing Repair New Construction Change Plans Plug and Abandon Convert to Injection Plug Back eration (clearly state all pertinent details, including estimated starting ally or recomplete horizontally, give subsurface locations and measure kit will be performed or provide the Bond No. on file with BLM/BlA dioperations. If the operation results in a multiple completion or recompletion or recompletion or provide the Bond No. on file with BLM/BlA dioperations. If the operation results in a multiple completion or recompletion or provide the Bond No. on file with BLM/BlA dioperations. If the operation results in a multiple completion or recompletion or provide the Bond No. on file with BLM/BlA dioperations. If the operation results in a multiple completion or recompletion or provide the Bond No. on file with BLM/BlA dioperations. If the operation results in a multiple completion or recompletion or provide the Bond No. on file with BLM/BlA dioperations. If the operation results in a multiple completion or recompletion or reco	is form for proposals to drill or to re-enter an ill. Use form 3160-3 (APD) for such proposals. PLICATE - Other instructions on reverse side. 7. If Unit or CA/Agi			

14 I hereby certify that the	ne foregoing is true and correct. Electronic Submission #61721 verifi For COG OPERATING			
Name (Printed/Typed)	KANICIA CARRILLO	Title	PREPARER	· · · · · · · · · · · · · · · · · · ·
Signature	(Electronic Submission)	Date	07/25/2008	
	THIS SPACE FOR FEDER	AL OR	STATE OFFICE USE	
Approved By		Title		Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office	2	

Title 18 U S C Section 1001 and Title 43 U S C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **