



PHONE (575) 383-2326 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR
MOREXCO, INC.
ATTN: DEEG BECKER
P.O. BOX 51208
MIDLAND, TX 79710
FAX TO: (432) 684-4369

Receiving Date: 06/30/08
Reporting Date: 07/01/08
Project Number: NOT GIVEN
Project Name: SUN STATE
Project Location: NOT GIVEN

Sampling Date: 06/30/08
Sample Type: SOIL
Sample Condition: INTACT
Sample Received By: AB
Analyzed By: CK/HM

30-015-24774

LAB NUMBER SAMPLE ID	GRO (C ₆ -C ₁₀) (mg/kg)	DRO (C ₁₀ -C ₂₈) (mg/kg)	Cr (mg/kg)
ANALYSIS DATE	06/30/08	06/30/08	06/30/08
H15077-1 FLOOR	<10.0	<10.0	<16
H15077-2 WALL COMPOSITE	<10.0	<10.0	32
Quality Control	423	431	500
True Value QC	500	500	500
% Recovery	84.8	86.2	100
Relative Percent Difference	6.5	11.3	<0.1

METHODS: TPH GRO & DRO: EPA SW-846 8015 M; Std. Methods 4500-CrB
*Analyses performed on 1:4 w:v aqueous extracts.

Cheryl D. Keene
Chemist

07/01/08
Date

H15077TCL MOREXCO

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.



Page ____ of ____

† Cardinal cannot accept verbal changes. Please fax written changes to 575-393-2476.