Submit 3 Copies To Appropriate District Office	State of New Mexico				Form (
District I	Energy, Minerals and Natural Resources			THE LABORE	Revised March 2	5, 1999	
1625 N. French Dr., Hobbs, NM 88240 District II				WELL API NO.	05400		
811 South First, Artesia, NM 88210	-				30-015-05489 5. Indicate Type of Lease		
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410				STATE			
District IV Santa Fe, NM 87505					Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505					1–1832		
SUNDRY NOTICES AND REPORTS ON WELLS 12				7. Lease Name or Unit Agreement Name:			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A							
PROPOSALS.)	CATION FOR PERMIT (FO	KW C-101) F	OR SUCH O				
1. Type of Well:							
Oil Well Gas Well	Other Plug	& Aband	on Op 3		a te M		
2. Name of Operator Me-Tex Oil & Gas, Inc	8. Well No.						
3. Address of Operator		2	PIESIA CO	9. Pool name or	Wildcat		
P. O. Box 2070 - Hobi	os, NM 88241	/65/5"	, GL*V		irg Jackson		
4. Well Location		- VOZ 61	81 119				
	220 6.6 4	¥ 4.1.		210 6-46	- the West	lina	
Unit Letter C: 330 feet from the North line and 2310 feet from the West line							
Section 32	Township	17S R a	inge 31E	NMPM Eddy	County		
	10. Elevation (Show	whether D	R, RKB, RT, GR, etc.	.)			
3736' GR							
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data							
NOTICE OF IN				SEQUENT REI	PORTOF: ALTERING CASIN		
PERFORM REMEDIAL WORK	PLUG AND ABANDOR	ч Ц	REMEDIAL WORK		ALIERING CASIN	1G L	
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRIL	LLING OPNS.	PLUG AND ABANDONMENT	Ā	
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AN CEMENT JOB	ID 🗆			
OTHER:			OTHER:				
12. Describe proposed or complet	ed operations. (Clearly s	tate all per	tinent details, and gi	ive pertinent dates,	including estimated	date	
of starting any proposed work)	. SEE RULE 1103. For	Multiple C	Completions: Attach	wellbore diagram	of proposed complet	tion	
or recompilation.							
2-19-2003 - Moved in and rigged up pulling unit. Jarred pump loose. POOH with rods and pump. Rigged down rod equipment. Changed rams in BOP. Shut well in for night.							
2-20-2003 - Nippled down wellhead and nippled up BOP. Rigged up floor and tubing equip-							
ment. TOOH with 2-7/8" tubing. Rigged up wireline. RIH with CIBP and set CIBP at 3196'.							
POOH & rigged down wireline. RIH with tubing. Circulated hole with plugging mud. Spotted							
a 15 sack Class C Neat cement plug from 3196-3051'. Pulled up hole to 1654'. Spotted							
25 sacks Class C Neat cement. POOH with tubing. Shut well in for night. WOC. 2-21-2003 - RIH with tubing and tagged plug at 1421'. Pulled up hole to 763'. Spotted							
2-21-2003 - RIH with tubing and tagged plug at 1421. Pulled up note to 763. Spotted 25 sacks Class C Neat cement. WOC 4 hours. RIH with tubing and tagged plug at 546'.							
POOH with tubing. Rigged down tubing equipment and floor. Nippled down BOP. Dug out							
cellar. Found cement on backside of 8-5/8" and inside. Rigged up wireline. Perforated							
5-1/2" casing at 60 '.	POOH & rigged d	lown wire	eline. Pressu	red up to 800	psi, OK. Shu	t	
well in for night.					001		
2-22-2003 - RIH to 12							
POOH with tubing. Cu						·	
I hereby certify that the information	above is true and compi	ete to me o	est of my knowledg	e and belief. CON	rinued:		
SIGNATURE PLATEST	fun	_TITLE	Agent for BCM	& Associates	DATEFeb. 28,	2003	
Type or print name Rusty Kle	in		·	Telepl	hone No. 748-215	9	
(This space for State use)							
APPPROVED BY DATE							
Conditions of approval, ital	T	4 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		ABbonur	B Oct 3 1 201		
	•		•	ግን የ ነ ላ ይ	10 UE 3 1 20	IJ	

ME-TEX OIL & GAS, INC. State M #1 Section 32-T17S-R31E Eddy County, New Mexico

SUNDRY NOTICE CONTINUED:

Installed regulation abandonment marker. PLUGGED AND ABANDONED - FINAL REPORT. Plugging completed February 21, 2003.

Rusty Klefin Agent for BCM & Associates

February 28, 2003