Form 3160-5 (August 1999)

1. Type of Well

UNITED STATES

Oil Cons. N.M. DIV-Dist. 2

FORM APPROVED OMB No. 1004-0135 ber 30, 2000

RECEIVED

DEPARTMENT OF THE INTERIOR 301 W. Grand Avenue Serial No. Artesia, NM 88210 LC-029295-B

OCT 2 8 2003

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

Water Injection Well

If Indian, Allottee or Tribe Name NA

CD-ARTESIA	SUBMIT IN	TRIPLICATE	- Other i	instructi	ons on	reverse s	side .

7. If Unit or CA/Agreement, Name and/or No.

Oil Well Gas Well A Other Name of Operator

Well Name and No. Turner "B" #41

9. API Well No.

Merit Energy Company

3b. Phone No. (include area code) 806-229-6300

30-015-05310

PO Box 300 WhiteFace, Texas 79379 Location of Well (Footage, Sec., T., R., M., or Survey Description) 10. Field and Pool, or Exploratory Area Grayburg-Jackson Field

1650' FNL & 1650' FWL Section 20, T-17S, R-31-E Unit F

11. County or Parish, State Eddy County, New Mexico

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepea Fracture Treat New Construction Plug and Abandon Plug Back	Production (Start/Resume) Reclamation Recomplete Temporarily Abandon Water Disposal	Water Shut-Off Well Integrity Other		

- 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days. following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)
 - 1. Set CIBP at 2660' and cap with 35' of cement.

RECEIVED

2. Perforate 5-1/2" casing at 1280' (base of salt at 1230')

OCT 2 8 2003

3. Set cement retainer at 1180'. Pump 75 sx. Class "C" below retainer.

OCD-ARTESIA

- Spot cement plug 450'-550' (top of sait at 505'). Tag plug to verify cement top.
- 5. Perforate 5-1/2" casing at 50'. Set cement plug from surface to 50' and attempt to circulate cement to surface outside of the 9-5/8" casing annulus.
- 6. Cut off 9-5/8" and 5-1/2" casing 3' below ground level.
- 7. Set dry hole marker

APPROVED

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)

Howard Boatright

Title Agent

UUT 24

Signature

Date October 10, 2003.

LES BABYAK PETROLEUM ENGINEER

THIS SPACE FOR FEDERAL OR STATE OFFICE USE


Approved by

Conditions of approval, if any, are attached. Approval of this focioe does not warrant or certify that the applicant holds legal or equitable title to these rights in the subject lease which would entitle the applicant to conduct operations thereon. Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

10000311151151

in anady, somer



replantage to a solution to the

* * * 17 ... 1. * *

