

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505



DEC 15 2008

OCD-ARTESIA

Form C-103
May 27, 2004

WELL API NO.

30-015-31186

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

ENTERPRISE "32" STATE COM

8. Well Number

1

9. OGRID Number

015742

10. Pool name or Wildcat

UNDES TURKEY TRACK; CISCO, NORTH

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

NEARBURG PRODUCING COMPANY

3. Address of Operator

3300 N. "A", Bldg. 2, #120, Midland, TX 79705

4. Well Location

Unit Letter B : 660 feet from the NORTH line and 740 feet from the WEST line

Section 32 Township 18 2 Range 29 E NMPM County EDDY

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type STEEL Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

10-23-08 Notify O.C.D., Phil Hawkins. 10-27-08 Set C.I.B.P. @9,550'. Dumpbail 5 sx. Class H cmt. -9,550'-9,510'. 10-28-08 Circulate 10# M.L.F. 10-29-08 Cut 5 1/2" csg. @8,000'. 10-30-08 Pull 5 1/2" csg. Spot 40 sx. Class H cmt. - 8,500'. 10-31-08 Tag T.O.C. @7,860'. Spot 40 sx. Class H cmt. 6,429'. Spot 40 sx. cmt. - 4,800'-4,644'. Spot 50 sx. cmt. @3,537'. 11-3-08 Tag T.O.C. @3,347'. Spot 40 sx. cmt. @895'-748'. Spot 50 sx. cmt. w/2% CaCl. - 452'-268'. W.O.C. & tag T.O.C. @254'. Circulate 30 sx. cmt. 100'- surface. Remove wellhead & anchors. Install P & A Marker. Backfill collar.

P & A DATE: 11-3-08

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE Gary Eggleston TITLE P & A SUPV. DATE 11-10-08

Type or print name GARY EGGLESTON

E-mail address:

Telephone No. (432) 530-0907

For State Use Only

APPROVED BY

Conditions of Approval, if any:

Accepted for record
NMOCD

TITLE

Approved for plugging of well bore only.
Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms. www.emnrd.state.nm.us/oed.

DATE 12/17/08