Subitait 3 Copies To Appropriate District Office		f New Mex			Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Mineral	s and Natur	al Resources	WELL API NO.	May 27, 2004
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSER	VATION	DIVISION	30-005-62978 5. Indicate Type of Leas	
<u>District III</u> 1000 Rio Brazos Rd , Aztec, NM 87410	1220 South St. Francis Dr.			STATE	FEE []
District IV	Santa Fe, NM 87505			6. State Oil & Gas Lease	
1220 S. St. Francis Dr., Santa Fe, NM 87505	•			V-2925	
SUNDRY NOTION (DO NOT USE THIS FORM FOR PROPOSALS	CES AND REPORTS O		CK TO A	7. Lease Name or Unit A	Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATI	ION FOR PERMIT" (FORM			Trailblazer ANL State	
1. Type of Well: Oil Well Gas Well Other				8. Well Number	
	JAN 0.5 2009				
2. Name of Operator				9. OGRID Number 009974	
Hanson Operating Company, Inc. 3. Address of Operator	OCD-ARTESIA			10. Pool name or Wilder	nt
P. O. Box 1515, Roswell, NM 8820				Acme San Andres Sou	
4. Well Location					
	2310 feet from the	North	line and 330	feet from the Ea	st line
Section 11	Township 8 S		ge 27 East	NMPM Chaves	County
Section 11	11. Elevation (Show w		Y		County
Pit or Below-grade Tank Application ☐ or Clo					
Pit typeDepth to Groundwater_>100' Dis	tance from nearest fresh wa	ter well <u>>2 mil</u>	es_Distance from neares	t surface water >10 miles	
Pit Liner Thickness: mil Below-Gr	rade Tank: Volume	bbls	; Construction Materi	ial	
12. Check A	Appropriate Box to	Indicate Na	ature of Notice, I	Report or Other Data	
NOTICE OF INT	FENTION TO	, 1	CLID		T OF:
NOTICE OF INT PERFORM REMEDIAL WORK □	PLUG AND ABANDON	ı 🗆 📗	REMEDIAL WORK	SEQUENT REPOR	RING CASING
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRIL		
PULL OR ALTER CASING	MULTIPLE COMPL		CASING/CEMENT		_
OTHER:			OTHER:		
13. Describe proposed or complet starting any proposed work).	ed operations. (Clearly	state all pert	nent details, and give	ve pertinent dates, including	g estimated date of
recompletion.	SEE RULE 1103. FOF	viultiple Coll	ipietions. Attach we	endore diagram of propose	d completion of
Plug and abandon well as fo	llows:				·
10/29/2008: MIRU.					
10/30/2008: RIH with wireling					
470'. Pump 120 sack cemer	nt plug and circul	ate to sur	face. Well plu	gged and abandon	ed. Witnessed
by Phil Hawkins.	,				
	,			4 0000	1
Clean and remediate location	n, and set Dry Ho	ole Marke	r by January 3	1, 2009.	
				•	
I hereby certify that the information about	ove is true and complete	to the best o	f my knowledge and	belief. I further certify that	any pit or below-grade
tank has been/will be constructed or closed acc	ording to NMOCD guideline	es 🛛, a general	permit 🗌 or an (attach	ed) alternative OCD-approved	plan □.
SIGNATURE (arol).	Smith T	TTLE Pro	duction Analyst	DATE 12	/31/2008
Type or print name Carol J. Sprith	E-ma	il address:	anson@dfn.com	well hore only.	
For State Use Only		1.3	er cover are progging of	wen nore only.	

SIGNATURE Carol J. Smith TITLE Production Analyst DATE 12/31/2008

Type or print name For State Use Only

ACCEPTED for record TITLE

APPROVED BY:

Conditions of Approval (if any):

TITLE Production Analyst DATE 12/31/2008

E-mail address: https://doi.org/10.1009